## **OCD-ARTESIA**

Form 3160-5 (August 2007)

## UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

FORM A	PPROVED
OMB No	1004-0137
Expires li	alv 31, 2010

5 Lease Serial No NMLC029418A

6 If Indian, Allottee or Tribe Name

SUNDRY NOTICES AND REPORTS ON WELLS
Do not use this form for proposals to drill or to re-enter an
abandoned well. Use Form 3160-3 (APD) for such proposal

apandoned well. (	Jse Form 3160-3 (A	PD) for suc	n proposais						
SUBMIT IN TRIPLICATE – Other instructions on page 2.					7. If Unit of CA/Agreement, Name and/or No NMNM71030C				
1. Type of Well  Oil Well  Gas Well  Other					8 Well Name and No.				
			Skelly Unit 782  9 API Well No.						
2 Name of Operator CHEVRON USA INCORPORATED COG Operating LLC (Agent)			,1	30-015-3801		ratory Area			
3a Address (Agent) 550 W Texas Ave , Suite 100 Midland, TX 79701 432-818-2319				_	10 Field and Pool or Exploratory Area  EREN; GLORIETA-YESO  11 Country or Parish State				
4 Location of Well (Footage, Sec., T,R,M, or Survey Description)				lacke	11 Country or Pa	rısh, State	24104	267	
Sec 23 T17S R31E 1250 FNL 897 FEL, Unit A					EDDY COUNTY, NM				
12 CHEC	K THE APPROPRIATE BO	X(ES) TO INDI	CATE NATURE	OF NOTIC	CE, REPORT OR	OTHER DA	ATA		
TYPE OF SUBMISSION			TYP	E OF ACT	ION				
Notice of Intent	Acidize	Deepe	en ure Treat	=	uction (Start/Resun	ie)	Water Shut-Off Well Integrity		
	Alter Casing  Casing Repair	=	Construction	=	Reclamation Recomplete		✓ Other		
Subsequent Report	Change Plans		and Abandon	$\equiv$			Drilling Operati	ons	
Final Abandonment Notice	Convert to Injection	Plug I	Back	☐ Wate	r Disposal				
Attach the Bond under which the work will be performed or provide the Bond No on file with BLM/BIA. Required subsequent reports must be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion in a new interval, a Form 3160-4 must be filed once testing has been completed. Final Abandonment Notices must be filed only after all requirements, including reclamation, have been completed and the operator has determined that the site is ready for final inspection.)  8/29/11 MIRU.  8/30/11 Dnilled out DV tool @ 3662.  9/09/11 Set packer @ 3712, test tog to 3400 psi, well started taking water, test failed.  9/09/11 Set packer @ 3712, test tog to 3000 psi, test failed. Tested 5-1/2 csg to 4000 psi for 10 min. Test good. Set packer @ 7065. Tested tbg to 3000 psi, test failed. Tested 5-1/2 csg to 3000 psi, for 10 mins. Test good. Annulus tested good from 7065 to surface. Released packer.  9/11/11 RIH w/CIBP, set @ 7050. Tested 5-1/2 csg to 4800 psi for 30 mins, tested good. Perf Lower Blinebry @ 6290 - 6490 w/ 1 SPF, 26 holes. Dumped 35 of cmt on top of CIBP.  9/13/11 Acidize w/3621 gals 15% HCL acid. Frac w/114,752 gals gel, 148,027# 16/30 White sand, 27,534# 16/30 CRC. CPB @ 6250. Perf Middle Blinebry @ 6020 - 6220 w/ 1 SPF, 26 holes. Acidize w/3568 gals 15% HCL acid. Frac w/113,968 gals gel, 149,463# 16/30 White sand, 28,463# 16/30 CRC. CBP @ 5980.  Perf Upper Blinebry @ 6675, 5715, 5759, 5808, 5860, 5915, 5947 w/ 4 SPF, 28 holes. Acidize w/3767 gals 15% HCL acid. Frac w/110,857 gals gel, 144,448# 16/30 White sand, 29,647# 16/30 CRC. CBP @ 5390.  Perf Paddock @ 5210 - 5360 w/1 SPF, 26 holes. Acidize w/3000 gals 15% HCL acid. Frac w/98,678 gals gel, 99,793# 16/30 White sand, 26,466# 16/30 CRC.  9/15/11 Dnll out plugs. Clean out to PBTD 7025.  9/16/11 Pall out plugs. Clean out to PBTD 7025.  9/16/11 Pall out plugs. Clean out to PBTD 7025.  9/16/11 Pall out plugs. Clean out to PBTD 7025.  9/16/11 Pall w/192 its 2-7/8" 6.5# J55 tbg, EOT @ 6278. RIH w/ 2-1/2" x 2									
Netha Aaron			Title PREPARI	ER		AINIOCI	DAMILLONI		
Signature M. Caro			Date 10/13/20	11	AC	CEPTE	ED FOR RE	CORD	
THIS SPACE FOR FEDERAL OR STATE OFFICE USE						7			
Approved by			T			00	CT 2.7 20;		
Conditions of approval, if any, are attached that the applicant holds legal or equitable tientitle the applicant to conduct operations to	tle to those rights in the subje- hereon	ct lease which wo	ould Office				E LAND MANAGE		
Title 18 U S C Section 1001 and Title 43 I feetitious or fraudulent statements or representations.					o make to any depa	artingerial of ag	gency of the United State	gs any false,	
(Instructions on page 2)			<del>- Moodh</del>	HOU IC	<del>╜╵┖</del> ┖┖┖┞╱	١.			