Submit 1 Copy To Appropriate District Office	State of New Mexico				Form C-103	
District I – (575) 393-6161	lergy, Minerals and Natural Resources				Revised August 1, 2011	
1625 N. French Dr., Hobbs, NM 88240				WELL API N		
<u>District II</u> – (575) 748-1283 811 S. First St., Artesia, NM 88210	OIL CONSERVATION DIVISION			30-015-23784		
<u>District III</u> – (505) 334-6178	1220 South St. Francis Dr.			5. Indicate Ty		
1000 Rio Brazos Rd., Aztec, NM 87410 <u>District IV</u> – (505) 476-3460	Santa Fe, NM 87505				Gas Lease No.	
1220 S. St. Francis Dr., Santa Fe, NM 87505	·			B-11535	Cous Lease Ivo.	
SUNDRY NOTICES AND REPORTS ON WELLS				7. Lease Nan	ne or Unit Agreement Name	
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)					WEST ARTESIA GRAYBURG UNIT	
1. Type of Well: Oil Well Gas Well Other				8. Well Num	8. Well Number 26	
2. Name of Operator				9. OGRID N	9. OGRID Number	
Alamo Permian Resources. LLC					274841	
3. Address of Operator					10. Pool name or Wildcat	
415 W. Wall Street, Suite 500, Midland, TX 79701				Artesia; Quee	n-Grayburg-San Andres	
4. Well Location					•	
Unit Letter F: 1710		ne and 22				
Section 8	Township 18S	Range	28E	NMPM	County EDDY	
	11. Elevation (Show wh	ether DR,	RKB, RT, GR, etc	c.)	and the state of the	
	<u>M</u>					
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data						
	ITENTION TO:				REPORT OF:	
PERFORM REMEDIAL WORK TEMPORARILY ABANDON	PLUG AND ABANDON CHANGE PLANS	_	REMEDIAL WO	RK RILLING OPNS.[ALTERING CASING	
TEMPORARILY ABANDON L	MULTIPLE COMPL		CASING/CEMEN		<u> </u>	
DOWNHOLE COMMINGLE	MOLTIFEE COMPL	ш	CASIING/CEIVIEI	41 JOB	J	
		ļ				
OTHER:			OTHER: F	RETURN TO PRO	DUCTION	
13. Describe proposed or com	leted operations. (Clearly	state all r		nd give pertinent	dates, including estimated date	
13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of						
proposed completion or rec	completion.		-	_	~	
1 22 12						
1-23-12						
MIRU PU. Long stroke rods and ch SDFN.	eck for pump action. Load	ed and tes	ted tubing to 500	PSI. POOH w/ ro	ds and pump. Secured well.	
1-24-12 TIH w/ pump and rods. Check pump action HWO. Long-stroked pump, good pump action. RD PU. Clean location.						
11H w/ pump and rods. Check pum	action HWO. Long-st	rokea pun	np, good pump ac	tion. RD PU. CI	ean location.	
				-		
					RECEIVED	
					1441 9 0 2042	
			<u> </u>		JAN 3 0 2012	
Spud Date:	Rig R	Release Da	te:		NMOCD ARTESIA	
					AINOCO ALLESIA	
I hereby certify that the information above is true and complete to the best of my knowledge and belief.						
SIGNATURE CALLO	talon TITI	F Pegu	latory Affairs Co	nordinator DA	TE 01/26/2012	
Type or print name						
APPROVED BY:	le TITL	F ()157	H. ENOLIKE	R	DATE ASIA	
Conditions of Approval (if any):	<u></u>	L10.00	- yeurs	· -	DAIL COJOO I LES	