Submit 1 Copy To Appropriate District Office <u>District 1</u>	State of New Mexico Energy, Minerals and Natural Resources	Form C-103 October 13, 2009
1625 N French Dr., Hobbs, NM 88240 District II		WELL API NO.
1301 W. Grand Ave, Artesia, NM 88210 OIL CONSERVATION DIVISION		30-005-63538 5. Indicate Type of Lease
District III 1000 Rio Brazos Rd, Aztec, NM 87410 1220 South St. Francis Dr.		STATE S FEE
District IV 1220 S St Francis Dr, Santa Fe, NM 87505		6. State Oil & Gas Lease No. VA-2101
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH		7. Lease Name or Unit Agreement Name Miller State
PROPOSALS)		8. Well Number
1. Type of Well: Oil Well Gas Well Other		1
2. Name of Operator Armstrong Energy Corporation		9. OGRID Number 001092
3. Address of Operator P.O. Box 1973, Roswell, NM 88202-1973		10. Pool name or Wildcat (973/1)
4. Well Location		Acme; I Rre - Permittu Gas
Unit Letter N : 1200 : feet from the South line and 1980 : feet from the West line		
	ownship 8S Range 27E	NMPM Chaves County
11	. Elevation (Show whether DR, RKB, RT, GR, e	tc.)
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data		
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:		
PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐ REMEDIAL WORK ☐ ALTERING CASING ☐		
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. P AND A		
PULL OR ALTER CASING		
DOWNHOLE COMMINGLE		
OTHER: Recompletion Pay	lad 🛛 OTHER:	
13. Describe proposed or completed operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.		
proposed work). SEE ROLE 19.13.7.14	4 NMAC. For Multiple Completions: Attach welloo	ore diagram of proposed completion or recompletion.
1. Set CIBP @ 6550' and cap w/ 35' of cement		
2. Perf Penn Zone 6153'-6156' & 6158'-6161', 4 spf, 24 shots 3. Acidize w/ 1000 gals 15% NEEE acid w/ 48 ball sealers, may pressure 5 000 psi		
3. Acidize w/ 1000 gais 1370 NET E acid w/ 40 ball scalers, max pressure 3,000 psi		
4. Set CIBP @ 6110' and cap w/ 35' of cement MAR 2 0 2012		
5. Perf W-3 Zone 5869'-5871', 4 spf, 12 shots		
6. Acidize w/ 1000 gals 15% NEFE acid w/ 24 ball sealers, max pressure 5,000 psi		
6 15		
Spud Date:	Rig Release Date:	
I hereby certify that the information abov	e is true and complete to the best of my knowle	dge and belief.
SIGNATURE J	TITLE Vice President	DATE 03/14/12
Type or print nameBruce A. Stubbs	E-mail address: <u>bastubbs@armstrongen</u>	ergycorp.com PHONE: (575) 625-2222
For State Use Only		
APPROVED BY. / (MANIA) TITLE (SANACIST 2/20/2012		
APPROVED BY:		
APPROVED BY:		
<i>'</i>	U ·	



500 North Main Street, Suite 200 P.O. Box 1973 Roswell, New Mexico 88202-1973 (575) 625-2222 Fax (575) 622-2512

March 14, 2012

MAR 2 0 2012

NMOCD ARTESIA

Oil Conservation Division 1301 W. Grand Avenue Artesia, New Mexico 88210

Re: VA-2101

Miller State #1

Township 8 South, Range 27 East, NMPM

Section 2

Chaves County, New Mexico

Dear Sir/Madam:

Enclosed is a Sundry Notices and Reports on Wells, Notice of Intent, Recompletion, for the Miller State #1 to be filed with your office,

If you have any questions, please contact Bruce Stubbs at 505-625-2222.

Sincerely,

ARMSTRONG ENERGY CORPORATION

ву:

rma Cunningham, Gao Tech

Enclosure

Additional Company of the Company of

Andrasel in a familia Motham and Jappela ma Wolfe Mode, of latera. Haces spicition site with the Miller and general general Co.

The same of the same

. . .

A Commence of the second state of