Form 3160-5 (April 2004)

(Instructions on page 2)

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

SUNDRY NOTICES AND REPORTS ON WELLS

OCD-ARTESIA

FORM APPROVED OM B No. 1004-0137 Expires: March 31, 2007

5. Lease Serial No.

NMNM0417696 6. If Indian, Allottee or Tribe Name

Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160 - 3 (APD) for such proposals.

abandoned wen. Ose Form \$160-3 (APD)) for such proposals.
SUBMIT IN TRIPLICATE- Other instructi	ions on reverse side. 7. If Unit or CA/Agreement, Name and/or No.
1. Type of Well ☐ ☐ Gas Well ☐ ☐ Other	8. Well Name and No.
2. Name of Operator OXY USA Inc.	16696 Lost Euk 4 Federal #16
1	Phone No (include area code) 30-015 - 37957 432-685-5717 10. Field and Pool, or Exploratory Area
4. Location of Well (Footage, Sec., T., R., M., or Survey Description)	Lost Tank Delaware, west
SL-2025 FSL 1210 FEL NESE (I) So	ec4T22S R31E 11. County or Parish, State
BL- 452 FSL B38 FEL SESE (P)	ti ti (f Eddy NM
12. CHECK APPROPRIATE BOX(ES) TO IND	DICATE NATURE OF NOTICE, REPORT, OR OTHER DATA
TYPE OF SUBMISSION	TYPE OF ACTION
Notice of Intent Subsequent Report Casing Repair Change Plans	Deepen Production (Start/Resume). Water Shut-Off Reclamation Well Integrity. New Construction Recomplete Plug and Abandon Temporarily Abandon Plug Back Water Disposal
13. Describe Proposed or Completed Operation (clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No on file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a miultiple completion or recompletion in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements. including reclamation, have been completed, and the operator has determined that the site is ready for final inspection.) RUPU 12/16/10, Drill out DV Tools and clean out to PBTD @ 8361', isolate casing leak @ approximately 6000', RDPU 12/21/10. 1/5/11, RIH w/ camera to DV Tool @ 5998', ports look to be open. RU 8/12/11, Perf 1 SPF @ 8298-8118, 7932-7648, 7354-6928' Total 60 holes. Frac w/ 13373g Treated Water followed by 6260g 7-1/2% NeFe HCl acid followed by 14856g Water Frac GR-21 followed by 128339g Delta Frac 200 R-16 w/ 226089# sand, RD Halliburton. Swab and flow back to clean up well. RIH & set RBP @ 6200' w/ CR @ 5848', EIR @ .50 BPM @ 1750#, sqz 150sx HalCem C (22bbl) cmt slurry @ 5998', Sqz to 2000#, WOC. RIH & tag cmt @ 5840' drill out to 6010', test sqz to 1000#, held 30min w/ no leak. POOH w/ RBP & POOH. Clean out well, RIH w/ 2-7/8" tbg and rod pump, Put well on pump 9/10/11 and test well for potential. Shut-In well pending C-104 approval.	
14. I hereby certify that the foregoing is true and correct Name (Printed/Typed) David Stewart	Title Regulatory Advisor
Signature	Date LOUGE CEPTED FOR PECODO
THIS SPACE FOR FEDERAL OR STATE OFFICE USE	
Approved by Conditions of approval, if any, are attached. Approval of this notice does certify that the applicant holds legal or equitable title to those rights in the which would entitle the applicant to conduct operations thereon. Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crin States any false. fictitious or fraudulent, statements or representations as to	
,, da ci i i i i i i i i i i i i i i i i i i	A OUTTON TIETO OFFICE