Submit 1 Copy To Appropriate District Office	State of New Mexico				Form C-103	
District I - (575) 393-6161	Energy, Minerals and Natural Resources			[Revised August 1, 2011	
1625 N. French Dr., Hobbs, NM 88240				WELL API NO.		
<u>District II</u> – (575) 748-1283 811 S. First St., Artesia, NM 88210	OIL CONSERVATION DIVISION			30-015-03362	?T	
District III - (505) 334-6178	1220 South St. Francis Dr.			5. Indicate Type of STATE	Lease FEE	
1000 Rio Brazos Rd., Aztec, NM 87410 District IV – (505) 476-3460	Santa Fe, NM 87505			6. State Oil & Gas		
1220 S. St. Francis Dr., Santa Fe, NM				o. State on & Gus	Lease IVO.	
SUNDRY NOTICES AND REPORTS ON WELLS				7 Lease Name or I	Unit Agreement Name	
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A				7. Lease Name of V	Jim Agreement Name	
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH				J L LANGFORD		
PROPOSALS.) 1. Type of Well: Oil Well ⊠ Gas Well □ Other				8. Well Number	8. Well Number 6	
2. Name of Operator				9. OGRID Number		
Alamo Permian Resources. LLC				274841		
3. Address of Operator				10. Pool name or Wildcat		
415 W. Wall Street, Suite 500, Midland, TX 79701				QUEEN/GRAYBU	IRG/SAN ANDRES	
4. Well Location						
Unit Letter C: 990	feet from the N lin	ne and 16	feet from	the W line		
Section 9 Town		29E	NMPM	County	EDDY	
	11. Elevation (Show wh	hether DR,	RKB, RT, GR, etc	c.)		
12 (11-	A	11 NT	CNI d'	D (Od F	> -4-	
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data						
NOTICE OF IN	NTENTION TO:		SUI	BSEQUENT REP	ORT OF:	
PERFORM REMEDIAL WORK			REMEDIAL WO		ALTERING CASING	
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐ COMMENCE DRILLING OPNS.☐ P AND A						
PULL OR ALTER CASING	MULTIPLE COMPL		CASING/CEMEI	NT JOB		
DOWNHOLE COMMINGLE						
OTHER:			OTHER: BI	ETUDN TO DDODUCT	TON	
OTHER:			other: Ri ⊠	ETURN TO PRODUCT	ION	
13. Describe proposed or com	pleted operations. (Clearly	state all p		nd give pertinent dates	, including estimated date	
of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of						
proposed completion or re	completion.					
1-26-2012						
1 20 2012						
RU PU. Un- hung well and disconnected pumping T. Laid down liner. POOH with rods. Rods parted on the body. Parted @ 1,750 ft.						
RIH to fish rods. Caught rods. POOH with pods and pump. Laid down pump. RIH with pump. Seated pump. Put liner and pumping T on.						
Checked for pump action. Good pump action. Hung well and put well on production. RD.						
RECEIVED						
FED 0.1 2012						
FEB 0 1 2012						
				INMO	CD ARTESIA	
					- ATTEON	
Spud Date:	Rio F	Release Da	te·			
Space Bate.		cerease Du				
I hereby certify that the information	above is true and complet	te to the be	est of my knowled	lge and belief.		
() Alp.						
SIGNATURE	O MONOMITI	LE <u>Regu</u>	latory Affairs Co	oordinator DATE_	1/30/2012	
Type or print name						
Property of print hame CARLESTONER L-man address. Cstoner (a) atamore court ces. com						
APPROVED BY:	$\mathcal{U}_{}$ titl	.E_]) \57	H DUDON	TAD SON	E 09/99/9013	
Conditions of Approval (if any):						