Form 3160-5 (February 2005)

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

OCD-ARTESIA

FORM APROVED OMB NO. 1004-0135 EXPIRES: March 31, 200

BUREAU OF LAND MANAGEMENT		EXPIRES: March 31, 2007
SUNDRY NOTICES AND REPORTS ON WELLS		5. Lease Serial No.
Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals		NMNM36379; K 4562 6. If Indian, Allottee or Tribe Name
SUBMIT II	N TRIPLICATE	
4a Tupo of Well Co. Co. Well Co. Other		7. Unit or CA Agreement Name and No
1a. Type of Well Oil Well Gas Well Other		8 Well Name and No.
2. Name of Operator		Cotton Draw Unit 136H
DEVON ENERGY PRODUCTION COMPANY, LP		9. API Well No
3. Address and Telephone No		30-01538534
20 N. Broadway, Oklahoma City, Ok 73102-8260 405-235-3611		10. Field and Pool, or Exploratory
 Location of Well (Report location clearly and in accordance with Federal requirements)* SEC 2 T25S R31E 		Paduca; Bone Spring 11. County or Parish State
BHL: 2600 FSL & 1642 FWL K SEC 35 T24S R31E		Eddy NM
12. CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA		
TYPE OS SUBMISSION TYPE OF ACTION		
Notice of Intent Subsequent Report	Acidize Deepen Deepen Casing Repair New Construction	Production (Start/Resume) Water Shut-Off Reclamation Well Integrity Recomplete Other_Drilling
	Change Plans Plug and Abandon	Temporarily Abandon Operations
Final Abandonment Notice	Convert to Injection Plug Back	Water Disposal of starting any proposed work and approximate duration thereof. If the proposal
deepen directionally or recomplete horizontally, give subsurface location and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No on file with BLMBIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirement, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection.		
4/7/11 - 4/8/1 - MIRU Ashton rig & s <u>pud w</u> ell. Notify NMOCD. TD 17 1/2" hole @ 709'. RIH w/ 17 jts 13 3/8" 48# H-40		
and set @ 709'. RU cementer lead w/ 397 sx & tail w/ 250 sx. Displ w/105 bbls FW. Circ 160sx. WOC. Rlsd rig @ 6:00.		
8/29/11 - 8/30/11 - PT BOPs, Manifold & Floor Valves to 3K psi H/150 psi L. Notify J. Blakely, BLM. Test BOPS. PT		
annular 1500 psi H & 250 L, good. PT csg 30 min 1210, good.		
8/31/11 - 9/3/11 - TD 12 1/4" hole @ 4264'. Run CBL & notify J. Blakely (BLM) log GR/CCL/CBL. Verbal apprvl to run 9		
5/8" csg. C. DeMontginy w/ BLM on site. RIH w/ jts 9 5/8" 40# J55 csg & set @ 4264'. RU BJ lead w/ 980 sx 35:65 POZ C		
& tail w/ 300 sx 60:40 POZ C. Displ w/320 bbls FW. Circ 383 sx to surf. WOC. Test BOPs, floor valves & choke to 5K psi		
H & 250 psi L . Test annular 2500 psi H & 250 psi L. WOC. PT csg to 1500 psi, hold for 30 min, good. CHC.		
9/20/11 - 9/23/11 TD 8 3/4" hole @ 16,530'. RIH w/ 168 jts 5 1/2" 20# P-110 LTC csg & 210 jts 17# P-110 BTC, set @		
16,530'. Test to 9000 psi. RU BJ: 1st stage lead w/ 425 sx Yld 2.01 cf/sx. Tail w/ 2100 sx 1.28 cf/sx. Rec 223 sx off DV		
Tool 2nd stage lead w/ 300 sx Vld 2.88 cf/sx tail w/ 150 sx. Vld 1.37 cf/sx. RD RI		
9/24/11 - Notifiy BLM to skid rig. RIsd rig on 9/25/11@0600. DVT@? Toc@?		
	DV (@ ?	10Ca;
14. Thereby certify that the foregoing is true and		
Signed Lind Con	Name Judy A. Barnett X86 Title Regulatory Specialis	
(This space for Federal or State Office use)		
Approved by	Title	Date
Conditions of approval, if any	1100	Date

*See Instruction on Reverse Side

within its jurisdiction

Accepted for record NMOCD

DEC 02 2011

RECEIVED

NOV 7 2011

NMOCO ARTESIA

ACCEPTED FOR RECORD

OCT 29 2011

BUREAU OF LAND MANAGEMENT CARLSBAD FIELD OFFICE