

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

OCD-ARTESIA

FORM APPROVED
OMB NO. 1004-0137
Expires March 31, 2007

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals.

SUBMIT IN TRIPLICATE - Other instructions on reverse side

1. Type of Well

☐ Oil Well ☒ Gas Well ☐ Other

2. Name of Operator

OXY USA INC.

16696

3a. Address

P.O. Box 4294, Houston, TX 77210-4294

3b. Phone No. (include area code)

(713) 366-5360

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)

660' FSL & 1980' FWL
SEC. 35 (L) T19S-R28E

5. Lease Serial No.

NMNM0473362

6. If Indian, Allottee or Tribe Name

7. If Unit or CA/Agreement, Name and/or No.

NM 71213

8. Well Name and No.

Dero Federal Com

#2

9. API Well No.

30-015-20973

10. Field and Pool, or Exploratory Area

WINCHESTER-WOLFCAMP

11. County or Parish, State

EDDY

NM

12. CHECK APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION

☐ Notice of Intent☒ Subsequent Report☐ Final Abandonment Notice

TYPE OF ACTION

☐ Acidize☐ Alter Casing☐ Casing Repair☐ Change Plans☐ Convert to Injection☐ Deepen☐ Fracture Treat☐ New Construction☐ Plug and Abandon☐ Plug Back☐ Production (Start/Resume)☐ Reclamation☐ Recomplete☐ Temporarily Abandon☐ Water Disposal☐ Water Shut-Off☐ Well Integrity☒ Other Change ofOperator

13. Describe Proposed or Completed Operation (clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recompleat horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompleat in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the final site is ready for final inspection.)


AS REQUIRED BY 43 CFR 3100.0-5(a) AND 43 CFR 3162.3(a), WE ARE NOTIFYING YOU OF A CHANGE OF OPERATOR ON THE ABOVE REFERENCED LEASE EFFECTIVE 3-1-08. OXY USA INC AS THE NEW OPERATOR ACCEPTS ALL APPLICABLE TERMS, CONDITIONS, STIPULATIONS AND RESTRICTIONS CONCERNING OPERATIONS CONDUCTED ON THE LEASE OR PORTION OF LEASE DESCRIBED. OXY USA INC. MEETS FEDERAL BONDING REQUIREMENTS AS FOLLOWS (43 CFR 3104):NATIONWIDE OIL & GAS BOND No. ES 0136

PLEASE ACCEPT THIS SUNDRY TO SATISFY THE CORRECTIVE ACTION REQUIREMENTS OF WRITTEN ORDER.

Bonds ESB000226 & NRB000862

SEE ATTACHED FOR
CONDITIONS OF APPROVAL

Accepted for record
NMOC
LRDade 04/11/12

14. I hereby certify that the foregoing is true and correct
Name (Printed/Typed)

JEREME W ROBINSON

Title

SR. REGULATORY ANALYST

Date 09/15/2011

THIS SPACE FOR FEDERAL OR STATE OFFICE USE

Approved by

Title

Date

Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.

Office

Title 18 U.S.C. Section 1001, and Title 43 U.S.C. Section 1212, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

**BUREAU OF LAND MANAGEMENT
Carlsbad Field Office
620 East Greene Street
Carlsbad, New Mexico 88220
575-234-5972**

Conditions of Approval

**Oxy USA Inc.
Dero Federal Com #2
NM0473362 3001520973**

1. Tank battery must be bermed/diked (must be able to contain 1 1/2 times the volume of the largest tank).
2. Submit for approval of water disposal method.
3. Submit updated facility diagrams as per Onshore Order #3
4. This agency shall be notified of any spill or discharge as required by NTL-3A.
5. All outstanding environmental issue must be addressed within 90 days. Contact Jim Amos for inspection and to resolve environmental issues. 575-234-5909
6. Install legible well sign on location with operator name, well name and number, lease number, unit number, 1/4 1/4, section, township, and range. NMOCD requires the API number on well signs.
7. Subject to like approval by NMOCD.