

Office
District I - (575) 393-6161
1625 N. French Dr., Hobbs, NM 88240
District II - (575) 748-1283
811 S. First St., Artesia, NM 88210
District III - (505) 334-6178
1000 Rio Brazos Rd., Aztec, NM 87410
District IV - (505) 476-3460
1220 S. St. Francis Dr., Santa Fe, NM
87505

Energy, Minerals and Natural Resources

Revised August 1, 2011

OIL CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87505

WELL API NO.
30-005-61772

5. Indicate Type of Lease
STATE ☐ FEE ☒

6. State Oil & Gas Lease No.

7. Lease Name or Unit Agreement Name
Twin Lakes San Andres Unit

8. Well Number 109

9. OGRID Number
269864

10. Pool name or Wildcat
Twin Lakes San Andres

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH
PROPOSALS.)

1. Type of Well: Oil Well ☐ Gas Well ☒ Other Injector

2. Name of Operator
Canyon E&P Company

3. Address of Operator
4925 Greenville Ave, Ste 900, Dallas, Texas 75206

4. Well Location

Unit Letter J : 1650 feet from the South line and 1650 feet from the East line
Section 12 Township 9S Range 28E NMPM County Chaves

11. Elevation (Show whether DR, RKB, RT, GR, etc.)
3929 GR

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐ MULTIPLE COMPL ☐
DOWNHOLE COMMINGLE ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ P AND A ☐
CASING/CEMENT JOB ☐

OTHER: Convert Injection Well to Producer

☒


OTHER: ☐

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

Canyon respectfully request approval to convert this well from an injector to a producer using the following procedure:

- 1) The injection tubing has been pulled and laid down.
- 2) RIH and perforate P-2 section of San Andres from 2690 to 2712 with 2 jsp.
- 3) Acidize, run new rods and tubing, set pumping unit, and place well on production.
- 4) Attached is a log shot.

*Out of compliance - failed MIT
Requires MIT to pass signed by OGD*



Spud Date:

Rig Release Date:

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE

TITLE President

DATE

6-1-12

Type or print name Mike Mvers

E-mail address: mike@canyonep.com

PHONE: 214-709-6784

For State Use Only

APPROVED BY:

DATE

Conditions of Approval (if any):

Submit current C102

