Office	State of New Mexico		•	Form C-103
District I	Energy, Minerals and N	atural Resources		May 27, 2004
1625 N. French Dr., Hobbs, NM 88240			WELL API NO. 30-015-20385	
<u>District II</u> 1301 W. Grand Ave., Artesia, NM 88210	ve. Artesia NM 88210 OIL CONSERVATION DIVISION			
District III	1220 South St. Francis Dr		5. Indicate Type of	
1000 Rio Brazos Rd., Aztec, NM 87410 District IV	Santa Fe, NM 87505		STATE 6. State Oil & Gas	FEE x
1220 S. St. Francis Dr., Santa Fe, NM		o. State Off & Gas	Lease No.	
87505				
SUNDRY NOTICES AND REPORTS ON WELLS			7. Lease Name or Unit Agreement Name	
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH			FAIR	
PROPOSALS.)  RECEIVED				
	Gas Well  Other	HECEIVED	8. Well Number	1
2. Name of Operator		MAR 2 9 2005	9. OGRID Number	
HAPPY (	OIL CO.	HOU MOTERIN	10 7 1	77711
3. Address of Operator 811 BULLOCK AVE. ARTESIA N.M. 88210			10. Pool name or Wildcat ATOKA S A	
4. Well Location			ATORASA	
Unit LetterD: 330 feet from theN line and330 feet from theW line				
Section 24 Township 18 S Range 26 E NMPM County EDDY				
11. Elevation (Show whether DR, RKB, RT, GR, etc.)				
3307 GR				
Pit or Below-grade Tank Application □ or Closure □				
Pit type NONEDepth to GroundwaterDistance from nearest fresh water well Distance from nearest surface water				
Pit Liner Thickness: mil Below-Grade Tank: Volumebbls; Construction Material				
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data				
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:				
PERFORM REMEDIAL WORK   PLUG AND ABANDON   REMEDIAL WORK				LTERING CASING
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. P AND A				
PULL OR ALTER CASING	MULTIPLE COMPL	CASING/CEMENT	I JOB	
OTHER:		OTHER:		
13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date				
of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion				
or recompletion.  Wellbore @				
		Weller	re w	Al - 1 at
2 19 2005 CDOT 125 CVC CEMEN	IT @ 1736' - 818' TAGGED	32.73	347584 1	V - Nat
3-18-2005 SPOT 125 SXS CEMENT @ 1736' - 818' TAGGED 3-18-2005 SPOT 15 SXS @ 60' TO SURFACE  Well Gore @ 32 739 7589 N = Lat  104. 3429 769 W = Long				
3 10 <b>2</b> 003				
		DIA MAL	2 Kus Q.	
PULLED 1106' OF 4 1/2" CASING CIRCULATED HOLE WITH 10# MUD  32. 740 5563° N = Lat				
CIRCULATED HOLE WITH 10# MUD $32.7405363 N = 241$				
INSTALLED DRY HOLE MARKE	К	104.34	38346° W	= Long
OF BANED TOGATION AND	GEW WARKER 4671 v			L
CLEANED LOCATION AND WAR NOT SEC.		W OF WELL. MA	ARKER IS SET	
e NW CORNER OF SEC.	24.			
I hereby certify that the information	above is true and complete to th	e best of my knowledge	e and belief. I further o	ertify that any pit or below-
grade tank has been/will be constructed or	closed according to NMOCD guidelin	es 🔲, a general permit 🔲 e	or an (attached) alternativ	e OCD-approved plan 🔲.
SIGNATURE CONT	Lew TITLE	AGGIL	. ,	DATE 3 - 28 QT
Jest Williams	IIIEL	110 779		
Type or print name		l address:	Tele	phone No.
For State Use Only	00	Suld by	~ TD	
APPROVED BY:	Titri E	JULO 194	pr A	RR 1 1 2005
Conditions of Approval (if any):	11100			



## NEW MEXICO ENERGY, MINERALS and NATURAL RESOURCES DEPARTMENT

**BILL RICHARDSON** Governor

Joanna Prukop Cabinet Secretary Acting Director Oil Conservation Division

RECEIVED

CUMHTERIA

. 676 5

346.

S 3 36 29 March 2005

Happy Oil Co. 811 Bullock Ave. Artesia, New Mexico 88210

Form C-103 Report of Plugging for your Fair # 1 D-24-18-26 API 30-015-20385 Cannot be approved until an NMOCD representative has made an inspection of the location and found it to be cleared to comply with OCD rules and regulations. Please check each item in the space provided to indicate that the work has been accomplished and the location is ready for final inspection.

1. All pits have been closed as per Rule 50.

NO PITS

- 2. Rat hole and cellar have been filled and leveled.
- 3. A steel marker 4" in diameter and approximately 4' above mean ground level has been set in concrete to mark the exact location of the plugged well. (Marker must have operator name, lease name, well number and location including quarter/quarter section or unit letter, section, township, range and API well ID number permanently welded, stamped or otherwise engraved into the metal marker.)
- 4. The location has been leveled as nearly as possible to original top ground contour and has been cleared of all junk and equipment.
- 5. The dead men and tie downs have been cut and removed.
- 6. If a one well lease or last remaining well on lease, the battery and burn pit locations have been NO BURN PIT leveled and cleared of all junk & equipment.
- 7. All environmental concerns have been addressed as per OCD guidelines.

The above are minimum requirements and no plugging bond will be cancelled until all locations for plugged and abandoned wells have been inspected and Form C-103 approved.

When all of the work outlined above has been done, please notify this office by completing, signing and returning this letter to us so that our representative will not have to make more than one trip to the location.

I certify that the above work has been done and the above-mentioned lease is ready for OCD inspection and approval.

Field Rep. II