

30-015-01468
Location Correction

Dade, Randy, EMNRD

From: Jennifer_Duarte@oxy.com
Sent: Tuesday, September 25, 2012 7:20 AM
To: Dade, Randy, EMNRD
Subject: FW: Chris Robin 20 Fed # 7

Randy,

Here is the information on the Chris Robin 20 Federal #7 that you had asked for on the location of the P&A (surveyor is calling it a dry hole) location. Hope this helps answer your questions. Please let me know if you need any further information.

Thank you,
Jennifer Duarte
Regulatory Analyst

Occidental Permian Ltd. / Oxy USA WTP LP / Oxy USA Inc.
Phone. 713/513-6640, Fax 713/985-8781

From: Weaver, Calvin C.(Dusty)
Sent: Thursday, September 20, 2012 12:32 PM
To: Duarte, Jennifer A
Subject: FW: Chris Robin 20 Fed # 7

Jennifer,

Here is where the dry hole is that shows to be at our location.....

Calvin C. (Dusty) Weaver
Cell.: 806-893-3067
Office: 432-685-5723

From: Tammy Kaber [<mailto:tkaber@jwsc.biz>]
Sent: Thursday, September 20, 2012 12:05 PM
To: Weaver, Calvin C.(Dusty)
Cc: Wilson, Jim B (RWI Construction Inc)
Subject: Chris Robin 20 Fed # 7

Dusty,

The Chris Robin 20 Fed # 7 is staked at 1650' FNL & 1980' FEL, the Dry Hole Marker is 381.5' in a westerly direction from this well. The Dry Hole Marker is the Swine WR-3, the calls are 1697' FNL & 2358' FEL, the company is Kersey & Co. Both wells are in Sec 20, T17S, R28E.

Hope this helps and thank you,