

UNITED STATES DEPARTMENT OF THE INTERIOR  
BUREAU OF LAND MANAGEMENT  
Oil Cons. DIV-Dist. 2  
1001 W. Grand Avenue  
Albuquerque, NM 88210FORM APPROVED  
OMB No. 1004-0137  
Expires: March 31, 2007

## SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals.

License Serial No.

NM-01159

Indian, Allottee or Tribe Name

## SUBMIT IN TRIPLICATE- Other instructions on reverse side.

1. Type of Well



Oil Well



Gas Well



Other

2. Name of Operator

EOG Resources, Inc

3a. Address

P.O. Box 2267, Midland, TX, 79702

3b. Phone No. (include area code)

432-561-8600

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)

660 FSL, 1830 FEL  
Sec 3, T18-S, R 30E

7. If Unit or CA/Agreement, Name and/or No.

8. Well Name and No.

Nelson 3 Federal #10

9. API Well No.

30-015-27490

10. Field and Pool, or Exploratory Area

Walters Lake

11. County or Parish, State

Eddy, New Mexico

RECEIVED

MAY 05 2005

## 12. CHECK APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

## TYPE OF SUBMISSION

- ☐ Notice of Intent  
☒ Subsequent Report  
☐ Final Abandonment Notice

## TYPE OF ACTION

- |   |   |   |   |
|---|---|---|---|
| <input type="checkbox"/> Acidize              | <input type="checkbox"/> Deepen           | <input type="checkbox"/> Production (Start/Resume)      | <input type="checkbox"/> Water Shut-Off |
| <input type="checkbox"/> Alter Casing         | <input type="checkbox"/> Fracture Treat   | <input type="checkbox"/> Reclamation                    | <input type="checkbox"/> Well Integrity |
| <input type="checkbox"/> Casing Repair        | <input type="checkbox"/> New Construction | <input type="checkbox"/> Recomplete                     | <input type="checkbox"/> Other          |
| <input type="checkbox"/> Change Plans         | <input type="checkbox"/> Plug and Abandon | <input checked="" type="checkbox"/> Temporarily Abandon |   |
| <input type="checkbox"/> Convert to Injection | <input type="checkbox"/> Plug Back        | <input type="checkbox"/> Water Disposal                 |   |

13. Describe Proposed or Completed Operation (clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recompleat horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompleat in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection.)

1. MI 4-18-05
2. Set CIBP at 6800-Cap/35 CMT. 4-20-05.
3. Pres Test Csg Int Test to 500 PSI 30 Min. - Chart OK. 4-21-05.
4. Circ 160 PKR Fluid 6750 - Surf.
5. Move Off 4-22-05.

ACCEPTED FOR RECORD

MAY - 3 2005

ALEXIS C. SWOBODA  
PETROLEUM ENGINEER14. I hereby certify that the foregoing is true and correct  
Name (Printed/Typed)

Jimmy Bagley

Title

Consultant

Signature

Date

4-23-05

THIS SPACE FOR FEDERAL OR STATE OFFICE USE

Approved by

Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.

Title

Date

Office

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

(Instructions on page 2)

Accepted for record - NMOCD