Submit 3 Copies To Appropriate District Office	State of New Mexico			Form C-103		
District I	Energy, Minerals and Natural Resources		Revised May 08, 2003			
1625 N. French Dr., Hobbs, NM 88240	ch Dr., Hobbs, NM 88240			WELL API NO.		
District II 1301 W. Grand Ave., Artesia, NM 88210 OIL CONSERVATION DIVISION				-015-32998		
District III 1220 South St. Francis Dr.			5. Indicate Type			
1000 Rio Brazos Rd., Aztec, NM 87410			STATE			
District IV 1220 S. St. Francis Dr., Santa Fe, NM			6. State Oil & G	as Lease No.		
87505				648	3-145	
SUNDRY NOTICES AND REPORTS ON WELLS				7. Lease Name of	or Unit Agreement Name	
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH						
PROPOSALS.)				HINT 15 STATE		
1. Type of Well:				8. Well Number		
	Other	V18	athweige	1		
2. Name of Operator			10L I 3 200	9. OGRID Num	ber	
MARBOB ENERGY CORPORAT	TON	31	00C & T 1111	, , , , , , , , , , , , , , , , , , ,	14049	
3. Address of Operator	<u> </u>	O:	BECEIVE	10. Pool name o		
1 -	NM 88211-0227	u,	2/112/20		WOLFCAMP, NORTH	
4. Well Location				1 11-21-011-01-01-1	WOLLOWN & WORLD	
Unit Letter <u>E</u> :	1650 feet from the	NORT	H line and	990 feet fro	om the <u>WEST</u> line	
Section 15		198 Ra		NMPM	County EDDY	
	11. Elevation (Show wh		, RKB, RT, GR, etc.,)		
		' GL				
	ppropriate Box to In-	dicate N	lature of Notice,	Report or Other	r Data	
NOTICE OF INT	TENTION TO:		SUB	SEQUENT RE	PORT OF:	
PERFORM REMEDIAL WORK 🗌	PLUG AND ABANDON		REMEDIAL WOR	к 🗆	ALTERING CASING []	
TEMPORARILY ABANDON 🔲	CHANGE PLANS		COMMENCE DRI	ILLING OPNS.	PLUG AND	
PULL OR ALTER CASING ☐ MULTIPLE ☐ CASING TEST AND					ABANDONMENT	
PULL OR ALTER CASING	COMPLETION	LJ	CEMENT JOB	ND 📙		
	OOM ELTION		J OZINIZIVI OOD			
OTHER:			OTHER: RECO	MPLETION/DOW	NHOLE COMMINGLEX	
13. Describe proposed or comple	eted operations. (Clearly	state all r	pertinent details, and	d give pertinent da	tes, including estimated date	
of starting any proposed wor						
or recompletion.	,				or proposed completion	
•						
RECOMPLETED IN T	HE WOLFCAMP AS F	OLLOWS	:			
(11 0 10 -	0 0-001					
6/13/05 - SET CIBP @ 9500'.						
6/14/05 - PERF THE WOLFCAMP @ 8751' - 9080' (12 SHOTS).						
6/15/05 - ACIDIZE PERFS W/ 2500 GAL NEFE 15% HCL ACID. SWAB/FLOW TEST.						
6/16/05 - TAG CIBP @ 9500'. DRILL OUT PLUG.						
6/17/05 - HUNG WELL ON PUMP. BEGAN DOWNHOLE COMMINGLING.						
(SEE A	DMINISTRATIVE OR	DER DH	C-3478)			
\mathcal{N}						
I hereby certify that the information a	have is true and complete	e to the he	est of my knowledge	a and haliaf		
, 1, 1	obve is true and complete	e to the be	est of my knowledge	e and belief.		
SIGNATURE	LINA CONT	ritle Pi	RODUCTION ANA	LYST	DATE 7/12/05	
Type or print name DIANA J	. BRIGGS ()			Telen	hone No. (505) 748–330	
(TEL : C C()		A			UL 1 5 200 5	
FOM	RECORDS ONLY	ŗ			ERL TO MA	
APPPROVED BY	T	TTLE			_DATE	
Conditions of approval, if any:						