Form 3160-5 (August 2007)

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

OCD Artesia

FORM APPROVED OMB NO. 1004-0135 Expires: July 31, 2010

F
Lease Serial No.
NMNM93190

SUNDRY N	OTICES AND REPORTS ON WELLS	
Do not use this	form for proposals to drill or to re-enter ar	7
abandoned well.	Use form 3160-3 (APD) for such proposal	s.

Do not use the abandoned we	is form for proposals to II. Use form 3160-3 (API	drill or to re-o D) for such pi	nter an oposals.	. 6	o. If Indian, Allottee o	r Tribe Name	
SUBMIT IN TRI	PLICATE - Other instruc	tions on reve	rse side.		. If Unit or CA/Agree	ment, Name and/o	r No.
Type of Well Gas Well ☐ Oth	ner ·			.	B. Well Name and No. LUCKY LOBO AS		<u></u> М 2
2. Name of Operator YATES PETROLEUM CORPORATIONE-Mail: tinah@yatespetroleum.com				Ì	API Well No. 30-015-33411		
3a. Address 105 SOUTH FOURTH STREE ARTESIA, NM 88210	ΞΤ΄	3b. Phone No. Ph: 575-748 Fx: 575-748-			0. Field and Pool, or WILDCAT; UPP		•
4. Location of Well (Footage, Sec., 7	., R., M., or Survey Description	1)		1	1. County or Parish,	and State	
Sec 28 T16S R27E SESE 660	DFSL 1200FEL	•	•		EDDY COUNTY	, NM	
12. CHECK APPI	ROPRIATE BOX(ES) TO	INDICATE	NATURE OF N	OTICE, REP	ORT, OR OTHER	R DATA	
TYPE OF SUBMISSION			TYPE OF	ACTION			
Notice of Intent	☐ Acidize	Deepe	en	Production	(Start/Resume)	□ Water Shut-	-Off
Notice of Intent	Alter Casing	☐ Fractu	ire Treat	Reclamation	on .	☐ Well Integri	ity
☐ Subsequent Report	☐ Casing Repair	□ New	Construction	Recomple	te .	Other	
☐ Final Abandonment Notice	Change Plans	□ Plug	and Abandon	☐ Temporari	ly Abandon	٠	
	Convert to Injection	Plug l	3ack	□ Water Dis	posal		
Yates Petroleum Corporation 1. MIRU. NU BOP. Release 2. Set a CIBP at 8820' with 39 3. Straddle interval 7546'-761 4. Acidize with 4000g 15% NI 5. Straddle interval 7438'-750 6. Adidize with 3000g 15% NI 7. If above zones are econom	packer. 5' cement on top. Perfora 0'. Swab down. EFE HCI with 75 ball seal 0'. Swab down.	ite Cisco 7438 ers. Flow and	'-7610'(92): swab.	S roduction. C (EE ATTACHE ONDITIONS	D FOR OF APPR()VAL
Wellbore schematics attached	AUUGO:	ed for its	e Sesa		REC	EIVED	-
		MOCD /	egraph		DEC	1 1 2012	
14. Thereby certify that the foregoing is Name(Printed/Typed) TINA HUE	For YATES PETRO Committed to AFMSS for	DLEUM CORPO or processing b	RÅTION, sent to y KURT SIMMON	the Carlsbad	12 ()	D ARTESU	
Name(Frince Types)			THE REGITE		JELITVISON .	·	
Signature (Electronic S	Submission)		Date 09/21/20)12	ΛPDI	SUVED	
	THIS SPACE FO	R FEDERAL	OR STATE C	OFFICE USE	/(111	TOVED	
Approved By		1	Title		O DEC	7 2012	
Conditions of approval, if any, are attache certify that the applicant holds legal or equ which would entitle the applicant to condu	uitable title to those rights in the let operations thereon.	subject lease	Office		- CADICDAD	ng Nowe ND MANAGEMEN FILL DOFFICE	
Title 18 U.S.C. Section 1001 and Title 43 States any false, fictitious or fraudulent s	U.S.C. Section 1212, make it a statements or representations as	crime for any per to any matter wit	son knowingly and hin its jurisdiction.	willfully to mak	e to any department of	agency of the Unit	icd

Well Name: Lucky Lobo ASX	Fed Com #2 F	ield:
Location: 660' FSL & 1200' F	EL Sec. 28-16S-27E	Eddy Co, NM
GL: 3439' Zero:	AGL:	KB: xxxx'
Spud Date:	Completion I	Date:
Comments:		

Casing Program	n
Size/Wt/Grade/Conn	Depth
9 5/8" 36# J55	1432'
5 1/2" 15.5&17# J55&P110	9170'

TOC 900' by calc.

CURRENT CONFIGURATION

9 5/8" csg @ 1432'. Cmtd w/ 1200 sx. Cmt circ.

Pkr @ 8476'

Composite plg@

Morrow perfs 8726-56'

Morrow perfs 8856-62'

5 1/2" csg @ 9170'

Cmtd w/ 2200 sx

TD 9170' PBTD 9121'

Date: 9/11/12 Lucky Lobo #2

Spud Date: Completion Date:	Wel!	Name	: Lucky Lobo AS	X Fed Com #2	Field:	
	Loca	ation:	660' FSL & 1200'	FEL Sec. 28-16S-27E	Eddy Co, NM	
	GL:	3439'	Zero:	AGL:	KB: xxx	'X'
Commonte	Spud Date:			Completion	Date:	
Comments.	Com	ments	· · · · · · · · · · · · · · · · · · ·			

Casing Program			
Size/Wt/Grade/Conn	Depth		
9.5/8" 36# J55	1432'		
5 1/2" 15.5&17# J55&P110	9170'		

TOC 900' by calc. PROPOSED CONFIGURATION

Cisco perfs 7438-45', 62-64', 94-7500' 7546-58', 65-73', 99-7610'

9 5/8" csg @ 1432'. Cmtd w/ 1200 sx. Cmt circ.

Morrow perfs 8726-56'

Morrow perfs 8856-62'

5 1/2" csg @ 9170' Cmtd w/ 2200 sx

TD 9170' PBTD 9121'

CIBP@8\$20'+ 35' cement Composite plg@(8820'

Date: 9/20/12 Lucky Lobo #2a

Lucky Lobo ASX Federal Com 2 30-015-33411 Yates Petroleum Corporation December 07, 2012 Conditions of Approval

Notify BLM at 575-361-2822 a minimum of 24 hours prior to commencing work.

Work to be completed by March 07, 2012.

- 1. Surface disturbance beyond the originally approved pad must have prior approval.
- 2. Closed loop system required.
- 3. Operator to have H2S monitoring equipment on location.
- 4. A minimum of a 3000 (3M) BOP to be used. All blowout preventer (BOP) and related equipment (BOPE) shall comply with reasonable well control requirements. A two ram system with a blind ram and a pipe ram designed for the size of the work string shall be adequate. Tapered work strings will require an additional pipe ram. The manifold shall comply with Onshore Oil and Gas Order #2 Attachment I (3M Diagrams of Choke Manifold Equipment). The accumulator system shall have an immediately available power source to close the rams and retain 200 psi above precharge. The pre-charge test shall follow requirements in Onshore Order #2.
- 5. Operator shall set CIBP across top of the Morrow formation, which is shown as 8,670' in the geological report. Plug shall be 190' in length and a minimum of 25 sacks of neat Class H cement. Plug to be set from approximately 8,670' to 8,480'.
- 6. All waste (i.e. drilling fluids, trash, salts, chemicals, sewage, gray water, etc.) created as a result of work over operations shall be safely contained and disposed of properly at a waste disposal facility. No waste material or fluid shall be disposed of on the well location or surrounding area. Porto-johns and trash containers will be on-location during fracturing operations or any other crew-intensive operations.
- 7. Subsequent sundry required detailing work done and completion report for new zone. Operator to include well bore schematic of current well condition when work is complete.
- 8. If recompletion is successful remove, well shall be renamed. Submit NOI to remove "com".
- 9. CA will terminate when well is plugged back.

JAM 120712