Office	State of New Mexico	Form C-103
Office <u>District I</u> – (575) 393-6161	Energy, Minerals and Natural Resources	Revised August 1, 201
1625 N. French Dr., Hobbs, NM 88240		WELL API NO.
<u>District II</u> – (575) 748-1283 811 S. First St., Artesia, NM 88210	OIL CONSERVATION DIVISION	30-015-40186
<u>District III</u> – (505) 334-6178	1220 South St. Francis Dr.	5. Indicate Type of Lease
1000 Rio Brazos Rd., Aztec, NM 87410	Santa Fe, NM 87505	STATE FEE
District IV - (505) 476-3460	Santa Pe, INIVI 67303	6. State Oil & Gas Lease No.
1220 S. St. Francis Dr., Santa Fe, NM 87505		V-3459
	TICES AND REPORTS ON WELLS	7. Lease Name or Unit Agreement Name
	OSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A	Southland Royalty APM State
DIFFERENT RESERVOIR. USE "APPL" PROPOSALS.)	ICATION FOR PERMIT" (FORM C-101) FOR SUCH	8. Well Number
1. Type of Well: Oil Well	Gas Well Other	5H
2. Name of Operator	Sub-Weil Suite.	9. OGRID Number
Yates Petroleum Corporation		025575
3. Address of Operator		10. Pool name or Wildcat
105 South Fourth Street, Artesia,	NM 88210	Turkey Track; Bone Spring
4. Well Location		
Unit Letter M :	200 feet from the South line and	500 feet from the West line
Unit Letter D	330 feet from the North line and	660 feet from the West line
Section 24	Township 19S Range 29E	NMPM Eddy County
Scellon 224	11. Elevation (Show whether DR, RKB, RT, GR, etc.	
	3327'GR	
		E destroyação a consequente de acuardo de acuardo de acuardo de acuardo de acuardo de astrojos de acuardo de a
12 Check A	appropriate Box to Indicate Nature of Notice,	Report or Other Data
12. Check 11	appropriate box to maleute tvatare of tvotice,	report of other bata
NOTICE OF I	NTENTION TO: SUI	BSEQUENT REPORT OF:
PERFORM REMEDIAL WORK	PLUG AND ABANDON ☐ REMEDIAL WO	RK \square ALTERING CASING \square
TEMPORARILY ABANDON	CHANGE PLANS COMMENCE DI	RILLING OPNS.□ P AND A □
DULL OD ALTED CACING] MULTIPLE COMPL ☐ CASING/CEME	NT IOR \square
PULL OR ALTER CASING	MOETIFEE COMPL CASINO/CEME	N1 30B
DOWNHOLE COMMINGLE		N1 30B
DOWNHOLE COMMINGLE		_
DOWNHOLE COMMINGLE OTHER:	OTHER: Spud	
OTHER: 13. Describe proposed or com	OTHER: Spud pleted operations. (Clearly state all pertinent details, a	and give pertinent dates, including estimated
OTHER: 13. Describe proposed or comdate of starting any proposed.	OTHER: Spud pleted operations. (Clearly state all pertinent details, a sed work). SEE RULE 19.15.7.14 NMAC. For Multip	and give pertinent dates, including estimated
OTHER: 13. Describe proposed or com	OTHER: Spud pleted operations. (Clearly state all pertinent details, a sed work). SEE RULE 19.15.7.14 NMAC. For Multip	and give pertinent dates, including estimated
OTHER: 13. Describe proposed or comdate of starting any proposed proposed completion or re	pleted operations. (Clearly state all pertinent details, a sed work). SEE RULE 19.15.7.14 NMAC. For Multiple completion.	and give pertinent dates, including estimated ble Completions: Attach wellbore diagram of
OTHER: 13. Describe proposed or comdate of starting any proposed proposed completion or re	OTHER: Spud pleted operations. (Clearly state all pertinent details, a sed work). SEE RULE 19.15.7.14 NMAC. For Multip	and give pertinent dates, including estimated ble Completions: Attach wellbore diagram of
OTHER: 13. Describe proposed or comdate of starting any proposed proposed completion or re	pleted operations. (Clearly state all pertinent details, a sed work). SEE RULE 19.15.7.14 NMAC. For Multiple completion.	and give pertinent dates, including estimated ble Completions: Attach wellbore diagram of
OTHER: 13. Describe proposed or comdate of starting any proposed proposed completion or re	pleted operations. (Clearly state all pertinent details, a sed work). SEE RULE 19.15.7.14 NMAC. For Multiple completion.	and give pertinent dates, including estimated ble Completions: Attach wellbore diagram of
OTHER: 13. Describe proposed or comdate of starting any proposed proposed completion or re	pleted operations. (Clearly state all pertinent details, a sed work). SEE RULE 19.15.7.14 NMAC. For Multiple completion.	and give pertinent dates, including estimated ble Completions: Attach wellbore diagram of
OTHER: 13. Describe proposed or comdate of starting any proposed proposed completion or response.	pleted operations. (Clearly state all pertinent details, a sed work). SEE RULE 19.15.7.14 NMAC. For Multiple completion.	and give pertinent dates, including estimated ble Completions: Attach wellbore diagram of
OTHER: 13. Describe proposed or comdate of starting any proposed proposed completion or response.	pleted operations. (Clearly state all pertinent details, a sed work). SEE RULE 19.15.7.14 NMAC. For Multiple completion.	and give pertinent dates, including estimated ble Completions: Attach wellbore diagram of
OTHER: 13. Describe proposed or comdate of starting any proposed proposed completion or response.	pleted operations. (Clearly state all pertinent details, a sed work). SEE RULE 19.15.7.14 NMAC. For Multiple completion.	and give pertinent dates, including estimated ble Completions: Attach wellbore diagram of
OTHER: 13. Describe proposed or comdate of starting any proposed proposed completion or response.	pleted operations. (Clearly state all pertinent details, a sed work). SEE RULE 19.15.7.14 NMAC. For Multiple completion. 1. Set 40' of 20" conductor and cemented with 121 sx	and give pertinent dates, including estimated ble Completions: Attach wellbore diagram of redi-mix to surface.
OTHER: 13. Describe proposed or comdate of starting any proposed proposed completion or response.	pleted operations. (Clearly state all pertinent details, a sed work). SEE RULE 19.15.7.14 NMAC. For Multiple completion.	and give pertinent dates, including estimated ble Completions: Attach wellbore diagram of redi-mix to surface.
OTHER: 13. Describe proposed or comdate of starting any proposed completion or re 2/5/13 – Spudded well at 11:15 AM	pleted operations. (Clearly state all pertinent details, a sed work). SEE RULE 19.15.7.14 NMAC. For Multiple completion. 1. Set 40' of 20" conductor and cemented with 121 sx RE	and give pertinent dates, including estimated ble Completions: Attach wellbore diagram of redi-mix to surface.
OTHER: 13. Describe proposed or comdate of starting any proposed completion or re 2/5/13 – Spudded well at 11:15 AM	pleted operations. (Clearly state all pertinent details, a sed work). SEE RULE 19.15.7.14 NMAC. For Multiple completion. 1. Set 40' of 20" conductor and cemented with 121 sx	and give pertinent dates, including estimated ble Completions: Attach wellbore diagram of redi-mix to surface.
OTHER: 13. Describe proposed or comdate of starting any proposed completion or re 2/5/13 – Spudded well at 11:15 AM	pleted operations. (Clearly state all pertinent details, a sed work). SEE RULE 19.15.7.14 NMAC. For Multiple completion. 1. Set 40' of 20" conductor and cemented with 121 sx RE	and give pertinent dates, including estimated ble Completions: Attach wellbore diagram of redi-mix to surface.
OTHER: 13. Describe proposed or comdate of starting any proposed completion or re 2/5/13 – Spudded well at 11:15 AM Spud Date: 2/5/13	pleted operations. (Clearly state all pertinent details, a sed work). SEE RULE 19.15.7.14 NMAC. For Multip completion. 1. Set 40' of 20" conductor and cemented with 121 sx Rig Release Date:	and give pertinent dates, including estimated ole Completions: Attach wellbore diagram of redi-mix to surface.
OTHER: 13. Describe proposed or comdate of starting any proposed completion or re 2/5/13 – Spudded well at 11:15 AM Spud Date: 2/5/13	pleted operations. (Clearly state all pertinent details, a sed work). SEE RULE 19.15.7.14 NMAC. For Multiple completion. 1. Set 40' of 20" conductor and cemented with 121 sx RE	and give pertinent dates, including estimated ole Completions: Attach wellbore diagram of redi-mix to surface.
OTHER: 13. Describe proposed or com date of starting any proposed completion or re 2/5/13 – Spudded well at 11:15 AM Spud Date: 2/5/13 I hereby certify that the information	pleted operations. (Clearly state all pertinent details, a sed work). SEE RULE 19.15.7.14 NMAC. For Multiple completion. 1. Set 40' of 20" conductor and cemented with 121 sx Rig Release Date:	and give pertinent dates, including estimated ole Completions: Attach wellbore diagram of redi-mix to surface. CEIVED B 1 5 2013 CD ARTESIA
OTHER: 13. Describe proposed or comdate of starting any proposed completion or re 2/5/13 – Spudded well at 11:15 AM Spud Date: 2/5/13	pleted operations. (Clearly state all pertinent details, a sed work). SEE RULE 19.15.7.14 NMAC. For Multiple completion. 1. Set 40' of 20" conductor and cemented with 121 sx Rig Release Date:	and give pertinent dates, including estimated ole Completions: Attach wellbore diagram of redi-mix to surface.
OTHER: 13. Describe proposed or com date of starting any proposed completion or re 2/5/13 – Spudded well at 11:15 AM Spud Date: 2/5/13 I hereby certify that the information SIGNATURE	pleted operations. (Clearly state all pertinent details, a sed work). SEE RULE 19.15.7.14 NMAC. For Multiple completion. 1. Set 40' of 20" conductor and cemented with 121 sx Rig Release Date: Rig Release Date: TITLE Regulatory Reporting Sup	and give pertinent dates, including estimated ole Completions: Attach wellbore diagram of redi-mix to surface. CEIVED B 1 5 2013 CD ARTESIA dge and belief. Dervisor DATE February 13, 2013
OTHER: 13. Describe proposed or comdate of starting any proposed completion or re 2/5/13 – Spudded well at 11:15 AM Spud Date: 2/5/13 I hereby certify that the information SIGNATURE Type or print name	pleted operations. (Clearly state all pertinent details, a sed work). SEE RULE 19.15.7.14 NMAC. For Multiple completion. 1. Set 40' of 20" conductor and cemented with 121 sx Rig Release Date: Rig Release Date: TITLE Regulatory Reporting Sup	and give pertinent dates, including estimated ole Completions: Attach wellbore diagram of redi-mix to surface. CEIVED B 1 5 2013 CD ARTESIA dge and belief. Dervisor DATE February 13, 2013
OTHER: 13. Describe proposed or com date of starting any proposed completion or re 2/5/13 – Spudded well at 11:15 AM Spud Date: 2/5/13 I hereby certify that the information SIGNATURE	Pleted operations. (Clearly state all pertinent details, a sed work). SEE RULE 19.15.7.14 NMAC. For Multip completion. 1. Set 40' of 20" conductor and cemented with 121 sx Rig Release Date: Rig Release Date: TITLE Regulatory Reporting Suppertate E-mail address: tinah@yatespetroleum.	and give pertinent dates, including estimated ole Completions: Attach wellbore diagram of redi-mix to surface. CEIVED B 1 5 2013 CD ARTESIA dge and belief. Dervisor DATE February 13, 2013 COM PHONE:575-748-4168
OTHER: 13. Describe proposed or comdate of starting any proposed completion or re 2/5/13 – Spudded well at 11:15 AM Spud Date: 2/5/13 I hereby certify that the information SIGNATURE Type or print name	pleted operations. (Clearly state all pertinent details, a sed work). SEE RULE 19.15.7.14 NMAC. For Multiple completion. 1. Set 40' of 20" conductor and cemented with 121 sx Rig Release Date: Rig Release Date: TITLE Regulatory Reporting Sup	and give pertinent dates, including estimated ole Completions: Attach wellbore diagram of redi-mix to surface. CEIVED B 1 5 2013 CD ARTESIA dge and belief. Dervisor DATE February 13, 2013