

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

OCD Artesia

FORM APPROVED
OMB No. 1004-0137
Expires: July 31, 2010

SUNDRY NOTICES AND REPORTS ON WELLS
Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals.

5. Lease Serial No. **NM29278**
6. If Indian, Allottee or Tribe Name
N/A

SUBMIT IN TRIPLICATE - Other instructions on page 2.

1. Type of Well
 Oil Well Gas Well Other

2. Name of Operator
Lime Rock Resources II-A, L.P.

3a. Address
1111 Bagby Street, Suite 4600, Houston, Tx 77002

3b. Phone No. (include area code)
575-623-8424

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)
2190' FNL & 1650' FEL, Section 4-18S-27E, Unit G

7. If Unit of CA/Agreement, Name and/or No.
N/A

8. Well Name and No.
Hondo Federal #1, 6, 7

9. API Well No.
30-015-00772 ATTACHED

10. Field and Pool or Exploratory Area
Red Lake; Queen-Grayburg-SA

11. Country or Parish, State
Eddy County, New Mexico

12. CHECK THE APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT OR OTHER DATA

TYPE OF SUBMISSION	TYPE OF ACTION			
<input checked="" type="checkbox"/> Notice of Intent	<input type="checkbox"/> Acidize	<input type="checkbox"/> Deepen	<input type="checkbox"/> Production (Start/Resume)	<input type="checkbox"/> Water Shut-Off
<input type="checkbox"/> Subsequent Report	<input type="checkbox"/> Alter Casing	<input type="checkbox"/> Fracture Treat	<input type="checkbox"/> Reclamation	<input type="checkbox"/> Well Integrity
<input type="checkbox"/> Final Abandonment Notice	<input type="checkbox"/> Casing Repair	<input type="checkbox"/> New Construction	<input type="checkbox"/> Recomplete	<input checked="" type="checkbox"/> Other Flaring Gas
	<input type="checkbox"/> Change Plans	<input type="checkbox"/> Plug and Abandon	<input type="checkbox"/> Temporarily Abandon	
	<input type="checkbox"/> Convert to Injection	<input type="checkbox"/> Plug Back	<input type="checkbox"/> Water Disposal	


13. Describe Proposed or Completed Operation: Clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recomple horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports must be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recomple in a new interval, a Form 3160-4 must be filed once testing has been completed. Final Abandonment Notices must be filed only after all requirements, including reclamation, have been completed and the operator has determined that the site is ready for final inspection.)

Requesting to flare gas due to DCP Artesia Plant keeping the Acid Gas Compressor Under Maximum Operating Volume.

Estimated Volume - 40 MCFPD

Estimated Time - 2 Weeks

Verbal approval has been given to flare gas by Duncan Whitlock on 2/4/13.



RDade 2/21/13
Accepted for record
NMOCD

** See Attached sheet for list of wells in battery.

14. I hereby certify that the foregoing is true and correct.

Name (Printed/Typed)
Michael Barrett

Title **Production Supervisor**

Signature *Michael Barrett*

Date **02/04/2013**

THIS SPACE FOR FEDERAL OR STATE OFFICE USE

Approved by *[Signature]*

Title

Office

APPROVED
FEB 14 2013
BUREAU OF LAND MANAGEMENT

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.



**LIME ROCK
RESOURCES**

Hondo / Kite Battery NM29278

Hondo Federal #1	30-015-00772 ✓
Hondo Federal #6	30-015-29053 ✓
Hondo Federal #7	30-015-30463