

Submit 1 Copy To, Appropriate District
Office
District I - (575) 393-6161
1625 N. French Dr., Hobbs, NM 88240
District II - (575) 748-1283
811 S. First St., Artesia, NM 88210
District III - (505) 334-6178
1000 Rio Brazos Rd., Aztec, NM 87410
District IV - (505) 476-3460
1220 S. St. Francis Dr., Santa Fe, NM
87505

State of New Mexico
Energy, Minerals and Natural Resources

Form C-103
Revised August 1, 2011

OIL CONSERVATION DIVISION

RECEIVED

APR 18 2013

HOBBSUCD

WELL API NO.
30-015-24743

5. Indicate Type of Lease
STATE ☒ FEE ☐

6. State Oil & Gas Lease No.

7. Lease Name or Unit Agreement Name

Cave State

8. Well Number 003

9. OGRID Number
14070

10. Pool name or Wildcat
Cave GB/SA

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH
PROPOSALS.)

1. Type of Well: Oil Well ☒ Gas Well ☐ Other

2. Name of Operator
State of New Mexico formerly Marks and Garner

3. Address of Operator
811 S First St Artesia, NM 88210

4. Well Location

Unit Letter E : 1650 feet from the North line and 330 feet from the West line

Section 4 Township 17S Range 29E NMPM 1 Eddy County

11. Elevation (Show whether DR, RKB, RT, GR, etc.)

Appropriate Box to Indicate Nature of Notice, Report or Other Data

Approved for plugging of well bore only.
Liability under bond is retained pending receipt of
C-103 (Specifically for Subsequent Report of Well
Plugging) which may be found at OCD web page
www.emnrd.state.nm.us/oed
PULL OR ALTER
DOWNHOLE COMMING

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ P AND A ☒
CASING/CEMENT JOB ☐

OTHER: ☐

OTHER: ☐

13. Describe proposed or completed operations. state all pertinent details, and give pertinent dates, including estimated date
of starting any proposed work). SEE RULE 19.15-7.14 NMAC. For Multiple Completions: Attach wellbore diagram of
proposed completion or recompletion.

3/27/2013 Moved in unit. Rods were parted and pump was stuck. Installed BOP and started stripping rods and tubing OOH.
Tallied pipe and made scrapper run. SION.

3/28/2013 RIH and set CIBP at 2391'. Circulated hole with mud and spotted 25 sx class c cement on top of CIBP. POOH to
1802' abs spotted 25 sx class c cement. POOH to 403' and circulated cement to surface. Cut'off wellhead, installed
marker and cut off anchors.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE [Signature] TITLE _____ DATE _____

Type or print name _____ E-mail address: _____ PHONE: _____

For State Use Only

APPROVED BY: [Signature] TITLE Dist. Mgr DATE 4-18-2013

Conditions of Approval (if any):

APR 23 2013

dm