	· · ·		
submit 1 Copy To Appropriate District	State of New Mexico		Form C-103
<u>District 1</u> – (575) 393-6161 1625 N. French Dr., Hobbs, NM 88240	bs, NM 88240 83 NM 88210 178 tec; NM 87410 460 DIL CONSERVATION DIVISION 1220 South St. Francis Dr. Santa Fe, NM 87505		Revised August 1, 2011 WELL API NO.
District II – (575) 748-1283 811 S. First St., Artesia, NM 88210 District III – (505) 334-6178			30-015-35270 5. Indicate Type of Lease
<u>District IV</u> - (505) 554-6175, 1000 Rio Brazos Rd., Aztec, NM 87410 <u>District IV</u> - (505) 476-3460			STATE X FEE 6. State Oil & Gas Lease No.
1220 S. St. Francis Dr., Santá Fe, NM 87505		• · · · · ·	
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)			7. Lease Name or Unit Agreement Name Full Choke Com
1. Type of Well: Oil Well 🔲 Gas Well X Other			8. Well Number 01
2. Name of Operator LEGEND NATURAL GAS II, LP			9. OGRID Number 258894
3. Address of Operator 15021 KATY FREEWAY, SUITE 200, HOUSTON, TX 77094			10. Pool name or Wildcat MALAGA; MORROW (GAS)
4. Well Location			
Unit Letter C : 660_feet from theNORTHline and1349feet from theWESTline Section 32 Township 24S Range 28E NMPM EDDY County			
11. Elevation (Show whether DR, RKB, RT, GR, etc.)			
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data			
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:			
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK X ALTERING CASING TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS P AND A I			
PULL OR ALTER CASING	MULTIPLE COMPL	ING/CEMEN	IT JOB
OTHER:	отн	ER:	
13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of			
proposed completion or recompletion. FULL CHOKE COM 01-WORKOVER DUE TO POSSIBLE LEAK IN TUBING			
05/03/2013-05/07/2013-PX PLUG IN X-NIPPLE/PACKER @ 12150'VIA SLICKLINE, RELEASE ON/OFF TOOL, TRIP OUT OF HOLE W/ 2 3/8" PRODUCTION TUBING, RIGH UP HYDROTESTES AND TEST TUBING BACK IN THE HOLE, REPLACED BAD JOINTS, LATH ONTO ON/OFF TOOL, PULL PX PLUG FROM X-NIPPLE/PACKER, SWABBED WELL, RESUMED			
PRODUCTION VIA NATURAL FLOW.			
Jubing depth?			
· · · · · · · · · · · · · · · · · · ·	/ <i>/</i> /		
Spud Date:	Rig Release Date:	<u> </u>	
I hereby certify that the jaformation at	ove is true and complete to the best of	my knowledg	ge and belief.
SIGNATORE DALL & MA	TITLE SR.RE		
Type or print nameIENNIFER MO	· · · · ·		ANALYST_DATE05/08/2013
For State Use Only	SLET		.COMPHONE: _817-872-7822
APPROVED BY: Conditions of Approval (if any):	1 TITLE DISTIL	Sylein	DATE 5/10/2013
<u>,</u>	ν.		
i		i	
		.:	$\ell^{(n)}$
	•		

~