

Submit 1 Copy To Appropriate District Office
District I - (575) 393-6161
1625 N. French Dr., Hobbs, NM 88240
District II - (575) 748-1283
811 S. First St., Artesia, NM 88210
District III - (505) 334-6178
1000 Rio Brazos Rd., Aztec, NM 87410
District IV - (505) 476-3460
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico

Department of Minerals and Natural Resources

Form C-103

Revised August 1, 2011

RECEIVED

MAY 24 2013 CONSERVATION DIVISION

NMOC D ARTESIA
1220 South St. Francis Dr.
Santa Fe, NM 87505

WELL API NO.

30-015-01945

5. Indicate Type of Lease

STATE ☒ FEE ☐

6. State Oil & Gas Lease No.

B9222

7. Lease Name or Unit Agreement Name

State KH 29

8. Well Number 4

9. OGRID Number 16696

10. Pool name or Wildcat

Artesia QUGBSA

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: Oil Well ☒ Gas Well ☐ Other ☐

2. Name of Operator

OXY USA Inc.

3. Address of Operator

P.O. Box 50250 Midland, TX 79710

4. Well Location

Unit Letter P : 660 feet from the south line and 990 feet from the east line
Section 19 Township 18S Range 28E NMPM County Leakey

11. Elevation (Show whether DR, RKB, RT, GR, etc.)

3592'

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐ MULTIPLE COMPL ☐
DOWNHOLE COMMINGLE ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ P AND A ☒
CASING/CEMENT JOB ☐

OTHER: ☐

OTHER: ☐

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

- 5/17/13 MIRU PU, unseat pump, start to POOH w/ rods & pump.
5/18/13 Continue to POOH w/ Rods & pump. NDWH, NU BOP, POOH w/ tbg. RIH w/ WL & set CIBP @ 1990', POOH. RIH w/ tbg & tag CIBP @ 1990'.
5/19/13 Circ hole w/ 10# MLF, spot 55sx CL C cmt, PUH, WOC. RIH & tag cmt @ 1005', POOH. RIH & set pkr @ 30', RIH w/ WL & perf @ 504', EIR @ 1.5BPM @ 500# w/ no returns, sqz 35sx CL C cmt, WOC.
5/20/13 RIH & tag cmt @ 501', contact Maxie Brown-NMOC D, rec appr to spot add'l cmt. Spot 15sx CL C cmt, POOH, WOC. RIH & tag cmt @ 315', POOH. RIH w/ WL & perf 4-1/2" & 8-5/8", POOH w/ WL. RIH & set pkr @ 30', EIR @ 2BPM w/ partial returns, sqz 150sx CL C cmt, lost circ during displacement. WOC.
5/21/13 RIH & tag cmt @ 125', RIH w/ WL & perf 4-1/2" & 8-5/8" @ 125', POOH w/ WL. RIH & set pkr @ 30', EIR w/ full returns, sqz 40sx CL C cmt, circ to surf, POOH w/ pkr, ND BOP top off csg, RDPU.

Spud Date:

Rig Release Date:

File Current C103 P&A
for final inspection

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE

David Stewart

TITLE

Regulatory Advisor

DATE

5/22/13

Type or print name

David Stewart

E-mail address: david_stewart@oxy.com

PHONE: 432-685-5717

For State Use Only

APPROVED BY:

Dr. J. Spewison

TITLE

Dr. J. Spewison

DATE

5/29/2013

Conditions of Approval (if any):

* Submit Subsequent C-103