	Submit 1 Copy To Appropriate District		State of Ne	W. Mar				Forme	C-103
	Office District I – (575) 393-6161	Energy	, Minerals and				ŀ	Form Revised July	
	1625 N. French Dr., Hobbs, NM 88240 District II (575) 748-1283					WELL A	PI NO. 30-02	3-20016	
	811 S. First St., Artesia, NM 88210		CONSERVA			5. Indica	te Type of Leas		
	District III – (505) 334-6178 1000 Rio Brazos Rd., Aztec, NM 87410	1	220 South S			ST	ATE 🔀	FEE 🗌	
	<u>District IV</u> – (505) 476-3460 1220 S. St. Francis Dr., Santa Fe, NM 87505		Santa Fe, 1	NM 875	05	6. State	Oil & Gas Leas 39224	e No.	
		TICES AND R. POSALS TO DRILL			BACK TO A	7. Lease	Name or Unit A	Agreement	Name ·
	DIFFERENT RESERVOIR. USÈ "APP PROPOSALS.)	LICATION FOR P	ERMIT" (FORM C	C-101) FOR	SUCH		chet North L	Jnit 25 S	State
	1. Type of Well: Oil Well	Gas Well 🚺	C Other			8. Well 1	001	<u></u>	
	2. Name of Operator	. Hughes (ompany	I P		9. OGRI	D Number 2510	х С Л	·.
	3. Address of Operator	indgries (ompany,			10. Pool	name or Wildc		
	P.O. Box 669, 208 E. Ho	uston St., E	Beeville, TX	(7810 ⁾	4-0669	P	ercha Sha	le	-
	4. Well Location								
	Unit Letter <u>G</u>		et from the		line and	4620	_feet from the _		line
	Section 25		ownship 30S on <i>(Show wheth</i>			NMPM	Cour	ty Hidal	qo
			4494	.32' G	R	ac.)			
•	<u>Un negati ağıranının mananda ayının serinde den kanana ayının ayını ayının ayının ayın ay</u>								
	12. Checl	<pre>c Appropriate</pre>	Box to India	cate Nat	ure of Notic	e, Report of	r Other Data	• •	
	NOTICE OF		τO·	1	SI	IBSEQUE	NT REPOR	TOF	
	PERFORM REMEDIAL WORK [-		REMEDIAL WO			RING CASE	NG 🗌 ·
	TEMPORARILY:ABANDON [CHANGE F			COMMENCE E		NS 🔀 🛛 P ANI	D A C	
			COMPL [CASING/CEME	ENT JOB			
	CLOSED-LOOP SYSTEM		.		OTHER:				
	OTHER: 13. Describe proposed or con			ate all pe	rtinent details,				
	OTHER 13. Describe proposed or con of starting any proposed	work). SEE RU		ate all pe	rtinent details,				
	OTHER: 13. Describe proposed or con	work). SEE RU		ate all pe	rtinent details,				
, ,	OTHER: 13. Describe proposed or con of starting any proposed proposed completion or s	work). SEE RU recompletion.	JLE 19.15.7.14	ate all pe NMAC.	rtinent details, For Multiple (Completions:	Áttach wellbor	e diagram c	of
, 8	OTHER 13. Describe proposed or con of starting any proposed	work). SEE RU recompletion.	JLE 19.15.7.14	ate all pe NMAC.	rtinent details, For Multiple (Completions:	Áttach wellbor	e diagram c	of
8	OTHER: 13. Describe proposed or con of starting any proposed proposed completion or s	work). SEE RU recompletion.	JLE 19.15.7.14	ate all pe NMAC.	rtinent details, For Multiple (Completions:	Áttach wellbor	e diagram c	of
8	OTHER: 13. Describe proposed or con of starting any proposed proposed completion or s	work). SEE RU recompletion.	JLE 19.15.7.14	ate all pe NMAC.	rtinent details, For Multiple (Completions:	Áttach wellbor	e diagram c 46' to 4	of 8'.
3	OTHER: 13. Describe proposed or con of starting any proposed proposed completion or s	work). SEE RU recompletion.	JLE 19.15.7.14	ate all pe NMAC.	rtinent details, For Multiple (Completions:	Áttach wellbor	e diagram c	of 8'.
5	OTHER: 13. Describe proposed or con of starting any proposed proposed completion or s	work). SEE RU recompletion.	JLE 19.15.7.14	ate all pe NMAC.	rtinent details, For Multiple (Completions:	Attach wellbor	e diagram c 46' to 4 EIVE	of 8'. D
8	OTHER: 13. Describe proposed or con of starting any proposed proposed completion or s	work). SEE RU recompletion.	JLE 19.15.7.14	ate all pe NMAC.	rtinent details, For Multiple (Completions:	Attach wellbor Iled from REC SEP	e diagram c 46' to 4 EIVE 09 2013	of 8'. D
8	OTHER: 13. Describe proposed or con of starting any proposed proposed completion or s	work). SEE RU recompletion.	JLE 19.15.7.14	ate all pe NMAC.	rtinent details, For Multiple (Completions:	Attach wellbor Iled from REC SEP	e diagram c 46' to 4 EIVE 09 2013	of 8'. D
8	OTHER: 13. Describe proposed or con of starting any proposed proposed completion or s	work). SEE RU recompletion.	JLE 19.15.7.14	ate all pe NMAC.	rtinent details, For Multiple (Completions:	Attach wellbor	e diagram c 46' to 4 EIVE 09 2013	of 8'. D
8	OTHER: 13. Describe proposed or co of starting any proposed proposed completion or : B/29/2013 Well Shut in	work). SEE RU recompletion.	JLE 19.15.7.14	ate all pe NMAC.	rtinent details, For Multiple (ve to loca	Completions:	Attach wellbor Iled from REC SEP	e diagram c 46' to 4 EIVE 09 2013	of 8'. D
8	OTHER: 13. Describe proposed or con of starting any proposed proposed completion or s	work). SEE RU recompletion.	JLE 19.15.7.14	ate all pe NMAC.	rtinent details, For Multiple (ve to loca	Completions:	Attach wellbor Iled from REC SEP	e diagram c 46' to 4 EIVE 09 2013	of 8'. D
	OTHER: 13. Describe proposed or completion of starting any proposed proposed completion or a second start of the second start	work). SEE RU recompletion. for 19 day	JLE 19.15.7.14 ys. Tidwe	ate all pe NMAC.	rtinent details, For Multiple (ve to loca	Completions:	Attach wellbor Iled from REC SEP NMOCE	e diagram c 46' to 4 EIVE 09 2013	of 8'. D
	OTHER: 13. Describe proposed or co of starting any proposed proposed completion or : B/29/2013 Well Shut in	work). SEE RU recompletion. for 19 day	JLE 19.15.7.14 ys. Tidwe	ate all pe NMAC.	rtinent details, For Multiple (ve to loca	Completions:	Attach wellbor Iled from REC SEP NMOCE	e diagram c 46' to 4 EIVE 09 2013	of 8'. D
	OTHER: 13. Describe proposed or completion of starting any proposed proposed completion or a second start of the second start	work). SEE RU recompletion. for 19 day	JLE 19.15.7.14 ys. Tidwe	ate all pe NMAC.	rtinent details, For Multiple (ve to loca	Completions:	Attach wellbor Iled from REC SEP NMOCE	e diagram c 46' to 4 EIVE 09 2013	of 8'. D
	OTHER: 13. Describe proposed or completion of starting any proposed proposed completion or a second start of the second start	work). SEE RU recompletion. for 19 day	JLE 19.15.7.14 ys. Tidwe	ate all pe NMAC.	rtinent details, For Multiple (ve to loca	Completions: tion. Dri edge and belie	Attach wellbor Iled from REC SEP NMOCE	e diagram c 46' to 4 EIVE 09 2013	of 8'. D
	OTHER: 13. Describe proposed or completion or starting any proposed proposed completion or starting and proposed completion or starting and the start in the sta	work). SEE RU recompletion. for 19 day 2012	JLE 19.15.7.14 ys. Tidwe Rig Rel and complete t	ease Date	rtinent details, For Multiple (ve to loca ve to loca t of my knowle rations M	Completions: tion. Dri edge and belie anager	Attach wellbor Iled from REC SEP NMOCE	e diagram o 46' to 4 EIVE 09 2013 ARTES 9/5/20	of 8'. D ∋!A 013
	OTHER: 13. Describe proposed or completion or starting any proposed proposed completion or starting and proposed completion or starting and the start of the sta	work). SEE RU recompletion. for 19 day 2012	JLE 19.15.7.14 ys. Tidwe Rig Rel and complete t	ease Date	rtinent details, For Multiple (ve to loca	Completions: tion. Dri edge and belie anager	Attach wellbor Iled from REC SEP NMOCE	e diagram c 46' to 4 EIVE 09 2013 0 ARTES	of 8'. D ∋!A 013
	OTHER: 13. Describe proposed or completion or starting any proposed proposed completion or starting and proposed completion or start in a specific start in the	work). SEE RU recompletion. for 19 day 2012 on above is true R. Ilseng	JLE 19.15.7.14 ys. Tidwe Rig Rel and complete t	ease Date to the bes address:	rtinent details, For Multiple (ve to loca ve to loca t of my knowle rations M	Completions: tion. Dri edge and belie anager	Attach wellbor	e diagram c 46' to 4 EIVE 09 2013 ARTES 9/5/20 361/358	of 8'. D ∋!A 013 8-3752
	OTHER: 13. Describe proposed or completion or starting any proposed proposed completion or starting and proposed completion or starting and the start of the sta	work). SEE RU recompletion. for 19 day 2012 on above is true R. Ilseng	JLE 19.15.7.14 ys. Tidwe Rig Rel and complete t E-mail	ease Date to the bes address:	rtinent details, For Multiple (ve to loca ve to loca t of my knowle rations M	Completions: tion. Dri edge and belie anager	Attach wellbor	e diagram c 46' to 4 EIVE 09 2013 ARTES 9/5/20	of 8'. D ∋!A 013 8-3752
	OTHER: 13. Describe proposed or como of starting any proposed proposed completion or it B/29/2013 Well Shut in B/29/2013 Well Shut in Spud Date: 5/26/ I hereby certify that the informati SIGNATURE <u>Jeffer</u> Type or print name <u>Jeffer</u> For State Use Only APPROVED B	work). SEE RU recompletion. for 19 day 2012 on above is true R. Ilseng	JLE 19.15.7.14 ys. Tidwe Rig Rel and complete t E-mail	ease Date to the bes address:	rtinent details, For Multiple (ve to loca ve to loca t of my knowle rations M	Completions: tion. Dri edge and belie anager	Attach wellbor	e diagram c 46' to 4 EIVE 09 2013 ARTES 9/5/20 361/358	of 8'. D ∋!A 013 8-3752