Submit 1 Copy To Appropriate District Office	State of New Mexico		Form C-103
<u>District I</u> – (575) 393-6161	Energy, Minerals and Natural Resources		Revised August 1, 2011
1625 N. French Dr., Hobbs, NM 88240			WELL API NO.
<u>District II</u> – (575) 748-1283 811 S. First St., Artesia, NM 88210	OIL CONSERVATION DIVISION		30-015-40508
District III - (505) 334-6178	1220 South St. Francis Dr.		5. Indicate Type of Lease STATE ☐ FEE ☐
1000 Rio Brazos Rd., Aztec, NM 87410 District IV – (505) 476-3460	Santa Fe, NM 87505		STATE FEE 6. State Oil & Gas Lease No.
1220 S. St. Francis Dr., Santa Fe, NM			o. State off & das Lease No.
87505			
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A			7. Lease Name or Unit Agreement Name
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH		Turquoise PWU 27	
PROPOSALS.)		8. Well Number 7H	
1. Type of Well: Oil Well Gas Well Other			
2. Name of Operator Devon Energy Production Company, L. P.			9. OGRID Number 6137
Devon Energy Production Company, L.P. 3. Address of Operator			10. Pool name or Wildcat
333 W. Sheridan, Oklahoma City, Ok 73102-8260			Parkway West; Bone Spring
		Turkway West, Bone Spring	
4. Well Location			
Unit Letter_L 2200feet from theSOUTH line and _330feet from the WESTline			
Section 27 Township 19S Range 29E NMPM EDDY County			
11. Elevation (Show whether DR, RKB, RT, GR, etc.)			
	3111.5' GL		The state of the s
40 61 1			-
12. Check A	appropriate Box to Indicate N	lature of Notice,	Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:			
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WOR			
TEMPORARILY ABANDON	CHANGE PLANS		ILLING OPNS. P AND A
PULL OR ALTER CASING	MULTIPLE COMPL	CASING/CEMEN	
DOWNHOLE COMMINGLE	MOETH LE COMI E	CASING/CEIVILIN	П 30В
BOWINIOLE GOMMINGLE			
OTHER:		OTHER: Comple	tion Report
13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date			
of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of			
proposed completion or recompletion.			
proposed compression or recompression.			
10/1/13 - 11/6/13 MIRU WL. RIH w/ CBL. TIH w/ perf guns frac& perf 7150 -11,399' w/ 6 stages: Total:128,325# 100 mesh sd;			
1,363,618# 20/40 sd & 454,878# 20/40 Super LC sd. RU PU & DO frac plugs. LH & CO to PBTD. CHC. Test csg to 1000 psiND			
BOP. NU WH. TOP.			
		_	
PEOCH			
NOV 14 2013 NMOCD ARTESIA			
NOV 14 2212			
1 4 2013			
		/ N	IMOCD ARTES.
		CHANGE	- SIA
I hereby certify that the information above is true and complete to the best of my knowledge and belief.			
SIGNATURE DATE 11/12/13			
Signature of the State of the S			
Type or print name _Judy A. Barnett E-mail address: <u>Judith.Barnett@dvn.com</u> PHONE : 405.228.8699			
For State Use Only			
- Al Val	Ø A	AS much	.1 .1
APPROVED BY:	TITLE DOST	11 Spenison	DATE 11/19/2013
Conditions of Approval (if any):	•	•	• •