

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Form C-141  
Revised August 8, 2011

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Submit 1 Copy to appropriate District Office in  
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

*nHMP 1409 742947* OPERATOR  Initial Report  Final Report

Name of Company Apache Corporation	<i>873</i>	Contact Larry Baker
Address 8 Ellison Lane Eunice, NM 88231		Telephone No. 432-631-6982
Facility Name Lee Federal # 87		Facility Type Oil Well
Surface Owner Federal	Mineral Owner	API No. 30-015-41842


LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
M	20	17S	31E	330'	FSL	990'	FVL	Eddy

Latitude \_\_\_\_\_ Longitude \_\_\_\_\_

NATURE OF RELEASE

Type of Release Oil	Volume of Release 1/2 Barrel of oil	Volume Recovered 0
Source of Release Well Head	Date and Hour of Occurrence 4/2/2014 at 7:45 a.m.	Date and Hour of Discovery 4/2/2014 at 7:45 a.m.
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Jim Amos	
By Whom? Craig Maxwell	Date and Hour 4/2/2014 at 3:00 p.m.	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	



If a Watercourse was Impacted, Describe Fully.\*

Describe Cause of Problem and Remedial Action Taken.\*  
On the morning of 4/2/2014 Apache was performing a fishing job at the Lee Federal 87. At 7:45 a pressure release occurred at the surface through the stripping head. Valve on blow out preventer was shut to stop the release within 15 minutes. The cause of the pressure release is still under investigation.

Describe Area Affected and Cleanup Action Taken.\*  
A light oily overspray on lease pad and approximately 2,000 square feet of pasture north-east of pad was affected.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Larry Baker</i>		<b>OIL CONSERVATION DIVISION</b>	
Printed Name: Larry Baker		Approved by Environmental Specialist:	
Title: Environmental Technician		Approval Date:	Expiration Date:
E-mail Address: larry.baker@apachecorp.com		Conditions of Approval:	Attached <input type="checkbox"/>
Date: 4-4-2014	Phone: 432-631-6982		

\* Attach Additional Sheets If Necessary

*2 RP - 2248*