Submit 1 Copy To Appropriate District Office	State of New Mexico		Form C-103	
<u>District I</u> – (575) 393-6161	Energy, Minerals and Natu	ıral Resources	Revised July 18, 2013	
1625 N. French Dr., Hobbs, NM 88240 <u>District II</u> – (575) 748-1283			WELL API NO. 30-015-31889	
811 S. First St., Artesia, NM 88210	M 88210 OIL CONSERVATION DIVISION 78 1220 South St. Francis Dr.		5. Indicate Type of Lease	
<u>District III</u> – (505) 334-6178 1000 Rio Brazos Rd., Aztec, NM 87410	cc, NM 87410 Sonto Fo. NIM 87505		STATE STEE	
<u>District IV</u> – (505) 476-3460	Santa Fe, NM 87	7505°	6. State Oil & Gas Lease No.	
1220 S. St. Francis Dr., Santa Fe, NM 87505				
	ICES AND REPORTS ON WELLS)	7. Lease Name or Unit Agreement Name	
	SALS TO DRILL OR TO DEEPEN OR PL CATION FOR PERMIT" (FORM C-101) FO			
PROPOSALS.)	CATION FOR PERMIT (FORM C-101) FC	ok such	Cotton Draw	
1. Type of Well: Oil Well	Gas Well 🛛 Other		8. Well Number #90	
2. Name of Operator	<u></u>		9. OGRID Number	
Devon Energy Production Compar	ıy, LP		6137	
3. Address of Operator		10. Pool name or Wildcat		
333 W. Sheridan Avenue, Oklahoma City, OK 73102		PADUCA;DELAWARE		
4. Well Location				
Unit LetterD:	660feet from theNorth		feet from theWestline	
Section 36		inge 31E	NMPM County Eddy	
	11. Elevation (Show whether DR)			
(f)	3498' GL; 3525' KB; 27' KB to	<u>UL</u>		
12 Charle	Ammonwisto Dov to Indicate N	latura af Natica '	Danast as Other Data	
12. CHECK A	Appropriate Box to Indicate N	iature of Notice,	Report of Other Data	
NOTICE OF IN	ITENTION TO:	SUBS	SEQUENT REPORT OF:	
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WOR		<u> </u>		
TEMPORARILY ABANDON		_		
PULL OR ALTER CASING	MULTIPLE COMPL	CASING/CEMENT	JOB L	
DOWNHOLE COMMINGLE CLOSED-LOOP SYSTEM				
OTHER:		OTHER:	П.	
			give pertinent dates, including estimated date	
		C. For Multiple Con	npletions: Attach wellbore diagram of	
proposed completion or rec	ompletion.			
Actual Plug & Abandonment				
1. (7/9/14)-MIRU. POOH w/existing 2-7/8" production tubing and rod pump.				
			lid not tag CIBP @ 7,600'. Spot 50 sx Cl C	
	7,634'. Spot 50 sx Cl C @ 7,634'.	Tagged TOC @ 7,35	0'. (DV tool @ 7504'. Delaware open perfs	
7643-8184.) 3. Spot 40 sx Cl C @ 6,160'. Tagged TOC @ 5,945'.				
		5'. Unable to pull.	Unable to pump in casing cuts @ 500 psi.	
Spot 35 sx Cl C @ 4,359'.	Tagged TOC @ 4,160'. (B.Salt @	4215'. 9-5/8 shoe @	0 4256'.)	
	s x Cl C inside/out on 7" casing. To			
	x Cl C inside/out on 7" casing. Tagg x Cl C inside/out on 7" casing to sur		3-3/8 shoe @ 677')	
	Set dry hole marker. Wellbore pla		NM OIL CONSERVATIO	
,	,		ARTESIA DISTRICT	
			AUG 0 7 2014	
Spud Date:	Rig Release Da	ate:	7.00 0 7 201 4	
6			DECEMEN	
I hereby certify that the information	above is true and complete to the b	ast of my knowledge	RECEIVED	
r hereby certify that the information	above is true and complete to the bi	est of my knowledge	e and benef.	
SIGNATURE RANNE S	1.4		0 - 111	
SIGNATURE / PVVVQ /	TITLE_Ope	erations Tech	DATE 8-5-14	
Type or print name Ronnie Slack	F-mail address: Ronnie	Slack@dyn.com	PHONE: 405-552-4615	
For State Use Only	Z man addressRounte.	SMCKWUVII.COIII	1110116405-332-4013	
	Λ . Δ	#50	2/12/11	
APPROVED BY: // Conditions of Approval (if any)	TITLE U/37	- yeurs	1 DATE 8/12/14	
Conditions of Approval (if any):	Shart Schoenunt	C-103		

