

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

RECEIVED

OCT 8 0 2014

Form C-141
Revised August 8, 2011

Submit Copy to appropriate District Office in
conformance with 19.15.29 NMAC.

Release Notification and Corrective Action

11AB1430857433

| | | | | | |
|---------------------------------|--|---------------|----------------------------|---|--|
| Name of Company Oxy USA | | 16696 | OPERATOR | <input type="checkbox"/> Initial Report | <input checked="" type="checkbox"/> Final Report |
| Address 1502 W Commerce | | | Contact Tiffney Burkham | | |
| Facility Name Seven Rivers 17-1 | | | Telephone No. 575-706-3616 | | |
| | | | Facility Type | | |
| Surface Owner | | Mineral Owner | | API No. 30-015-33430 | |

LOCATION OF RELEASE

| Unit Letter | Section | Township | Range | Feet from the | North/South Line | Feet from the | East/West Line | County |
|-------------|---------|----------|-------|---------------|------------------|---------------|----------------|--------|
| N | 17 | 20S | 25E | 1250 | S | 1650 | W | Eddy |

Latitude _____ Longitude _____

NATURE OF RELEASE

| | | |
|--|---|-----------------------------------|
| Type of Release GAS | Volume of Release 2,200MCF | Volume Recovered |
| Source of Release | Date and Hour of Occurrence 10/4/2014 | Date and Hour of Discovery |
| Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required | If YES, To Whom? Mike Bratcher NMOCD | |
| By Whom? Tiffney Burkham | Date and Hour | |
| Was a Watercourse Reached? <input type="checkbox"/> Yes <input type="checkbox"/> No | If YES, Volume Impacting the Watercourse. | |
| If a Watercourse was Impacted, Describe Fully.* | | |
| Describe Cause of Problem and Remedial Action Taken.* Flaring was due to IBGP Shutdown. Flaring due to Enterprise Compressor down. | | |
| Describe Area Affected and Cleanup Action Taken.* | | |
| I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations. | | |
| Signature: <i>Tiffney Burkham</i> | OIL CONSERVATION DIVISION | |
| Printed Name: Tiffney Burkham | Signed By: <i>Mike Bratcher</i> Approved by Environmental Specialist | |
| Title: HES Administrative Assistant | Approval Date: 11/4/14 | Expiration Date: N/A |
| E-mail Address: Tiffney_burkham@oxy.com | Conditions of Approval: FINAL | Attached <input type="checkbox"/> |
| Date: 8/16/2014 Phone: 575-628-4116 | | |

* Attach Additional Sheets If Necessary

2RP-2574