Submit 1 Gopy To Appropriate District Office	Energy, Minerals and Natural Resources Or., Hobbs, NM 88240 1748-1283 Intesia, NM 88210 19334-6178 OIL CONSERVATION DIVISION 1220 South St. Francis Dr.		Form C-103 Revised July 18, 2013	
<u>District 1</u> – (575) 393-6161 1625 N. French Dr., Hobbs, NM 88240			WELL API NO.	
<u>District II</u> – (575) 748-1283 811 S. First St., Artesia, NM 88210			30-015-21182 5. Indicate Type of L	eace
<u>District III</u> (505) 334-6178 1000 Rio Brazos Rd., Aztec, NM 87410			STATE	FÉE 🛛
<u>District IV</u> ~ (505) 476-3460	Santa Fe, NM 87505		6. State Oil & Gas L	ease No.
1220 S. St. Francis Dr., Santa Fe, NM 87505		•		·
SUNDRY NOT	ICES AND REPORTS ON WELLS		7. Lease Name or Ur	nit Agreement Name
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH			Dogges "10" Com	
PROPOSALS.)			Rogers "10" Com 8. Well Number	1
Type of Well: Oil Well Name of Operator	Gas Well 🛛 Other		9. OGRID Number	
Fasken Oil and Ranch, Ltd.	,		151416	
3. Address of Operator			10. Pool name or Wi	ldcat
6101 Holiday Hill Road, Midland,	TX 79707		Atoka; Penn	
4. Well Location				
Unit Letter <u>I</u> :	1650' feet from the South		feet from the	Eastline
Section 10	Township 18S 11. Elevation (Show whether DR	Range 26		County Eddy
	3344' KB	K, KKB, KI, GK, eic.		
			*	
12. Check A	Appropriate Box to Indicate N	Nature of Notice,	Report or Other Da	nta
			-	
NOTICE OF IN	ITENTION TO:	1 .	SEQUENT REPO	
TEMPORARILY ABANDON	PLUG AND ABANDON CHANGE PLANS	REMEDIAL WOR		.TERING CASING ☐ AND A
PULL OR ALTER CASING	MULTIPLE COMPL	CASING/CEMEN		
DOWNHOLE COMMINGLE				
CLOSED-LOOP SYSTEM		·.		<u>_</u>
OTHER:	Alatad anamations (Classic state all	OTHER:	d aiva mantinaét dataa i	naludina actimated data
	oleted operations. (Clearly state all ork). SEE RULE 19.15.7.14 NMA			
proposed completion or rec		c. For Manipie co	impletions. Attach well	oore diagram or
11 05 14 10 11 14				
11-25-14 - 12-11-14				
MIRU BCM and Associates plug	ging equipment, set steel pit an	d bled down well t	o steel pit. BCM & As	ssociates pusher
decided to run gauge ring on wire	eline, called for and waited on w	ireline. RU BCM	wireline truck, RIW w	/ 3.668" 2-7/8" collar
and 4' sub on wireline to 8840' w				
pusher Daniel Martinez on 11-24 information.	-14, talked w/ Randy at 3:00 p.n	n. MST. Please s	ee sundry notice attac	chment for additional
Approved for plugging of well	bore only.			•
Libility under bond is retain	ed pending receipt		NM (DIL CONSERVATION
of C-103 (Subsequent Report which may be found at OCD	Web Page under			ARTESIA DISTRICT
Forms, www.cmnrd.state.nm.	us/ocd.	<u> </u>		1 LEC 1 8 2014
Spud Date:	Rig Release D	ate:		·
	<u>_</u>	L		RECEIVED
I hereby certify that the information	above is true and complete to the b	est of my knowledg	ge and belief.	
SIGNATURE June	TITLE	Regulatory Anal	yst DATE	12-17-2014
 				
Type or print name Kim Ty	E-mail addres	s: <u>kimt@forl</u>	l.com PHONE:	432-687-1777
For State Use Only	$\langle ada \rangle$	W.	h	11/2/
APPROVED BY:	TITLE TITLE	57/1/Jeg-	LW87 DATE	12/19/2014
Conditions of Approval (if any):	, , , , , , , , , , , , , , , , , , , ,			7 /

\$ 50 bmt Subsequent C-103

Fasken Oil and Ranch, Ltd.

Rogers "10" Com #1

API No. 30-015-21182

Plug and Abandon

Sundry Notice Attachment

11-25-14 - 12-11-14

Set CIBP @ 8825'. RIW w/ 2-3/8" tubing and did not tag CIBP, picked up 1 joint 2-3/8" tubing, RIW to 8855' and did not tag CIBP. RU BCM wireline truck on tubing, RIW w/ 10' x 7/8" rod on wireline, tagged at 8910'. POW w/ 2-3/8" tubing, observed CIBP set and broke in proper position. Contacted Randy Dodd w/ NMOCD at 7:40 a.m. MST, received approval to set CIBP no higher than 8750'. Set CIBP @ 8759'. Packed off plug, rotated off CIBP, and pushed CIBP to 8783' and stacked out on CIBP. Note: CIBP set at 8783'. Spotted 25 sx class "H" cement on top of CIBP at 8783'. Tagged TOC at 8365', notified Midland office and Randy Dodd w/ NMOCD at 8:48 a.m. MST on 12-3-14 via left voice mail. Cut 4-1/2" casing @ 7375'. Tried to pull casing free without success. Notified Midland office and Randy Dodd at NMOCD at 3:00 p.m. MST on 12-3-14 and received instructions to spot 25 sx cement plug 50' below cut at 7375' and no tag required. RIW w/ 2-3/8" tubing to 7428', 53' below casing cut at 7375' and spotted 25 sx Class "H" cement, did not have to tag this plug. POW and LD 48 joints 2-3/8" tubing to 5908'; 8' below Wolfcamp at 5900'. Contacted NMOCD, Randy Dade at 7:18 a.m. MST on 12-4-14, permission was given to spot 25 sx Class "C" cement across Wolfcamp interval, waited 4 hours and tag. Spotted 25 sx Class "C" cement and SD for 4 hours. Tagged TOC at 5465', notified Midland office and NMOCD, Randy Dade, via voice mail w/ TOC at 3:05 p.m. MST on 11-4-14. Cut and pulled 4-1/2" casing at 5000'. Notified NMOCD, Randy Dade at 8:20 a.m. MST on 12-9-14 w/ details of where 4-1/2" casing was cut, he wanted stub plug and plug at 4500'. Tagged top of casing at 5001'. Spotted 75 sx Class "C" cement at 5052'. Tagged TOC at 4768', notified Midland office and NMOCD, Randy Dade at 3:16 p.m. MST on 12-9-14. Spotted 65 sx Class "C" cement at 4512'. Tagged TOC at 4318', 82' above 4400', notified Midland office and NMOCD, Randy Dade at 7:38 a.m. MST on 12-10-14 via voicemail. Spotted 35 sx Class "C" cement at 1883'. Tagged TOC at 1710', 40' above 1750', notified Midland office and NMOCD, Randy Dade at 2:40 p.m. MST on 12-10-14 via voicemail. Spotted 60 sx Class "C" cement at 1278'. Tagged TOC at 1062', 98' above 1160', notified Midland office and NMOCD, Randy Dade at 7:13 a.m. MST on 12-11-14 via voicemail. Spotted 30 sx class "C" cement at 517', did not tag plug. Spotted 25 sx Class "C" cement at 106' to surface. WOC for 4 hours and cut all wellheads off, RD plugging unit and released all rental equipment. Notified NMOCD, Randy Dade at 2:17 p.m. MST on 12-11-14, final plugs spotted, well plugged to surface.