Form 3160-5 (August 2007)

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

NM OIL CONSERVATION

ARTESIA DISTRET

FORM APPROVED OMB NO. 1004-0135 Expires: July 31, 2010

SUNDRY NOTICES AND REPORTS ON WELLS JAN 13 2015 not use this form for proposals to drill and

5. Lease Serial No.

54-NMNM27279 8HL-LC 06840

Do not use this form for proposals to drill or to re-enter an abandoned well. Use form 3160-3 (APD) for such proposals.

6. If Indian, Allottee or Tribe Name

		RE RE	CEIVED			
SUBMIT IN TRI	7. If Unit or CA/Agreement, Name and/or No. NM /33367					
Type of Well Gas Well				8. Well Name and No BRADLEY 31 B2).	
2. Name of Operator	Contact: JACK	IE LATHAN		9. API Well No:		
MEWBOURNE OIL COMPAN	Y E-Mail: jlathan@mewbou	rne.com		30-015-40562		
3a. Address PO BOX 5270 HOBBS, NM 88241		Phone No. (include area of 575-393-5905	code)	10. Field and Pool, o BONE SPRING		
4. Location of Well (Footage, Sec., T	., R., M., or Survey Description)			11. County or Parish	, and State	
Sec 31 T18S R30E Mer NMP	NWNW 720FNL 10FWL			EDDY COUNT	Y, NM	
12. CHECK APPR	ROPRIATE BOX(ES) TO IND	ICATE NATURE (OF NOTIĆE, R	EPORT, OR OTHE	ER DATA	<u> </u>
TYPE OF SUBMISSION		ТҮР	E OF ACTION			
☐ Notice of Intent	☐ Acidize	☐ Deepen	☐ Produc	tion (Start/Resume)	☐ Water	Shut-Off
	☐ Alter Casing	☐ Fracture Treat	Reclan	nation	☐ Well I	Integrity
Subsequent Report	□ Casing Repair	■ New Construction	□ Recom	Recomplete		
☐ Final Abandonment Notice	☐ Change Plans	☐ Plug and Abandon	☐ Tempo	□ Temporarily Abandon		ıd
. i	□ Convert to Injection	□ Plug Back	■ Water	Disposal		
w/180 sks Thixad Class C with CaCl2. Mixed 14.8#/g w/1.34 y 190# @ 4 BPM. Ran temperat stages w/250 Class C w/4% C	le. TD'd hole @ 325'. Ran 325' additives. Mixed @ 14.4#/g w/ rd. Plug down @ 10:15 AM 07/2 ure survey indicating TOC @ 2/ aCl2. Mixed @ 14.8#/g w/1.34 y ular to 1500#. At 11:30 P.M. 07 4" bit.	1.65 yd. Tail w/350 : 21/14. Did not circ ci 26'. RIH w/1" pipe & yd. Circ 10 sks of cn	sks Class C w/ mt. Lift pressur tag @ 215'. C nt to the pit. W	2% e @ mt in 7 DC.		
Copy of Temperature survey a	ttached.	<i>y</i> *				
Bond on file: NM1693 nationwi		, , , , , , , , , , , , , , , , , , ,	Cospied k HVD NHIDK	ar record Divivios	•	
14. I hereby certify that the foregoing is	true and correct. Electronic Submission #256903 For MEWBOURNE Oll Committed to AFMSS for proc	L COMPANY, sent to essing by DEBORAH	the Carlsbad HAM on 10/17	2014 ()		000
Name(Printed/Typed). JACKIE LA	THAN	Title AUT	HORIZED A	PESENTATIVE-(IR REC	ORDI
Signature (Electronic Si	ubmission)	Date 08/1:	3/2014			
	THIS SPACE FOR FE			SE JAN 6	2015	
4				Lotriol	War	
Approved By.		Title		BUREAU OF LAND	MANAGEM	FNI
onditions of approval, if any, are attached crify that the applicant holds legal or equi hich would entitle the applicant to conduc	table title to those rights in the subject	lease Office		CARLSBAD FIE		



WELDING • BOP TESTING NIPPLE UP SERVICE • BOP LIFTS • TANDEM MUD AND GAS SEPARATORS

Pg.	of	

	19 merding semances	Lo	dagton, M	A • 675-3	96-4540	Pg	_ 01	
Company	Moultourne		_ Date:	723	.14	Invoice # ,	8-44-739	,
Leoso: 🏑	BRADLEY31 BLOAS							
Plug Size	&Type: (27, 12	Drill Pipe Siz	·•	MATE	Taste	- Luis Gb-	1	
Required	BOP:	· · · · · · · · · · · · · · · · · · ·	Insta	led BOP:				
Appropriate	Caaling Valve Must Be Open During BOP Test *			<i>)</i>	* Check Val	ve Musi 8o Open/Disable	d To Tost Kill Line Valves *	
#11 #10	H9 H7 #8	#26 #4 #4 #3 #25 Super Ch	#5 #88 Mud Gaug Valve	#6	Kelly/ Top Drive		Dark Valva #19 Stand Pipe Valve #24 Fig. 11W Valve #18 Pump Valve #21	
	Casing			٠.				
TEST 0	ITEMS TESTED	TEST LENGTH	LOW PSI	HIGH PSI	· 	REMARKS		
ij	ITEMS TESTED	TEST LENGTH	150 PSI	НІВН PSI 3000		HEMARKS		
1EST 0					3	HEMARKS		
ij	17	10/10	250	3 <i>0</i> 00				
2.	17 14	10/10	150 150	3000 3000	5767 -1	Zos	seret also	hav p 's
3.	17 14 19	10/10	150 150 150	<i>3დ</i> 0 3 <i>დ</i> 0 3000	5701 -1	Zos	such des	lucis 's
3.	17 14 19 18	10/10 10/10 10/10 15/10	150 150 150 250	3యం 3యు 3ంత	5701 -1	Zos	such des	lues p *=
3.4.5	17 14 19 18 15, 9, 7 13, 9, 7	10/10 10/10 10/10 10/10 10/10	250 250 250 250 250 250 250	3000 3000 3000 3000 1500	570/ -1	Zos	perch. Idea	her's
3.4.5.	17 14 19 18 15, 9, 7 13, 9, 7	10/10 10/10 10/10 10/10 10/10	250 250 250 250 250 256 250	3000 3000 3000 3000 5000 1500 2500	5767 -1	Zos	such de	har's
3 4 5 5 7 7	17 14 19 18 15,9,7 13,9,7 13,9,7	10/10 10/10 10/10 10/10 10/10 10/10	250 250 250 250 250 250 250	3000 3000 3000 3000 5000 5000 3000	57.01 -1	Zos	such des	heer 's
3.4.5.	17 14 18 18 15,9.7 13,9.7 14,10,7 14,10,7 14,10,7	10/10 10/10 10/10 10/10 10/10 10/10	250 250 250 250 250 250 250 250	3000 3000 3000 3000 3000 3000 3000	5707 -1	Zos	punh. Ilva	lice or "a
3.4.5.7.	17 14 19 18 15, 9, 7 13, 9, 7 14, 10, 8 13, 11, 3, 4, 6	10/10 10/10 10/10 10/10 10/10 10/10	250 250 250 250 250 250 250 250 250	3000 3000 3000 3000 3000 3000 3000 300	57.67 -1	Zos	probable de	hes p'
3.4.5.7.	17 14 19 18 15, 9, 7 13, 9, 7 14, 10, 8 13, 11, 3, 4, 6	10/10 10/10 10/10 10/10 10/10 10/10	250 250 250 250 250 250 250 250 250	3000 3000 3000 3000 3000 3000 3000 300	57.07 -1	Zos	such des	her'
3.4.5.7.	17 14 19 18 15, 9, 7 13, 9, 7 14, 10, 8 13, 11, 3, 4, 6	10/10 10/10 10/10 10/10 10/10 10/10	250 250 250 250 250 250 250 250 250	3000 3000 3000 3000 3000 3000 3000 300	5707 -1	Zos	purcha al la	hest's
3.4.5.7.	17 14 19 18 15, 9, 7 13, 9, 7 14, 10, 8 13, 11, 3, 4, 6	10/10 10/10 10/10 10/10 10/10 10/10	250 250 250 250 250 250 250 250 250	3000 3000 3000 3000 3000 3000 3000 300	5787 -1	Zos	durch dus	heor's
3.4.5.7.	17 14 19 18 15, 9, 7 13, 9, 7 14, 10, 8 13, 11, 3, 4, 6	10/10 10/10 10/10 10/10 10/10 10/10	250 250 250 250 250 250 250 250 250	3000 3000 3000 3000 3000 3000 3000 300	57.07 -1	Zos	such des	her'
3.4.5.7.	17 14 19 18 15, 9, 7 13, 9, 7 14, 10, 8 13, 11, 3, 4, 6	10/10 10/10 10/10 10/10 10/10 10/10	250 250 250 250 250 250 250 250 250	3000 3000 3000 3000 3000 3000 3000 300		Zos	such de	hest's
3.4.5.7.	17 14 19 18 15, 9, 7 13, 9, 7 14, 10, 8 13, 11, 3, 4, 6	10/10 10/10 10/10 10/10 10/10 10/10	250 250 250 250 250 250 250 250 250	3000 3000 3000 3000 3000 3000 3000 300	5787 -1	Zos	durch du	heer to
3,4,5,6,7,8,00	17 14 19 18 15, 9, 7 13, 9, 7 14, 10, 8 13, 11, 3, 4, 6	10/10 10/10 10/10 10/10 10/10 10/10	250 250 250 250 250 250 250 250 250	3000 3000 3000 3000 3000 3000 3000 300	57.07 -1	Zos	such de	har's


MELDING SERVICES, INC


Company Newboures Date 7-23-14
Lease BRADLEY ST BODA ED COM. SH. County Eddy NIVER
Drilling Contractor Patiers 140 Plug & Drill Pipe Size C27, 12, 4/284
Accumulator Pressure: Solo Manifold Pressure: 1500 - Annular Pressure: 1500 -
Accumulator Function Test - 00&G0#2
To Check - USABLE FLUID IN THE NITROGEN BOTTLES (III.A.2.c.i. or ii or iii)
Make sure all rams and annular are open and if applicable HCR is closed.
 Ensure accumulator is pumped up to working pressure! (Shut off all pumps)
1. Open HCR Valve. (If applicable)
2. Close annular.
3. Close all pipe rams.
4. Open one set of the pipe rams to simulate closing the blind ram.
5. For 3 ram stacks, open the annular to achieve the 50+ % safety factor. (5M and greater systems).
6. Record remaining pressure 1500 psi. Test Fails if pressure is lower than required.
a. {950 psi for a 1500 psi system} b. {1200 psi for a 2000 & 3000 psi system}
7. If annular is closed, open it at this time and close HCR.
To Check - PRECHARGE ON BOTTLES OR SPHERICAL (III.A.2.d.)
Start with manifold pressure at, or above, maximum acceptable pre-charge pressure:


- Start with manifold pressure at, or above, maximum acceptable pre-charge pressure:
 a. (800 psi for a 1500 psi system)
 b. [1100 psi for 2000 and 3000 psi system]
 - 1. Open bleed line to the tank, slowly. (gauge needle will drop at the lowest bottle pressure)
 - 2. Close bleed line. Barely bump electric pump and see what pressure the needle jumps up to.
 - 3. Record pressure drop les o psi. Test fails if pressure drops below minimum.
- Minimum: a. (700 psi for a 1500 psi system) b. (900 psi for a 2000 & 3000 psi system)

To Check - THE CAPACITY OF THE ACCUMULATOR PUMPS (III.A.2.f.)

- Isolate the accumulator bottles or spherical from the pumps & manifold.
- Open the bleed off valve to the tank, {manifold psi should go to 0 psi} close bleed valve.
 - 1. Open the HCR valve, (if applicable)
 - 2. Close annular
 - 3. With pumps only, time how long it takes to regain the required manifold pressure.
 - 4. Record elapsed time 1: 772 . Test falls if it takes over 2 minutes.
- a. (950 psi for a 1500 psi system) b. (1200 psi for a 2000 & 3000 psi system)







Rotary Wire Line SERVICE, INC. "Specializing to Pipe Recovery"

Hob	ba, Ne	ew Me	xico 88240	· ·							
		Co	ompany	M	lewboı	Jrne	9				
		W	ell	В	radlev	31	B 2 [DA F	ed Com 1	H	
1 %					,					• /	
00		Fie	eld								
Mewbourne Bradley 31 B 2 DA Fed Corn 18 Eddv		Co	ounty	Ε	ddy ·	•			State	NM	
82[Lo	cation:				API	#: 3	0-015-4056	2	
Company Mewbourne Well Bradley 31 E Field Eddy			170' FNL - 250' FWL								
radl dd	Ž										
) <u>s</u> a u	Z		····	SEC	30	TWF	18s	RG	E 30e		
) E		Perm	anent Dati	ım					Elevation		
Compai Well Field	State	Log l	Log Measured From								
Countries Countr	₿	Drillin	ng Measure	ed Fro	om						
Date				Γ	7/21/	14			······································		
Run Number	******				1						
Depth Driller											
Depth Logger					256	3'			······································		
Bottom Logged I	nterve	1	*******	<u> </u>	************						
Top Log Interval				ļ							
Open Hole Size Type Fluid					Wat						
Density / Viscosit				}	yvai	81					
Max. Recorded T	<u>omn</u>										
Estimated Cemer)			226	3'					
Time Well Ready	***************************************										
Time Logger on I		'n	·						· · · · · · · · · · · · · · · · · · ·		
Equipment Numb			~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~		10	<u> </u>		******	······································		
Location											
Recorded By					Bryan M	anle	у				
Witnessed By					Jerry Van	Winl	de				
Dun Number			Record				Ci.			Recor	
Run Number		lit	From		То		Si	ze	Weight	F	
					······································					+	
										 	
		·								1	
Casing Record			Size			Wg	t/Ft		. Тор		
Surface String			13 3/8						Floor Surfac	e	
Prof. String											
Production String							······				
Liner		<u></u>			_		····				

80tton To Section To	not, except in the case of gross	trical or other measuren	our part, be liable or	responsible for any lo	ss, costs, damages, or exp	enses
incurred or sustained by anyo	one resulting from any interpret general terms	ation made by any of out is and conditions set out i	in our current Price	employees. These inte Schedule.	erpretations are also subje	ct to our
		Commer	nts			
·						New square
						girant-rapid
	•				•	and the state of t
					•	Georgia
		·				·
,						er i en
				•		
Database File: Dataset Pathname: Presentation Format: Dataset Creation: Charted by:	bradley 31 b 2 da fed cor pass3 temp Mon Jul 21 16:42:52 201 Depth in Feet scaled 1:24	4 by Log PIP Cased	ihole Loggi	,	,	
		75		TEMP (degF)		125
		TEMP	think hadra angles a despuid tradition and a second solidate and the second solidate and second solidate a		·	
		(degF)				
		70.0				
	The state of the s	4 1 1		1 1		1 1.

.

