

ocd Artesia

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

FORM APPROVED
OMB No. 1004-0137
Expires: October 31, 2014

SUNDRY NOTICES AND REPORTS ON WELLS
Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals.

5. Lease Serial No.
NMLC-029338-A

6. If Indian, Allottee or Tribe Name

SUBMIT IN TRIPLICATE - Other instructions on page 2.

7. If Unit of CA/Agreement, Name and/or No.

1. Type of Well

Oil Well Gas Well Other

8. Well Name and No.
Gissler A Battery

2. Name of Operator
Burnett Oil Co., Inc.

9. API Well No.

3a. Address
Burnett Plaza - Suite 1500
801 Cherry Street, Unit 9 Fort Worth, Texas 76102

3b. Phone No. (include area code)
817-583-8730

10. Field and Pool or Exploratory Area

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)
approx: 609' FSL, 483' FEL, T17S, R30E, Sec. 11, Unit P, SESE

11. County or Parish, State
Eddy County, NM

12. CHECK THE APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT OR OTHER DATA

| TYPE OF SUBMISSION | TYPE OF ACTION | | | |
|--|---|---|--|--|
| <input checked="" type="checkbox"/> Notice of Intent | <input type="checkbox"/> Acidize | <input type="checkbox"/> Deepen | <input type="checkbox"/> Production (Start/Resume) | <input type="checkbox"/> Water Shut-Off |
| <input type="checkbox"/> Subsequent Report | <input type="checkbox"/> Alter Casing | <input type="checkbox"/> Fracture Treat | <input type="checkbox"/> Reclamation | <input type="checkbox"/> Well Integrity |
| <input type="checkbox"/> Final Abandonment Notice | <input type="checkbox"/> Casing Repair | <input type="checkbox"/> New Construction | <input type="checkbox"/> Recomplete | <input checked="" type="checkbox"/> Other <u>Production Facility</u> |
| | <input type="checkbox"/> Change Plans | <input type="checkbox"/> Plug and Abandon | <input type="checkbox"/> Temporarily Abandon | <u>Change</u> |
| | <input type="checkbox"/> Convert to Injection | <input type="checkbox"/> Plug Back | <input type="checkbox"/> Water Disposal | |

13. Describe Proposed or Completed Operation: Clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports must be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 must be filed once testing has been completed. Final Abandonment Notices must be filed only after all requirements, including reclamation, have been completed and the operator has determined that the site is ready for final inspection.)

Burnett is requesting permission to add an emergency flare to the Gissler A Battery. Updated Battery diagram is attached. The flare will be located on the already existing Gissler A 30 pad.

Flare will be a minimum 150' from the battery equipment. The flare will be 35' high and will follow the API standards. Flare will be metered to record flared gas.

LRD 2/11/15
Accepted for record
NMOCD

NM OIL CONSERVATION
ARTESIA DISTRICT

FEB 2 2015

RECEIVED

14. I hereby certify that the foregoing is true and correct. Name (Printed/Typed)
Leslie Garvis

Title Regulatory Coordinator

Signature

Leslie Garvis

Date

11/25/14

THIS SPACE FOR FEDERAL OR STATE OFFICE USE

Approved by

FIELD MANAGER

Title

Date

Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.

Office ARLSBAD FIELD OFFICE


Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

(Instructions on page 2)

BURNETT OIL CO., INC.
 EDDY COUNTY, NM
 GISSLER A FEDERAL BATTERY
 T 17S, R 30E, SEC 11, UNIT P, SESE
 APPROX: 609' FSL, 483' FEL
 LEASE: NMLC-029338-A

*Note: Flare will be located on the Gissler A 30 Pad

UPDATED: 11/25/2014



REVISION 5/8/2014

- | | | | |
|--|------------------------------|--|-------------------------------|
| | 500 BBL STEEL OIL SALES TANK | | 500 BBL FIBERGLASS WATER TANK |
| | 500 BBL STEEL OIL SALES TANK | | 500 BBL FIBERGLASS WATER TANK |
| | 500 BBL STEEL OIL SALES TANK | | 750 BBL FIBERGLASS GUN BARREL |
| | 210 BBL STEEL SKIM TANK | | 2 PHASE SEPARATOR |

SITE LEGEND

- FWKO
- HEATER TREATER
- WATER LINE
- OIL LINE
- GAS LINE
- FENCED FIREWALL

VALVE LEGEND

- LOAD LINE VALVE
- FILL LINE VALVE
- EQUALIZER LINE VALVE
- COMBUSTOR GAS METER
Meter# FMS 200F-33
- FLARE GAS METER
- CIRC LINE VALVE
- BS&W LOAD LINE VALVE
- WATER LINE VALVE
- COMBUSTOR
- EMERGENCY FLARE

COMBUSTOR LINE
 COMBUSTOR LINE
 FLARE LINE

BURNETT OIL CO., INC.
 EDDY COUNTY, NM
 GISSLER A FEDERAL BATTERY
 T 17S, R 30E, SEC 11, UNIT P, SESE
 APPROX: 609' FSL, 483' FEL
 LEASE: NMLC-029338-A

ATTACHMENT TO SITE FACILITY DIAGRAM

General sealing of valves, sales by tank gauge

Production Phase:

Load Line Valves sealed closed. Fill valve to tank that is in production will be open.

Equalizer valve to tank that is in production will be open. Circulation valves will be opened as necessary, then resealed.

BS&W Load Line valve will be sealed at all times, unless cleaning tanks, then resealed once tank maintenance is complete.

Sales Phase:

The tank from which sales are being made will be isolated by sealing closed the fill line valve, circulating valve, and the equalizer valve during sales and opening the sales valve. Upon completion of the sale, the sales valve will be resealed.

Sales by truck will be by tank gauge.

GISSLER A BATTERY

- GISSLER A 12
- GISSLER A 13
- GISSLER A 14
- GISSLER A 15
- GISSLER A 29
- GISSLER A 30
- GISSLER A 34
- GISSLER A 35
- GISSLER A 36
- GISSLER A 38
- GISSLER A 39
- GISSLER A 42

| | <u>VALVE</u> | <u>PRODUCTION PHASE</u> | <u>SALES PHASE</u> | <u>CIRCULATING</u> | <u>NOTE</u> |
|---|-------------------------------|-------------------------|--------------------|--------------------|---|
| 1 | LOAD LINE VALVE | CLOSED | OPEN | CLOSED | |
| 2 | PRODUCTION FILL LINE VALVE | OPEN OR CLOSED | CLOSED | CLOSED OR OPEN | |
| 3 | EQUALIZER LINE VALVE | OPEN | CLOSED | CLOSED OR OPEN | |
| 4 | CIRCULATING LINE VALVE | OPEN OR CLOSED | CLOSED | OPEN | RE-SEALED ONCE CIRCULATING IS COMPLETE |
| 5 | BS&W LOAD LINE VALVE | CLOSED | CLOSED | CLOSED | OPEN FOR TANK MAINTENANCE, RESEALED ONCE MAINTENANCE IS COMPLETE |
| 6 | WATER LINE VALVE | OPEN | NA | NA | WATER TANKS ARE ISOLATED FROM OIL PRODUCTION TANKS |