

Submit 1 Copy To Appropriate District Office
District I - (575) 393-6161
1625 N. French Dr., Hobbs, NM 88240
District II - (575) 748-1283
811 S. First St., Artesia, NM 88210
District III - (505) 334-6178
1000 Rio Brazos Rd., Aztec, NM 87410
District IV - (505) 476-3460
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy, Minerals and Natural Resources

Form C-103
Revised July 18, 2013

OIL CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87505

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)		WELL API NO. 30-015-34554
1. Type of Well: Oil Well ☐ Gas Well ☒ Other ☐		5. Indicate Type of Lease STATE ☐ FEE ☒
2. Name of Operator CHI Operating Inc.		6. State Oil & Gas Lease No.
3. Address of Operator P.O. Box 1799, Midland, TX 79702		7. Lease Name or Unit Agreement Name WC 4
4. Well Location Unit Letter 4 Lot 1 1100 feet from the North line and 990 feet from the East line Section 4 Township 22-C Range 26-E NMPM Eddy County		8. Well Number 4
11. Elevation (Show whether DR, RKB, RT, GR, etc.) 3216' GR		9. OGRID Number 004378
		10. Pool name or Wildcat Happy Valley Morrow

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐ MULTIPLE COMPL ☐
DOWNHOLE COMMINGLE ☐
CLOSED-LOOP SYSTEM ☐
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ P AND A ☒
CASING/CEMENT JOB ☐
OTHER: ☐

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

4/24/14----MIRU.
4/25/14----Blow down well pump 65 bbls brine ND well head NUBOP.
4/28/14----LD 200 jts 2%.
4/29/14----LD production string total 295 jts RU WL RIH 5 1/2 gauge ring stack out @ 10940. OCD ok'd to set CIBP @ 10940' dump bail 3 sxs class "H" cmt to cap TOC @ 10940' run work string in hole 200 jts SIW.
4/30/14----Tag @ 10895' LD tbg spot 25 sxs "H" cmt @ 10013' pull 30 sids WOC.
5/01/14----RIH Tag @ 10005' OCD ok'd to spot 25 sxs @ 10005' WOC & Tag @ 9710', circ hole w/ salt gel mud LD tbg @ 5876' LD tbg @ 5876' SIW.
5/02/14----Spot 25 sxs "C" cmt @ 5876'-5623' POH RIH w/ 5 1/2 pkr set @ 1840' load hole pressure test csg 400# ok. Run WL perf @ 2185' est rate pressure up tbg spot 25 sxs @ 2235' POH SIW.
5/05/14----RIH Tag @ 1975' RIH w/ 5 1/2 pkr @ 323' run WL perf @ 568' est rate 2BPM @ 100# sqz 75 sxs @ 568'-468' WOC.
5/06/14----RIH Tag @ 460' perf @ 100' est rate 2BPM @ 100#, circ 30 sxs cmt inside & out 100'-surface RDMO.

Spud Date:

Rig Release Date:

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE  TITLE P&A Tech DATE 5/12/14

Type or print name Greg Bryant E-mail address: pamc@chienergyinc.com PHONE: 432-563-3355

For State Use Only

APPROVED BY:  TITLE J. S. H. Spewer DATE 4/27/15

Conditions of Approval (if any):