						Form approved.	
Form 3160-5 (November 1983)		U TED STAT		SUBMET IN T	R! CATE*	Budget Bureau Expires August	31 1095
(Formerly 9-331)		ALT OF THE			TO DO THE	5. LEASE DESIGNATION	AND SERIAL NO.
ON COME PRESENTATION	BUREA	U OF LAND MAN	AGEMEN	10001	10 2.	LC 071066	
	AN NOT	CES AND RE	PORTS/	ON WELLS"	1///	6. IF INDIAM, ALLOTTE	OR TRIBE NAME
tesia MADo not use this f	orm for propos	als to drill or to deep	en or plug l	ack of Allerent res	orvoir.		
	USE "APPLICA	TION FOR PERMIT	-" for such p	roposals.V V O J			
1. KECEIVED DI			,	5 / * 19k	35	7. UNIT AGREEMENT NA	XE
WELL LAI WELL L	OTHER						
2. 4P 000	l l			$\mathcal{Z}_{i} = \mathcal{W}_{i,j}$	w 1	8. FARM OR LEASE NAI	Œ
The Petroleum	Corporati	lon of Delawa	re 🗸	3,0	··· /	Brushy 12 Fe	ederal
3. ADDE PAS OF DESATOR	1				46	9. WELL NO.	
ASTEPIAN PETICE CI	eek Blvd.	Suite 350	Dallas,	Texas 75219	-4419	1	
1. LOCATION OF WELL (Re See also space 17 below	10 PIBLD AND POOL, OR WILDCAT						
At surface Unit Letter "N"						N Brushy Draw Delaware	
560' FSL &	11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA						
	·· · · · · · · · · · · · · · · · · · ·					Sec. 12, T26	
14. PERMIT NO.		15. BLEVATIONS (Sho	w whether pP	, RT, GR, etc.)		12. COUNTY OR PARISH	18. STATE
API# 30-015-25	3416	3019.4' GR	•	3027.7' КВ		Eddy	NM
16.	Check Ap	propriate Box To	Indicate N	ature of Notice, F	lenort or O	ther Data	
wa.	TICE OF INTENT			1	•		
Nu	TICE OF INTERI	10 10 .			ausasqu:	ENT REPORT OF:	
TEST WATER SHUT-OFF	P	CLL OR ALTER CASING		WATER SHUT-O		EXPAIRING W	BLL.
FRACTURE TREAT	и	ULTIPLE COMPLETE		FRACTURE TREA		ALTERING CA	SING
SHOOT OR ACIDIZE	A	BANDON*		SHOOTING OR A	CIDIZING X	ABANDONMEN	T*
REPAIR WELL	cı	HANGE PLANS				nt production o	
(Other)				(Norm: F	leport results : on or Recomple	of multiple completion of tion Report and Log for	on Well m.}
250 sx Trinity w/450 sx class burton. Release 10/25/85 Presected & float cook each time.  Ran cement Bon Canyon w/ 4" of	Light. C. Test used rig 6 sure test collar & s PBTD 6 54 d Log, Ga sg. gun:	t plug to 175 Tested plug ed plug to 1 3:00 PM 10/ ed 5-1/2" ca thoe. Pressu 178' KB.  Amma Ray Log, from 5302'	0 psi. to 1750 700 psi 19/85. sing to re teste and CCI to 5328	Cemented thr psi. Cement @ 8:00 AM CD 3000 psi; he ed casing to the from 5465' with 20 holds.	u bottom ed thru t T 10/18/8  ld ok. I 3000 psi: to 3000'.	5488' KB. Cem DV tool @ 4807 cop DV tool @ 3 35. Cemented b Drilled thru ea each stage. Perforated C	S590' KB by Halli- ach DV Held Cherry
Fraced Cherry # 12/20 sand.  18. I hereby certify has the SIGNED  (This space for Federal	e toregoing is	rue and correct				00 # 20/40 sand	
AAPPROVED BY		<b>- -</b>	TLE			DATE	
COMDITIONS OF APPI	IOVALL LI AN	Y:				- VAIN	
LAUT D							
Nous	_						
NOV - 4 198	5	*See In	structions	on Reverse Side			

\*See Instructions on Reverse Side