

Submit 3 Copies To Appropriate District
Office
District I
1625 N. French Dr., Hobbs, NM 87240
District II
1301 W. Grand Ave., Artesia, NM 88210
District III
1000 Rio Brazos Rd., Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy, Minerals and Natural Resources

Form C-103
Revised May 08, 2003

OIL CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87505

| |
|---|
| WELL API NO. 30-015-33055 |
| 5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/> |
| 6. State Oil & Gas Lease No. 33039 |
| 7. Lease Name or Unit Agreement Name: State 1624 |
| 8. Well Number 291 |
| 9. OGRID Number 218885 |
| 10. Pool name or Wildcat Cottonwood Creek; Wolfcamp |

| | |
|--|--|
| SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.) | |
| 1. Type of Well: Oil Well <input type="checkbox"/> Gas Well <input type="checkbox"/> Other <input type="checkbox"/> | RECEIVED NOV 02 2005 OIL CONSERVATION DIVISION |
| 2. Name of Operator LCX ENERGY, LLC | |
| 3. Address of Operator 110 N. Marienfeld, Ste. 200, Midland, TX 79701 | |
| 4. Well Location Unit Letter <u>C</u> : <u>660</u> feet from the <u>North</u> line and <u>1980</u> feet from the <u>West</u> line Section <u>29</u> Township <u>16S</u> Range <u>24E</u> NMPM <u>Eddy</u> County | |
| 11. Elevation (Show whether DR, RKB, RT, GR, etc.) | |

12. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

- PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☒ MULTIPLE COMPLETION ☐

OTHER: Fracture treat well ☒

SUBSEQUENT REPORT OF:

- REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐
CASING TEST AND CEMENT JOB ☐

OTHER: ☐

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

1. TIH w/2 7/8" drill pipe and spear, spear liner hanger, release and POOH w/Liner hanger and 4 1/2" slotted liner.
2. RIH and clean out horizontal hole to 7305'. POOH.
3. Run 4 1/2" guide shoe, 1 jt. 4 1/2" 11.6# casing, float collar, 3000' - 4 1/2" 11.6# casing. Baker Liner Hanger. Set liner at 7305'.
4. Cement 4 1/2" liner w/425 sx cement.
5. Fracture treat well w/19000 bbls gelled water and 160,000# 100 mesh, 160,000# 20/40 mesh sand in 4 stages.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Sharon Hindman TITLE Regulatory Agent DATE 10/31/2005

Type or print name Sharon Hindman

Telephone No. 432-687-1575

(This space for State use)

APPROVED BY FOR RECORDS ONLY TITLE DATE NOV 03 2005
Conditions of approval, if any: