Submit 3 Copies To Appropriate District	State of New N	Mexico	Form C-103
Office District I	Energy, Minerals and Natural Resources		May 27, 2004
1625 N. French Dr., Hobbs, NM 88240		WELL API NO.	
District II OIL CONCEDIA TION DIVICION		30-015-24487	
Jol W. Grand Avc., Artesia, NW 88210		5. Indicate Type of Lease	
District III 1220 South St. Francis Dr. 1000 Rio Brazos Rd., Aztec, NM 87410		STATE ⊠ FEE □	
District IV Santa Fe, NM 87505		6. State Oil & Gas Lease No.	
1220 S. St. Francis Dr., Santa Fe, NM			17612
87505			
SUNDRY NOTICES AND REPORTS ON WELLS		7. Lease Name or Unit Agreement Name	
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A		Avalon (Delaware) Unit	
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)			
	s Well 🔲 Other		8. Well Number 259
	is well [] Ouler	DEOCIVED	9. OGRID Number
2. Name of Operator		RECEIVED	
Exxon Mobil Corporation		MAY A 1 200F	007673 10. Pool name or Wildcat
3. Address of Operator		NOV 2 1 2005	l l
P.O. Box 4358, CORP-MI-P056, House	ston, 1X //210-4358	OCU-MITESIA	Avalon; Delaware 3715
4. Well Location			
Unit Letter N:_	330 feet from the south	line and 198	0 feet from the west line
	wnship 20S Range		4PM County Eddy
	1. Elevation (Show whether L	OR, RKB, RT, GR, etc.)	
	3264' GR		
Pit or Below-grade Tank Application or C	losure 🔝		
Pit typeDepth to Groundwater	Distance from nearest fres	h water well Dist	ance from nearest surface water
Pit Liner Thickness: mil	Below-Grade Tank: Volume	bbls: Co	nstruction Material
12. Check App	propriate Box to Indicate	Nature of Notice,	Report or Other Data
NOTICE OF DIT		1 01104	SECUENT DEDOOT OF
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:			
	PLUG AND ABANDON	REMEDIAL WORK	
PERFORM REMEDIAL WORK 🗌 🛚 F			
PERFORM REMEDIAL WORK F	PLUG AND ABANDON 🔲	REMEDIAL WORK	
PERFORM REMEDIAL WORK F	PLUG AND ABANDON CHANGE PLANS	REMEDIAL WORK	
PERFORM REMEDIAL WORK	PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPL	REMEDIAL WORK COMMENCE DRII CASING/CEMENT OTHER: Chemi	ALTERING CASING LLING OPNS. P AND A JOB cal treatment
PERFORM REMEDIAL WORK	PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPL	REMEDIAL WORK COMMENCE DRII CASING/CEMENT OTHER: Chemi	ALTERING CASING LLING OPNS. P AND A JOB
PERFORM REMEDIAL WORK FITEMPORARILY ABANDON FOR STREET OF STREET	PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPL Code operations. (Clearly state a	REMEDIAL WORK COMMENCE DRII CASING/CEMENT OTHER: Chemi Ill pertinent details, and	ALTERING CASING LLING OPNS. P AND A JOB cal treatment
PERFORM REMEDIAL WORK FITEMPORARILY ABANDON FOR STREET OF STREET	PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPL Code operations. (Clearly state a	REMEDIAL WORK COMMENCE DRII CASING/CEMENT OTHER: Chemi Ill pertinent details, and	ALTERING CASING LLING OPNS. P AND A JOB cal treatment give pertinent dates, including estimated date
PERFORM REMEDIAL WORK FITEMPORARILY ABANDON FOR STANDARD FOR STANDARD	PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPL Code operations. (Clearly state a	REMEDIAL WORK COMMENCE DRII CASING/CEMENT OTHER: Chemi Ill pertinent details, and	ALTERING CASING LLING OPNS. P AND A JOB cal treatment give pertinent dates, including estimated date
PERFORM REMEDIAL WORK FITEMPORARILY ABANDON FOR STANDARD FOR STANDARD	PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPL Ed operations. (Clearly state a). SEE RULE 1103. For Mul	REMEDIAL WORK COMMENCE DRII CASING/CEMENT OTHER: Chemi Ill pertinent details, and tiple Completions: Att	ALTERING CASING LLING OPNS. P AND A JOB cal treatment give pertinent dates, including estimated date ach wellbore diagram of proposed completion
PERFORM REMEDIAL WORK FITEMPORARILY ABANDON FOR TEMPORARILY ABANDON	PLUG AND ABANDON CHANGE PLANS C	REMEDIAL WORK COMMENCE DRII CASING/CEMENT OTHER: Chemi all pertinent details, and tiple Completions: Att	ALTERING CASING LLING OPNS. P AND A Cal treatment I give pertinent dates, including estimated date ach wellbore diagram of proposed completion ut down, isip vacuum si well 1000 gals
PERFORM REMEDIAL WORK FITEMPORARILY ABANDON FOR TEMPORARILY ABANDON	PLUG AND ABANDON CHANGE PLANS C	REMEDIAL WORK COMMENCE DRII CASING/CEMENT OTHER: Chemi all pertinent details, and tiple Completions: Att	ALTERING CASING LLING OPNS. P AND A JOB cal treatment give pertinent dates, including estimated date ach wellbore diagram of proposed completion
PERFORM REMEDIAL WORK FITEMPORARILY ABANDON FOR TEMPORARILY ABANDON	PLUG AND ABANDON CHANGE PLANS C	REMEDIAL WORK COMMENCE DRII CASING/CEMENT OTHER: Chemi all pertinent details, and tiple Completions: Att	ALTERING CASING LLING OPNS. P AND A Cal treatment I give pertinent dates, including estimated date ach wellbore diagram of proposed completion ut down, isip vacuum si well 1000 gals
PERFORM REMEDIAL WORK FITEMPORARILY ABANDON FOR TEMPORARILY ABANDON	PLUG AND ABANDON CHANGE PLANS C	REMEDIAL WORK COMMENCE DRII CASING/CEMENT OTHER: Chemi all pertinent details, and tiple Completions: Att	ALTERING CASING LLING OPNS. P AND A Cal treatment I give pertinent dates, including estimated date ach wellbore diagram of proposed completion ut down, isip vacuum si well 1000 gals
PERFORM REMEDIAL WORK FITEMPORARILY ABANDON FOR TEMPORARILY ABANDON	PLUG AND ABANDON CHANGE PLANS C	REMEDIAL WORK COMMENCE DRII CASING/CEMENT OTHER: Chemi all pertinent details, and tiple Completions: Att	ALTERING CASING LLING OPNS. P AND A Cal treatment I give pertinent dates, including estimated date ach wellbore diagram of proposed completion ut down, isip vacuum si well 1000 gals
PERFORM REMEDIAL WORK FITEMPORARILY ABANDON FOR TEMPORARILY ABANDON	PLUG AND ABANDON CHANGE PLANS C	REMEDIAL WORK COMMENCE DRII CASING/CEMENT OTHER: Chemi all pertinent details, and tiple Completions: Att	ALTERING CASING LLING OPNS. P AND A Cal treatment I give pertinent dates, including estimated date ach wellbore diagram of proposed completion ut down, isip vacuum si well 1000 gals
PERFORM REMEDIAL WORK FITEMPORARILY ABANDON FOR TEMPORARILY ABANDON	PLUG AND ABANDON CHANGE PLANS C	REMEDIAL WORK COMMENCE DRII CASING/CEMENT OTHER: Chemi all pertinent details, and tiple Completions: Att	ALTERING CASING LLING OPNS. P AND A Cal treatment I give pertinent dates, including estimated date ach wellbore diagram of proposed completion ut down, isip vacuum si well 1000 gals
PERFORM REMEDIAL WORK FITEMPORARILY ABANDON FOR TEMPORARILY ABANDON	PLUG AND ABANDON CHANGE PLANS C	REMEDIAL WORK COMMENCE DRII CASING/CEMENT OTHER: Chemi all pertinent details, and tiple Completions: Att	ALTERING CASING LLING OPNS. P AND A Cal treatment I give pertinent dates, including estimated date ach wellbore diagram of proposed completion ut down, isip vacuum si well 1000 gals
PERFORM REMEDIAL WORK FITEMPORARILY ABANDON FOR TEMPORARILY ABANDON	PLUG AND ABANDON CHANGE PLANS C	REMEDIAL WORK COMMENCE DRII CASING/CEMENT OTHER: Chemi all pertinent details, and tiple Completions: Att	ALTERING CASING LLING OPNS. P AND A Cal treatment I give pertinent dates, including estimated date ach wellbore diagram of proposed completion ut down, isip vacuum si well 1000 gals
PERFORM REMEDIAL WORK FITEMPORARILY ABANDON FOR TEMPORARILY ABANDON	PLUG AND ABANDON CHANGE PLANS C	REMEDIAL WORK COMMENCE DRII CASING/CEMENT OTHER: Chemi all pertinent details, and tiple Completions: Att	ALTERING CASING LLING OPNS. P AND A Cal treatment I give pertinent dates, including estimated date ach wellbore diagram of proposed completion ut down, isip vacuum si well 1000 gals
PERFORM REMEDIAL WORK FITEMPORARILY ABANDON FOR TEMPORARILY ABANDON	PLUG AND ABANDON CHANGE PLANS C	REMEDIAL WORK COMMENCE DRII CASING/CEMENT OTHER: Chemi all pertinent details, and tiple Completions: Att	ALTERING CASING LLING OPNS. P AND A Cal treatment I give pertinent dates, including estimated date ach wellbore diagram of proposed completion ut down, isip vacuum si well 1000 gals
PERFORM REMEDIAL WORK FEMPORARILY ABANDON COPULL OR ALTER CASING MOTHER: 13. Describe proposed or complete of starting any proposed work or recompletion. 11-04-05 Arrive at loc, rig up, start 12% bbls Nefedxbx max press availables	PLUG AND ABANDON CHANGE PLANS CHANGE PLANS CHANGE PLANS CHANGE PLANS CHANGE PLANS CHANGE PLANS (Clearly state a). SEE RULE 1103. For Mult acid via annulus. Sart pwg injection rate 2.0@ 15 m	REMEDIAL WORK COMMENCE DRII CASING/CEMENT OTHER: Chemi all pertinent details, and tiple Completions: Att flush, all flush in, sh in press total load ac	ALTERING CASING LLING OPNS. P AND A SIDE CAIL TREATMENT NOT A CONTROL OF AND A SIDE CAIL TREATMENT NOT AND A CONTROL OF AND A PAND A SIDE CAIL TREATMENT NOT AND A CONTROL OF A CONTROL
PERFORM REMEDIAL WORK	PLUG AND ABANDON CHANGE PLANS (Clearly state at a cid operations. (Clearly state at a cid via annulus. Sart pwg injection rate 2.0@ 15 m cove is true and complete to the	REMEDIAL WORK COMMENCE DRII CASING/CEMENT OTHER: Chemi all pertinent details, and tiple Completions: Att flush, all flush in, sh in press total load ac	ALTERING CASING LLING OPNS. P AND A SIDE CAIL TREATMENT P AND A SIDE CAIL TREATMENT SI
PERFORM REMEDIAL WORK	PLUG AND ABANDON CHANGE PLANS (Clearly state at a cid operations. (Clearly state at a cid operations.) (Clearl	REMEDIAL WORK COMMENCE DRIF CASING/CEMENT OTHER: Chemi all pertinent details, and tiple Completions: Att flush, all flush in, sh in press total load act e best of my knowledge as a general permit	ALTERING CASING LLING OPNS. P AND A Goal treatment I give pertinent dates, including estimated date each wellbore diagram of proposed completion at down, isip vacuum si well 1000 gals and 24 bbls oil water 56 bbls total load 80 e and belief. I further certify that any pit or belower an (attached) alternative OCD-approved plan .
PERFORM REMEDIAL WORK	PLUG AND ABANDON CHANGE PLANS (Clearly state at a cid operations. (Clearly state at a cid operations.) (Clearl	REMEDIAL WORK COMMENCE DRIF CASING/CEMENT OTHER: Chemi all pertinent details, and tiple Completions: Att flush, all flush in, sh in press total load act e best of my knowledge as a general permit	ALTERING CASING LLING OPNS. P AND A Goal treatment I give pertinent dates, including estimated date each wellbore diagram of proposed completion at down, isip vacuum si well 1000 gals and 24 bbls oil water 56 bbls total load 80 e and belief. I further certify that any pit or belower an (attached) alternative OCD-approved plan .
PERFORM REMEDIAL WORK	PLUG AND ABANDON CHANGE PLANS (Clearly state at a cid operations. (Clearly state at a cid operations.) (Clearl	REMEDIAL WORK COMMENCE DRIF CASING/CEMENT OTHER: Chemi all pertinent details, and tiple Completions: Att flush, all flush in, sh in press total load act e best of my knowledge as a general permit	ALTERING CASING LLING OPNS. P AND A Goal treatment I give pertinent dates, including estimated date each wellbore diagram of proposed completion at down, isip vacuum si well 1000 gals and 24 bbls oil water 56 bbls total load 80 e and belief. I further certify that any pit or belower an (attached) alternative OCD-approved plan .
PERFORM REMEDIAL WORK	CHANGE PLANS CHANGE PLANS CHANGE PLANS MULTIPLE COMPL ed operations. (Clearly state a). SEE RULE 1103. For Multiple and via annulus. Sart pwg injection rate 2.0@ 15 means according to NMOCD guideling. TITLE	REMEDIAL WORK COMMENCE DRII CASING/CEMENT OTHER: Chemi Ill pertinent details, and tiple Completions: Att flush, all flush in, sh in press total load act be best of my knowledges c best of my knowledges c best of my knowledges Staff Office Assistant	ALTERING CASING LLING OPNS. PAND A Goal treatment I give pertinent dates, including estimated date each wellbore diagram of proposed completion at down, isip vacuum si well 1000 gals and 24 bbls oil water 56 bbls total load 80 E and belief. I further certify that any pit or belower an (attached) alternative OCD-approved plan. DATE_11/14/2005_
PERFORM REMEDIAL WORK	PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPL CHANGE PLANS MULTIPLE COMPL CHANGE PLANS. (Clearly state at a cid operations. (Clearly state at a cid via annulus. Sart pwg injection rate 2.0@ 15 m cove is true and complete to the sed according to NMOCD guideling. TITLE E-mail address: tiffany.	REMEDIAL WORK COMMENCE DRII CASING/CEMENT OTHER: Chemi Ill pertinent details, and tiple Completions: Att flush, all flush in, sh in press total load act be best of my knowledges c best of my knowledges c best of my knowledges Staff Office Assistant	ALTERING CASING CALING OPNS. P AND A SIDE CAILING OPNS. P AND A SIDE CAILIN
PERFORM REMEDIAL WORK	CHANGE PLANS CHANGE PLANS CHANGE PLANS MULTIPLE COMPL ed operations. (Clearly state a). SEE RULE 1103. For Multiple and via annulus. Sart pwg injection rate 2.0@ 15 means according to NMOCD guideling. TITLE	REMEDIAL WORK COMMENCE DRII CASING/CEMENT OTHER: Chemi Ill pertinent details, and tiple Completions: Att flush, all flush in, sh in press total load act be best of my knowledges c best of my knowledges c best of my knowledges Staff Office Assistant	ALTERING CASING LLING OPNS. PAND A Gal treatment I give pertinent dates, including estimated date each wellbore diagram of proposed completion at down, isip vacuum si well 1000 gals and 24 bbls oil water 56 bbls total load 80 eand belief. I further certify that any pit or belower an (attached) alternative OCD-approved plan . DATE_11/14/2005_ il.com Telephone No. 281-654-1936
PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING MOTHER: 13. Describe proposed or complete of starting any proposed work or recompletion. 11-04-05 Arrive at loc, rig up, start 12% bbls Nefedxbx max press availables I hereby certify that the information aborder tank has been/will be constructed or closed starting any proposed work or recompletion. I hereby certify that the information aborder tank has been/will be constructed or closed starting any proposed work or recompletion. I hereby certify that the information aborder tank has been/will be constructed or closed starting any proposed work or recompletion. Type or print name Tiffany Stebbins For State Use Only Acception	CHANGE PLANS CHANGE PLANS CHANGE PLANS MULTIPLE COMPL ded operations. (Clearly state a). SEE RULE 1103. For Multiple to the complete to the sed according to NMOCD guideline. E-mail address: tiffany.	REMEDIAL WORK COMMENCE DRII CASING/CEMENT OTHER: Chemi Ill pertinent details, and tiple Completions: Att flush, all flush in, sh in press total load act e best of my knowledge es	ALTERING CASING LLING OPNS. PAND A Gal treatment I give pertinent dates, including estimated date each wellbore diagram of proposed completion at down, isip vacuum si well 1000 gals and 24 bbls oil water 56 bbls total load 80 eand belief. I further certify that any pit or belower an (attached) alternative OCD-approved plan . DATE_11/14/2005_ il.com Telephone No. 281-654-1936
PERFORM REMEDIAL WORK TEMPORARILY ABANDON OPULL OR ALTER CASING OTHER: 13. Describe proposed or complete of starting any proposed work or recompletion. 11-04-05 Arrive at loc, rig up, start 12% bbls Nefedxbx max press availables I hereby certify that the information aborded tank has been/will be constructed or closs SIGNATURE Jeffany Stebbins Type or print name Tiffany Stebbins For State Use Only Accept	PLUG AND ABANDON CHANGE PLANS MULTIPLE COMPL CHANGE PLANS MULTIPLE COMPL CHANGE PLANS COMPL CHANGE PLANS (Clearly state at a cid via annulus. Sart pwg injection rate 2.0@ 15 m cove is true and complete to the sed according to NMOCD guideling. TITLE E-mail address: tiffany.	REMEDIAL WORK COMMENCE DRII CASING/CEMENT OTHER: Chemi Ill pertinent details, and tiple Completions: Att flush, all flush in, sh in press total load act e best of my knowledge es	ALTERING CASING LLING OPNS. PAND A Gal treatment I give pertinent dates, including estimated date each wellbore diagram of proposed completion but down, isip vacuum si well 1000 gals and 24 bbls oil water 56 bbls total load 80 belief. I further certify that any pit or belower an (attached) alternative OCD-approved plan DATE_11/14/2005_ DATE_11/14/2005_ iil.com Telephone No. 281-654-1936