Form 3160-5 (April 2004)

OCD-ARTESIA UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

FORM APPROVED OM B No. 1004-0137 Expires: March 31, 2007

SUNDRY NOTICES AND REPORTS ON WELLS Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals.				5. Lease Serial No. NM-58024 6. If Indian, Allottee or Tribe Name		
						abandoned v
SUBMIT IN TRIPLICATE- Other instructions on reverse side. 1. Type of Well RECEIVED				7. If Unit or CA/Agreement, Name and/or No.		
Oil Well Gas Well Other			JAN 2 7 2006	8. Well Name and No. DD Federal 25 No. 1		
2. Name of Operator Chaparral F	Energy, LLC	₩	NU-MITESIA	9. API Well No		
a Address 701 Cedar Lake Blvd., Oklaho	3b. Phone No. (ii	n. Phone No. (include area code) 405/478-8770		30-015-24905 10. Field and Pool, or Exploratory Area		
4. Location of Well (Footage, Sec., T., R., M., or Survey Description)				Dagger Draw Up. Penn N.		
Unit H, Sec. 25-19S-24E 1980' FNL & 660' FEL				11. County or Parish, State Eddy Co., NM		
12 OUTOV A	DDD ODDIATE DOV(CC) TO	INDICATE NA	TUDE OF NOTICE D	<u> </u>		
	PPROPRIATE BOX(ES) TO	INDICATE NA		EPORT, OR OT	HER DATA	
TYPE OF SUBMISSION	TYPE OF ACTION					
Notice of Intent	Acidize Alter Casing Casing Repair	Deepen Fracture Treat New Construct	Production (Standard Reclamation Recomplete	art/Resume)		
Subsequent Report	Change Plans	Plug and Aband			Oulci	
Final Abandonment Notice	Convert to Injection	Plug Back	Water Disposal			
Return well to production						
			•			
•		•				
I hereby certify that the foreg Name (Printed/Typed)	going is true and correct	1.				
		Title	Engineering Tech			
Signature Desci	Comisa	Date	01	/03/2006		
ACCEPTE	THIS SPACE FOR FI	EDERAL OR	STATE OFFICE	JSE		
proved by SGD.)	DAVID & GLASS		Title	Date		
nditions of approval, if any lateral tify that the applicant holds legal ich would entitle the applicant to		the subject lease	Accepted F	or Record		
es any false, fictitious or fraudule	43 U.S.C. Section 1212, make it a ci	rime for any person to any matter withir	Continuous	Production	on And Keeping	

(Instructions on page 2)

Well On Continuous Production!

Accepted for record - NMOCD