Form 3160-5 (August 1999)

its jurisdiction.

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

OCD-ARTESIA

FORM APROVED OMB NO. 1004-0135

EXPIRES: NOVEMBER 30, 2000

SUNDRY NOTICES AND REPORTS ON WELLS		5. Lease Serial No.	5. Lease Serial No.	
Do not use this form for proposals to drill or to re-enter an		NM-0544986		
abandoned well. Use Form 3160-3 (APD) for such proposals		6. If Indian, Allottee or Tribe Name		
SUBMIT IN TRIPLICATE RECFIVED 1a. Type of Well Gas Well Other		7. Unit or CA Agreen	NA nent Name and No.	
		Sim Si Grenigicon	NA	
FEB 0.8 7006		8 Well Name and No.		
2. Name of Operator DEVON ENERGY PRODUCTION COMPANY LB		TODD 25P FEDERAL 16		
DEVON ENERGY PRODUCTION COMPANY, LP	9. API Well No.			
3. Address and Telephone No.		30-015-28817		
20 North Broadway, Ste 1500, Oklahoma City, OK 73102 405-552-4615		10. Field and Pool, or Exploratory		
 Location of Well (Report location clearly and in accordance with Federal requirements)* 660 FSL 660 FEL P 25 T23S R31E 		INGLE WE 12. County or Parish	LLS (DELAWARE)	
000 F3L 000 FEL F 23 1233 R31E		1		
	EDDY	NM		
CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA TYPE OS SUBMISSION TYPE OF ACTION				
		n (Start/Resume)	Water Shut-Off	
✓ Notice of Intent		• •	Well Integrity	
Subsequent Report Casing Repair New Con	struction 🔲 Recomple	ete	Other	
Final Abandonment Notice		rily Abandon	 	
Convert to Injection Plug Back Water Disposal 13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work and approximate duration thereof. If the proposal				
deepen directionally or recomplete horizontally, give subsurface location and measured and true vertical depths of	all pertinent markers and zones. A	ttach the Bond under which t	he work will be performed or provide	
the Bond No. on file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirement, including reclamation, have been completed, and the operator has				
determined that the site is ready for final inspection)				
Note: Form C108, Application for Authorization to Inject, approved by Santa Fe on 1/24/06. Administrative Order SWD-1023. Form C103, Notice of Intent to convert to SWD was mailed to OCD-Artesia office on 1/30/06. 1. Perforate the Delaware Cherry Canyon at 5776' – 5920' for salt water disposal. 2. Acidize 5776' – 5920' with +/- 5000 gallons 7-1/2% NeFe acid. Swab back acid. Obtain static fluid level. 3. Frac 5776' – 5920' with +/- 120,000 lb proppant. 4. Run 5-1/2" IPC packer and 2-7/8", IPC tubing. Set packer +/- 5730'. 5. Load hole with packer fluid and perform MIT Test on casing. Chart results. 6. Wellhead injection pressure shall be limited to no more than 1155 psi. 7. Commence water injection. Note date of injection. NOTE: Notify OCD 24 Hrs in advance of performing MIT Test.				
Accepted for record - NMOCD Accepted for record - NMOCD 7. 14. Thereby certify that the foregoing is true and correct Signed Rame Mark Signed Rame Mark Title Ronnie Slack Title Engineering Technician Date 1/30/2006				
(This space for Federal or State Office use) Approved by (ORIG. SGD.) ALEXIS C. SWOBODA, Title	LEUM ENGINEE	a cco	0 6 2006	
Approved by Conditions of approval, if any:		Date FLD	0 0 2000	



