Submit 3 Copies To Appropriate District Office	State of New Mexico		Form C-103	
District I	Energy, Minerals and Natural Resources		Revised March 25, 1999	
1625 N. French Dr., Hobbs, NM 88240 District II			WELL API NO. 30-005-60697	
811 South First, Artesia, NM 88210	OIL CONSERVATION DIVISION		5. Indicate Type of	of Lease
<u>District III</u> 1000 Rio Brazos Rd., Aztec, NM 87410	1220 South St. Francis Dr.		STATE FEE X	
District IV	Santa Fe, NM 87505		6. State Oil & G	····
1220 S. St. Francis Dr., Santa Fe, NM 87505			o. blate on co	
SUNDRY NOTICES AND REPORTS ON WELLS			7. Lease Name or	Unit Agreement Name:
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A				
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)		Twin Lakes San A	andres Unit	
1. Type of Well:				
Oil Well Gas Well Other				
2. Name of Operator			8. Well No.	
Tipton Oil & Gas Acquisitions, Inc.			48	
3. Address of Operator		EB 2 1 2006	9. Pool name or V	
F.O. Dox 1254, Lovington, NVI 88200			Twin Lake, San A	ndres (Assoc)
4. Well Location OCU-NATEDIA				
Unit Letter M 570	feet from the <u>South</u> lin	ne and <u>330</u> fee	t from the <u>West</u>	line
Section 3:	Township 8S Ran	ge 29E	NMPM Chay	ves, County
多种类型 化原子化	10. Elevation (Show whether DI	R, RKB, RT, GR, etc	c.)	Land Arthur Strain
			1.4	
11. Check	Appropriate Box to Indicate Na	ature of Notice,	Report or Other	Data
NOTICE OF II	NTENTION TO:	SUB	SEQUENT RE	PORT OF:
PERFORM REMEDIAL WORK	☐ PLUG AND ABANDON ☐	REMEDIAL WOR	K 🗆	ALTERING CASING
TEMPORARILY ABANDON	CHANGE PLANS	COMMENCE DR	ILLING OPNS. 🗌	PLUG AND ABANDONMENT
PULL OR ALTER CASING	] MULTIPLE	CASING TEST A	ND 🗀	ABANDONWENT
	COMPLETION	CEMENT JOB		
OTHER:		OTHER: CONVE	RT TO PRODUCER	$\mathbf{x}$
12. Describe proposed or comple	eted operations. (Clearly state all per	rtinent details, and g	give pertinent dates,	including estimated date
of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion				
or recompilation.				
1. POOH with pkr. and pla	stic coated the			
2. RIH w/csg. scraper.	nio coulca tog.			
3. RIH with 2 3/8" tbg., pu	mp and rods.			
4. Set pumping unit.				
5. Hang on, space out.	15/07			
6. Convert to production 1 24-hr. test 4 BO and 10 l				
2 in test i bo and for	311			
I hereby certify that the information above is true and complete to the best of my knowledge and belief.				
SIGNATURE Sublice Mikely TITLE Agent, For Clay Tipton (Sec-Treas.), Principal DATE 2/16/06				
Type or print name Loc Clay Tipton Telephone No. 505-631-4121				
(This space for State use)		Gerry Guye		FEB <b>2 2</b> 2006
APPPROVED BY Den	y Juny	Compliance		
Conditions of approval, if any:	TITLE_	Onlibilation	- Ullian.	DATE
i any.	,			