Form 3160-5 (August 2007)

UNITED STATES DEPARTMENT OF THE INTERIOR **BUREAU OF LAND MANAGEMENT**

NMOCD Artesia

FORM APPROVED OMB NO. 1004-0135 Expires: July 31, 2010

5: Lease Serial No. NMNM29234

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to re-enter an abandoned well. Use form 3160-3 (APD) for such proposals.					6. If Indian, Allottee o	6. If Indian, Allottee or Tribe Name	
SUBMIT IN TRIPLICATE - Other instructions on reverse side.					7. If Unit or CA/Agree	ement, Name and/or No.	
1. Type of Well Oil Well Gas Well Other					8. Well Name and No. LOTOS 8 FEDER		
Name of Operator Contact: CINDY H MURILLO CHEVRON USA INCORPORATED E-Mail: CHERRERAMURILLO@CHEVRON.COM					9. API Well No. 30-015-32758-0	9. API Well No. 30-015-32758-00-S1	
3a. Address 15 SMITH ROAD MIDLAND, TX 79705	3b. Phone No. (include area code) Ph: 575-263-0431 Fx: 575-263-0445			10. Field and Pool, or SAND DUNES	10. Field and Pool, or Exploratory SAND DUNES		
4. Location of Well (Footage, Sec., T., R., M., or Survey Description)					11. County or Parish,	and State	
Sec 8 T24S R31E SENW 1980FNL 1980FWL					EDDY COUNTY	/, NM	
12. CHECK APPI	ROPRIATE BOX(ES) TO I	NDICATE	NATURE OF	NOTICE	, REPORT, OR OTHE	R DATA	
TYPE OF SUBMISSION	TYPE OF ACTION				N	,	
Notice of Intent	☐ Acidize	□ Deep	en	☐ Production (Start/Resume)		■ Water Shut-Off	
_	☐ Alter Casing	☐ Fracture Treat		☐ Reclamation		■ Well Integrity	
☐ Subsequent Report	☐ Casing Repair	■ New Construction		□ Recomplete		□ Other	
☐ Final Abandonment Notice	Chánge Plans		Plug and Abandon		porarily Abandon		
	☐ Convert to Injection	□ Plug Back		☐ Wat	er Disposal		
following completion of the involved testing has been completed. Final At determined that the site is ready for f CHEVRON USA INC IS REQUESTING. THE PROCEDURE IS AS FO 1. PULL OUT OF HOLE WITH 2. SET 5 1/2" CIBP AT 7800', 3. LOAD HOLE WITH INHIBIT 4. PRESSURE TEST CASING 5. SUBMIT A MIT CHART TO CHEVRON IS REQUESTING.	pandonment Notices shall be filed in all inspection.) UESTING TO TEMPORARY LLOWS: 1 RODS: PUMP AND TUBING CAP WITH 35' CEMENT. IFO FI UID	only after all r	SEE A	WELL. ATTA DITIC	CHED FOR ONS OF APPRIANT OIL ART	CONSERVATION ESIA DISTRICT EB 2 2 2016	
NMOCD QT 2/24/16							
14. I hereby certify that the foregoing is	true and correct. Electronic Submission #32- For CHEVRON US/ mitted to AFMSS for process	A INCORPO	RATED, sent to	the Carlsi	tion System) oad	RECEIVED	
Name (Printed/Typed) CINDY H		Title PERMI	TTING-S	PECIALIST/			
Signature (Electronic S	Submission)		Date 11/30/2	015	AV PROV <u>ZL</u>) / /	
	THIS SPACE FOR	FEDERA	L OR STATE	OFFICE	USEFR 1 2 2016	11 1/1	
Approved By Conditions of approval, if any, are attached		Title		NEAU UF LAIN JAMAN JA CARLSBAD V ZLD CIFIO	MENT WILL		
certify that the applicant holds legal or equ which would entitle the applicant to condu		Office	1/5				
Title 18 U.S.C. Section 1001 and Title 43 States any false, fictitious or fraudulent s	U.S.C. Section 1212, make it a cri- statements or representations as to	me for any per any matter wit	son knowingly and hin its jurisdiction.	wintuliy to	make to any department or a	agency of the United	

BUREAU OF LAND MANAGEMENT Cartsbad Field Office 620 East Greene Street Carlsbad, New Mexico 88220 575-234-5972

Approved for a period of 12 months ending 02/12/2017 subject to conditions of approval.

Temporary Abandonment of Wells on Federal Lands **Conditions of Approval**

A temporarily abandoned well is defined as a completion that is not capable of production in paying quantities but which may have value as a service well. Pursuant to 43 CFR 3162.3-4 (c), no well may be temporarily abandoned for more than 30 days without the prior approval of the authorized officer.

Temporary Abandonment (TA) status approval requires a successful mechanical or casing integrity test as follows:

- A Notice of Intent (NOI) Sundry Notice (Form 3160-5) requesting approval to run a mechanical integrity test (MIT) or casing integrity test (CIT).
- 2. A description of the temporary abandonment procedure.
 - a. A bridge plug or packer must be installed as close to 50 feet above any open perforations or open hole as possible. If a cement plug is used, the top of the cement must be verified by tagging. CIBP must be capped with minimum 25 sacks cement, placed with tubing, or 35 feet of cement if placed with bailer.
 - b. The wellbore must be filled with corrosion inhibited fluid and pressure tested to 500 psi. The casing shall be capable of holding this pressure for at least 30 minutes. Any leak-off will be evaluated.
 - c. All downhole production/injection equipment (tubing, rods, etc.) shall be removed from the casing if they are not isolated by a packer.
 - d. A bradenhead test must be conducted. If the test indicates a problem exists, a remedial plan and time frame for remediation shall be submitted within ninety (90) days of the test.
 - e. Contact the appropriate BLM office at least 24 hours prior to the scheduled Casing Integrity Test. For wells in Eddy County, 575-361-2822; Lea County 575-393-3612.
- 3. Provides justification why the well should be temporarily abandoned rather than permanently plugged and abandoned and an estimated date that the well will be returned to beneficial use or plugged and abandoned. 43 CFR 3162.3-4 (a) The operator shall promptly plug and abandon...wells in which oil or gas is not encountered in paying quantities...

Wells that successfully pass the casing integrity test may be approved for Temporary Abandonment (TA) status provided that the operator:

- 1. Submits a subsequent Sundry Notice (Form 3160-5) requesting TA approval with well bore diagram with all perforations and CIBP's and tops of cement on CIBP's.
- 2. Describes the temporary abandonment procedure.
- Attaches a clear copy or the original of the pressure test chart. 3.
- 4. Give justification to allow well to be place in TA status and plan for future use of well with time frame that well will be place back on line or plans to P&A well will be submitted.

If the well does not pass the casing integrity test, then the operator shall within 30 days submit to BLM for approval one of the following:

- 1. A procedure to repair the casing so that a TA approval can be granted.
- 2. A procedure to plug and abandon the well.

Lotos 8 Federal 803

- 1. Well is approved to be TA/SI for a period of 12 months or until 02/12/2017
- 2. This will be the last TA approval for this well.
- Must submit NOI to recomplete or NOI to P&A. Must be submitted by 02/12/2017
- COA's met at this time.