

District I - (575) 393-6161
1625 N. French Dr., Hobbs, NM 88240
District II - (575) 748-1283
811 S. First St., Artesia, NM 88210
District III - (505) 334-6178
1000 Rio Brazos Rd., Aztec, NM 87410
District IV - (505) 476-3460
1220 S. St. Francis Dr., Santa Fe, NM 87505

OIL CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87505

WELL API NO. 30-015-03560
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No. B-8876
7. Lease Name or Unit Agreement Name TURKEY TRACK SEC 3 UNIT
8. Well Number 016
9. OGRID Number 370922
10. Pool name or Wildcat 61020: Turkey Track 7 RVRS QU GB SA

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: Oil Well <input checked="" type="checkbox"/> Gas Well <input type="checkbox"/> Other <input type="checkbox"/>	
2. Name of Operator WS OIL AND GAS OPERATING, LLC	
3. Address of Operator PO BOX 5375, Midland, TX 79704	
4. Well Location Unit Letter P : 660 feet from the S line and 660 feet from the E line Section 3 Township 19S Range 29E NMPM County EDDY	
11. Elevation (Show whether DR, RKB, RT, GR, etc.)	

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	P AND A <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	MULTIPLE COMPL <input type="checkbox"/>	CASING/CEMENT JOB <input type="checkbox"/>	
DOWNHOLE COMMINGLE <input type="checkbox"/>			
OTHER: <input type="checkbox"/>		OTHER: RETURN TO PRODUCTION <input checked="" type="checkbox"/>	2-3-16

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

SEE ATTACHED

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Carie Stoker TITLE Regulatory Affairs Coordinator DATE: 4/14/2016

Type or print name Carie Stoker E-mail address: carie@stokeroilfield.com PHONE: 432.664.7659

APPROVED BY: Accepted for record TITLE NMOC DATE 4-21-16
Conditions of Approval (if any): NMOC

02/01/2016

MIRU. UNHANG WELL AND WORK TO UNSEAT PUMP. PUMP 10 FW DOWN ANNULUS AND FINALLY UNSEATED PUMP. POOH WITH PUMP AND RODS. ND WELLHEAD. PU ON TUBING. WELLHEAD AND 2' X 7" NIPPLE WAS PULLED OUT OF CASING COLLAR. COLLAR THREADS GOOD. THREADS ON 2' SUB WERE STRIPPED. SWISD DUE TO HIGH WIND.

02/02/16

TRIED TO SCREW 2.00' 7" CASING SUB INTO CASING COLLAR WITHOUT SUCCESS. STRIPPED 2.00' SECTION OVER 2-3/8" TUBING. RU WELDER AND GROUND THREADS OFF CASING SUB. STRIPPED BACK OVER TUBING AND SEATED CASING SUB INTO COLLAR. WELDED CASING TOGETHER. RD WELDER. NU BOP. POOH WITH 2-3/8" BADLY PITTED TUBING. PU 6-1/4" BIT, 7" CASING SCRAPER TO 1672'. TAGGED SOLID. POOH WITH BIT AND SCRAPER. RIH WITH 2-3/8" STANDARD SEATING NIPPLE ON 2-3/8" J55, EUE 8RD BLUE BAND TUBING. LANDED EOT @ 1661'. SWISDON.

02/03/2016

ND BOP. NU WELLHEAD. LAND TBG 1712'. PREP FOR RODS. PU PUMP AND RIH. SPACED OUT WELL AND HWO. LOADED TUBING WITH 4 BBLs. TEST PUMP TO 500 PSI. CLEANED LOCATION AND RDMO.

TUBING

KB	3.00'	3.00'
54 JTS 2-3/8" J55 EUE 8RD BLUE BAND TUBING	1708.64'	1711.64'
2-3/8" STANDARD SEATING NIPPLE	1.10'	1712.74'

RODS

1-1/4" X 11' POLISH ROD W/1-1/2" LINER	6.00'
2' - 6' PONY SUBS	16.00'
67 X 3/4" RODS	1675.00'
2" X 1-1/2" X 10' RWBC PUMP	10.00'