

State of New Mexico  
Energy, Minerals and Natural Resources Department

Susana Martinez  
Governor

David Martin  
Cabinet Secretary

Tony Delfin  
Deputy Cabinet Secretary

David Catanach, Director  
Oil Conservation Division



**\*Response Required - Deadline Enclosed\***

*Field Inspection Program*  
*"Preserving the Integrity of Our Environment"*

07-Jun-16

BOPCO, L.P.  
P. O. BOX 2760  
MIDLAND TX 79702

**LETTER OF VIOLATION - Inspection**

Dear Operator:

The following inspection(s) indicate that the well, equipment, location or operational status of the well(s) failed to meet standards of the New Mexico Oil Conservation Division as described in the detail section below. To comply with standards imposed by Rules and Regulations of the Division, corrective action must be taken immediately and the situation brought into compliance. The detail section indicates preliminary findings and/or probable nature of the violation. This determination is based on an inspection of your well or facility by an inspector employed by the Oil Conservation Division on the date(s) indicated.

Please notify the proper district office of the Division, in writing, of the date corrective actions are scheduled to be made so that arrangements can be made to reinspect the well and/or facility.

***INSPECTION DETAIL SECTION***

<b>POKER LAKE UNIT CVX JV PC No.004H</b>				<b>P-5-25S-30E</b>	<b>30-015-36998-00-00</b>	
<b>Inspection Date</b>	<b>Type Inspection</b>	<b>Inspector</b>	<b>Violation?</b>	<b>*Significant Non-Compliance?</b>	<b>Corrective Action Due By:</b>	<b>Inspection No.</b>
06/07/2016	Routine/Periodic	Gilbert Cordero	Yes	No	9/10/2016	iGC1615938142
<b>Comments on Inspection:</b> LOCATION SIGN IS INCORRECT- PLU PIERCE CANYON 5 STATE 001H						

<b>POKER LAKE CVX JV BS No.020H</b>				<b>P-2-25S-30E</b>	<b>30-015-40661-00-00</b>	
<b>Inspection Date</b>	<b>Type Inspection</b>	<b>Inspector</b>	<b>Violation?</b>	<b>*Significant Non-Compliance?</b>	<b>Corrective Action Due By:</b>	<b>Inspection No.</b>
06/07/2016	Routine/Periodic	Gilbert Cordero	Yes	No	9/10/2016	iGC1615935052
<b>Comments on Inspection:</b> LOCATION SIGN IS INCORRECT - PLU BIG SINKS STATE 002H						

<b>POKER LAKE UNIT CVX JV BS No.023H</b>				<b>N-2-25S-30E</b>	<b>30-015-41392-00-00</b>	
<b>Inspection Date</b>	<b>Type Inspection</b>	<b>Inspector</b>	<b>Violation?</b>	<b>*Significant Non-Compliance?</b>	<b>Corrective Action Due By:</b>	<b>Inspection No.</b>
06/07/2016	Routine/Periodic	Gilbert Cordero	Yes	No	9/10/2016	iGC1615933952
<b>Comments on Inspection:</b> LOCATION SIGN IS INCORRECT - PLU BIG SINKS STATE 003H						

Thank you for your prompt attention to this matter and your efforts in helping to protect our environment and the infrastructure of the oil and gas industry.

Sincerely,



COMPLIANCE OFFICER

Artesia OCD District Office

\* Significant Non-Compliance events are reported directly to the U.S. Environmental Protection Agency, Region VI, Dallas, Texas.