Form 3160-5 (August 2007)

# UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

FORM APPROVED OMB NO. 1004-0135 Expires: July 31, 2010

## SUNDRY NOTICES AND REPORTS ON WELLS Do not use this form for proposals to drill or to re-enter an abandoned well. Use form 3160-3 (APD) for such proposals.

Lease Serial No. NMLC049945B

6. If Indian, Allottee or Tribe Name

7. If Unit or CA/Agreement, Name and/or No. SUBMIT IN TRIPLICATE - Other instructions on reverse side. I. Type of Well Well Name and No.
 PARROT FEDERAL COM 2 Name of Operator DAVID STEWART Contact: API Well No. **OXY USA INC** 30-015-33345 E-Mail: david\_stewart@oxy.com 3b. Phone No. (include area code) Ph: 432-685-5717 10. Field and Pool, or Exploratory
LAKE MCMILLAN WOLFCAMP 3a. Address P.O. BOX 50250 MIDLAND, TX 79710 4. Location of Well (Footage, Sec., T., R., M., or Survey Description) 11. County or Parish, and State Sec 29 T19S R27E NESE 1600FSL 660FEL EDDY COUNTY, NM 32.628710 N Lat. 104.294620 W Lon

## 12. CHECK APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION	TYPE OF ACTION			
<ul> <li>□ Notice of Intent</li> <li>☑ Subsequent Report</li> <li>□ Final Abandonment Notice</li> </ul>	☐ Acidize ☐ Alter Casing ☐ Casing Repair ☐ Change Plans ☐ Convert to Injection	☐ Deepen ☐ Fracture Treat ☐ New Construction ☑ Plug and Abandon ☐ Plug Back	☐ Production (Start/Resume) ☐ Reclamation ☐ Recomplete ☐ Temporarily Abandon ☐ Water Disposal	☐ Water Shut-Off ☐ Well Integrity ☐ Other

13. Describe Proposed or Completed Operation (clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection.)

5/17/2016 MIRU PU, start to POOH w/ rods.

5/18/2016 Continue to POOH w/ rods & LD. Pump 10# brine for well control. MIRU BOP and accumulator.

5/19/2016 POOH w/ tbg & LD. SD for rig inspection.

5/20/2016 RIH w/ BHA, bit collars and tbg to 8326', tight @ top of liner @ 7983'. Drill & clean out to cmt/CIBP @ 8360', ru pwr swivel, and drill out to 8375', no circ/returns, PUH .

5/23/2016 RIH w/ BHA, continue to drill/clean out @ 8375-8433', continue in hole to 8975'. Drill cmt/CIBP @ 8975-9021', continue in hole to 9990', PUH to 8320'.

MM OIL CONSERVATION

ARTESIA DISTRICT

JUN 3 0 20.3

RECEIVED

d by the BLM Well Information System sent to the Carlsbad
Title SR. REGULATORY ADVISOR
Date 06/08/2016  L OR STATE OF Hing BLM approvals will he reviewed
Date 06/08/2016  L OR STATE OF Pending BLM approvals will pending BLM appro

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willhully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

### Additional data for EC transaction #341436 that would not fit on the form

### 32. Additional remarks, continued

مريو چين

5/24/2016 Contact BLM, rec approval to set CIBP @ 9993', POOH w/ BHA. RIH w/ CIBP & set @ 9993', POOH. Start to RIH w/ tbg.

5/25/2016 RIH w/ tbg & tag CIBP @ 9993', M&P 10# MLF, M&P 25sx CL H cmt, PUH, WOC. RIH & tag cmt @ 9689', PUH to 8835', M&P 40sx CI H cmt, PUH, WOC.

5/26/2016 RIH w/ tbg & tag cmt @ 8820', M&P 25sx CL H cmt, PUH, WOC. RIH & tag cmt @ 8835'. BLM approved setting CIBP @ 8330', POOH. RIH w/ CIBP & tag cmt stringer @ 8085', POOH, RIH w/ bar & tag up @ 8816', POOH.

5/27/2016 RIH w/ bit & clean out to 8400', POOH. RIH w/ CIBP & set @ 8330'. RIH w/ tbg & tag CIBP @ 8330', M&P 90sx CL H cmt, PUH, WOC.

5/31/2016 RIH w/ tbg & tag cmt @ 8000'. BLM approved setting CIBP @ 7983', POOH. RIH w/ CIBP & set @ 7983', POOH.

6/1/2016 RIH w/ tbg & tag CIBP @ 7983', circ hole w/ 10# MLF, M&P 70sx CI H cmt, PUH, WOC. RIH & tag cmt @ 7629', PUH to 5450', M&P 35sx CL C cmt, PUH, WOC.

6/2/2016 RIH w/ tbg & tag cmt @ 5235', POOH. RIH w/ pkr & set @ 2443', RIH & perf @ 2870', EIR @ 1.5bpm @ 500#, circ through 9-5/8" csg, M&P 75sx CL C cmt, PUH, WOC. RIH & tag cmt @ 2663', PUH & set pkr @ 815'. RIH & perf @ 1125', EIR @ 1.5bpm @ 300#, circ through 9-5/8" csg, M&P 75sx CL C cmt, PUH, WOC.

6/3/2016 RIH w/ tbg & tag cmt @ 990', POOH. RDPU, dig out cellar, to confirm surface csg valve, found csg clamp on surf csg w/ no surface valve & wellhead. Contact Jim Amos-BLM, will need to visually confirm cmt to surface after cutoff, if no cmt will need to 1". RUPU, rih w/ pkr & set @ 30', RIH & perf @ 480', EIR @ 2.5bpm @ 100#, circ through 9-5/8" csg, M&P 170sx CL C cmt, circ cmt to surf, visually confirmed. ND BOP & acumulator, RDPU