	·				
Office	o Appropriate District		tate of New M		Form C-103
<u>District I</u> - (575)		Energy, N	finerals and Nat	ural Resources	Revised July 18, 2013
	r., Hobbs, NM 88240	· · ·			WELL API NO. 30-015-35558
<u>District II</u> (575) 811 S. First St., A		OIL CO	NSERVATION	N DIVISION	
	<u>District III</u> – (505) 334-6178 1220 South St. Francis Dr.				5. Indicate Type of Lease
1000 Rio Brazos I	1000 Rio Brazos Rd., Aztec, NM 87410				STATE FEE
District IV - (505) 476-3460 is Dr., Santa Fe, NM	2	bailla FC, INIVI o	7505	6. State Oil & Gas Lease No.
87505	s DI., Santa Fe, INIVI				
	SUNDRY NOT	ICES AND REPO	ORTS ON WELLS	S	7. Lease Name or Unit Agreement Name
(DO NOT USE T	HIS FORM FOR PROPO	DSALS TO DRILL OF	R TO DEEPEN OR PL	UG BACK TO A	SER_ STATE -Black Lake SWD
DIFFERENT RES	SERVOIR. USE "APPL]	ICATION FOR PERM	4IT" (FORM C-101) F	OR SUCH /C///	8. Well Number 001
		8. Wen Number 001			
1. Type of W		A OCRID Number			
2. Name of O	owl SW	D Operating, L	LC '		9. OGRID Number
3. Address of					308339 10. Pool name or Wildcat Current:
5. Address of					
	8214 W	Salt Draw; Morrow (Gas) Pool ID 96819 (Pending: SWD; Delaware per SWD-1464)			
4. Well Locat	tion	······································			(Pending: SWD; Delaware per SWD-1404)
	-	- 660 feet f	from the Nort	th line and	1980 feet from the West line
		10011			
Section	on /		nship 25-S R	V	NMPM County Eddy
		11. Elevation (R, RKB, RT, GR, etc	
	and the second		<u>3067' G</u>	<u>.L.</u>	
	12. Check	Appropriate Bo	ox to Indicate N	Nature of Notice,	, Report or Other Data
			·	1	
	NOTICE OF I				SEQUENT REPORT OF:
	EMEDIAL WORK			REMEDIAL WOR	
TEMPORARIL					
PULL OR ALT	ER CASING	MULTIPLE CC	OMPL 🗌	CASING/CEMEN	ІТ ЈОВ
DOWNHOLE	Commingle 🗌	1			
CLOSED-LOC	OP SYSTEM	j -			Townsees Abandan and MIT Test
OTHER:			\boxtimes	OTHER:	Temporary Abandon and MIT Test
13. Descri	be proposed or com	pleted operations.	(Clearly state all	pertinent details, ar	nd give pertinent dates, including estimated da
					mpletions: Attach wellbore diagram of
	sed completion or re		NGED C	105 on N	AME CHANGE FROM
	ly safety meetings pr	lor to all operation	NS / = h in ations are a stim		KIMISCAL SIATE
			/ objective meetin	g; comigure weinea	d as appropriate; install BOP & P/U on tubing.
	t:52,000# - lower 16'		an ring to 10 EOE'	P. dissussed w/ OCD	ron loft 10 stands in hole for weekend
					rep – left 10 stands in hole for weekend.
					ershot, fish, wash – got down to TOL.
					dia. Cutter on work string; SDFN. s – 308'; mill, fish, wash to 12,250'.
			r and cut i bo @ 1	10,815 ; itvi u 9 joint	5 – 508 , mill, isil, wash to 12,250 .
	15 – Set CIBP @ 12,2		B@ 12 250' D/II-	and CIRC 9# MIE to A	1400'; P/U and spot 20 sx (100') 9122' to 9022'; I
	pot 25 sx 7200' to 71				
					asing pressure test. RD pulling unit.
	16 – Riff and tag cem 16 – Send TBG to yar				aong pressure test. Ito punng unit.
				500 m el / 20 m la vete	s witnessed by Richard Inge, OCD. Chart Attac
		\/ TOF TOMOFFOUL	n 8/16/16 Mit to 1	5UU NCI / 4U minute	
			r; 8/16/16 MIT to 1	500 psi / 30 minute	
10) 8/15/	16 – notify OCD of I				
			r; 8/16/16 MIT to Rig Release D		5 (MIT 8/16/16)
10) 8/15/	16 – notify OCD of I				
10) 8/15/ Spud Date:	/16 – notify OCD of I [Rig Up] 7/22/2	16	Rig Release D	Date: 8/07/16	5 (MIT 8/16/16)
10) 8/15/ Spud Date:	16 – notify OCD of I	16	Rig Release D	Date: 8/07/16	5 (MIT 8/16/16)
10) 8/15/ Spud Date:	/16 – notify OCD of I [Rig Up] 7/22/2	16	Rig Release D	Date: 8/07/16	5 (MIT 8/16/16)
10) 8/15/ Spud Date:	/16 – notify OCD of I [Rig Up] 7/22/2	16	Rig Release D	Date: 8/07/16	5 (MIT 8/16/16) ge and belief.
10) 8/15/ Spud Date:	/16 – notify OCD of I [Rig Up] 7/22/2	16	Rig Release D	Date: 8/07/16	5 (MIT 8/16/16)
10) 8/15/ Spud Date:	(16 - notify OCD of P) [Rig Up] 7/22/2 that the information	16	Rig Release D d complete to the l 	Date: 8/07/16	5 (MIT 8/16/16) ge and belief. DATE 8/27/2016
10) 8/15/ Spud Date:	(16 – notify OCD of 1 [Rig Up] 7/22/2 that the information That the information ame	16	Rig Release D d complete to the l 	Date: 8/07/16	5 (MIT 8/16/16) ge and belief. DATE 8/27/2016
10) 8/15/ Spud Date:	(16 – notify OCD of I [Rig Up] 7/22/2 that the information that the information ame Only	16 n above is true and	Rig Release E d complete to the l TITLEAg E-mail addrea	Date: 8/07/16 best of my knowled ent/consultant ss: ben@soscor	5 (MIT 8/16/16) ge and belief. DATE 8/27/2016 isulting.us PHONE: 903-488-9850
10) 8/15/ Spud Date:	(16 – notify OCD of I [Rig Up] 7/22/2 that the information that the information ame Only	16 n above is true and	Rig Release E d complete to the l TITLEAg E-mail addrea	Date: 8/07/16 best of my knowled ent/consultant ss: ben@soscor	5 (MIT 8/16/16) ge and belief. DATE 8/27/2016 isulting.us PHONE: 903-488-9850
10) 8/15/ Spud Date:	$\frac{16 - \text{notify OCD of I}}{[\text{Rig Up}] 7/22/2}$	16 n above is true and	Rig Release E d complete to the l TITLEAg E-mail addrea	Date: 8/07/16 best of my knowled ent/consultant ss: ben@soscor	5 (MIT 8/16/16) ge and belief. DATE 8/27/2016 isulting.us PHONE: 903-488-9850
10) 8/15/ Spud Date:	(16 – notify OCD of I [Rig Up] 7/22/2 that the information that the information ame Only	16 n above is true and	Rig Release E d complete to the l TITLEAg E-mail addrea	Date: 8/07/16 best of my knowled ent/consultant ss: ben@soscor	5 (MIT 8/16/16) ge and belief. DATE 8/27/2016 isulting.us PHONE: 903-488-9850
10) 8/15/ Spud Date:	$\frac{16 - \text{notify OCD of I}}{[\text{Rig Up}] 7/22/2}$	16 n above is true and whee NGE Temporory	Rig Release D d complete to the l 	Date: 8/07/16 best of my knowled ent/consultant ss: ben@soscor	5 (MIT 8/16/16) ge and belief. DATE 8/27/2016
10) 8/15/ Spud Date:	$\frac{16 - \text{notify OCD of I}}{[\text{Rig Up}] 7/22/2}$	16 n above is true and whee NGE Temporory	Rig Release E d complete to the l TITLEAg E-mail addrea	Date: 8/07/16 best of my knowled ent/consultant ss: ben@soscor	5 (MIT 8/16/16) ge and belief. DATE 8/27/2016 isulting.us PHONE: 903-488-9850

÷.,

4

