

BREITBURN OPERATING LP
Inspection Violation Corrections (Tony Morales, Inspector)

Tony Morales
 8-12-16

| Well Name and Number | API Number | Inspection Number | Corrective Action / Date |
|-----------------------------|--------------|-------------------|--|
| Artesia Unit No. 045 | 30-015-01775 | iTM1618742156 | Location sign corrected, debris removed 08/04/2016 |
| Artesia Unit No. 063 | 30-015-01781 | iTM1618735339 | Location sign correct and visible 08/04/2016 |
| Artesia Unit No. 043 | 30-015-01790 | iTM1618740651 | Location sign correct and visible 08/04/2016 |
| Artesia Unit No. 065 | 30-015-20273 | iTM1618738328 | Location sign correct and visible 08/04/2016 |
| Dunn B Federal No. 013 | 30-015-01809 | iTM1619042596 | Location sign correct and visible 08/08/2016 |
| Dunn B Federal No. 023 | 30-015-01815 | iTM1619035958 | Location sign correct and visible 08/25/2016 |
| Dunn B Federal No. 018 | 30-015-01825 | iTM1619043230 | Location sign correct and visible 08/08/2016 |
| Dunn B Federal No. 009 | 30-015-01835 | iTM1619048056 | Location sign correct and visible 08/08/2016 |
| Dunn B Federal No. 007 | 30-015-02683 | iTM1619047592 | Staining remediated/sign visible 08/25/2016 |
| Dunn B Federal No. 037 | 30-015-23225 | iTM16190236379 | Location sign correct and visible 08/08/2016 |
| State 14 C No. 001 | 30-015-01838 | iTM1619335165 | Location sign correct and visible 08/08/2016 |
| State 14 C No. 002 | 30-015-01839 | iTM1619335518 | Staining remediated /sign correct 08/25/2016 |
| State 14 C No. 010 | 30-015-02020 | iTM1619645859 | Location sign correct and visible 08/08/2016 |
| State 14 C No. 011 | 30-015-02019 | iTM1619646089 | Location sign correct and visible 08/08/2016 |
| State 14 A No. 001 | 30-015-01853 | iTM1619339499 | Location sign correct and visible 08/08/2016 |
| State 14 B No. 003 | 30-015-01855 | iTM1619338957 | Location sign correct and visible 08/08/2016 |
| State 14 B No.004 | 30-015-01856 | iTM1619339930 | Power restored/sign correct and visible 08/08/2016 |
| State 647AC 713 No.122 | 30-015-02017 | iTM1619644847 | Location sign correct and visible 08/25/2016 |
| State 647AC 713 No.124 | 30-015-01869 | iTM1619342285 | Staining remediated /sign visible 08/25/2016 |
| State 647AC 713 No.131 | 30-015-01870 | iTM1619347945 | Staining remediated / old tank removed 08/25/2016 |
| State 647AC 713 No.140 | 30-015-29079 | iTM1619340670 | Staining remediated / contamination removed 08/25/2016 |
| State E 1286 No. 126 | 30-015-01880 | iTM619349792 | Staining remediated /sign correct/power on 08/25/2016 |
| State E 1286 No. 128 | 30-015-01881 | iTM1619350199 | Staining remediated/sign correct 08/25/2016 |
| Humble State No. 002 | 30-015-01957 | iTM1619540836 | Location sign correct and visible 08/08/2016 |
| Humble State No. 003 | 30-015-01890 | iTM1619432024 | Location sign correct and visible 08/08/2016 |
| Western Yates State No. 002 | 30-015-01960 | iTM1619541772 | Location sign replaced/gallon drum removed 08/26/2016 |
| Vandeventer State No. 002 | 30-015-20103 | iTM1619539370 | Staining remediated/location sign visible 08/26/2016 |
| Mershon StateNo. 003 | 30-015-02005 | iTM1619637470 | Location sign correct and visible 08/08/2016 |
| Gulf State No. 001 | 30-015-02024 | iTM1619647591 | Location sign correct and visible 08/25/2016 |
| Gulf State No. 002 | 30-015-02025 | iTM1619647997 | Location sign correct and visible 08/25/2016 |

| | | | |
|--------------------------|--------------|----------------|--|
| State 643 AC 711 No. 27 | 30-015-02071 | iTM1620046235 | Location Sign correct and visible 08/25/2016 |
| State 647 AC 711 No. 043 | 30-015-02073 | iTM1620045323 | Location sign correct and visible 08/25/2016 |
| State 647 AC 711No. 070 | 30-015-02047 | iTM1619747475 | Staining remediated/sign visible 08/25/2016 |
| State 647 AC 711 No .074 | 30-015-02048 | iTM1619747699 | Staining remediated 08/25/2016 |
| State 647 AC 711 No. 086 | 30-015-02056 | iTM1620040861 | Location sign correct and visible 08/25/2016 |
| State 647 AC 711 No.089 | 30-015-02055 | iTM1620041221 | Location sign correct and visible 08/25/2016 |
| State 647 AC 711 No. 090 | 30-015-02168 | iTM16120328995 | Location sign correct and visible 08/25/2016 |
| State 647 AC 711 No. 092 | 30-015-02052 | iTM1620041627 | Location sign correct and visible 08/25/2016 |
| State 647 AC711 No. 093 | 30-015-02053 | iTM1619746928 | Location sign correct and visible 08/25/2016 |
| State 647 AC 711 No. 100 | 30-015-02054 | iTM1619746484 | Location sign correct and visible 08/25/2016 |
| State 647 AC 711 No. 101 | 30-015-02015 | iTM1619648871 | Location sign correct and visible 08/12/2016 |
| State 647 AC 711 No.129 | 30-015-02030 | iTM1619646529 | Location sign correct and visible 08/25/2016 |
| State 647 AC 711 No. 132 | 30-015-29078 | iTM1620040589 | Staining remediated/sign visible/power on 08/12/2016 |
| State 647 AC 711 No. 133 | 30-015-29075 | iTM1619747133 | Staining remediated/sign correct and visible 08/09/2016 |
| Rotary State No. 006 | 30-015-02112 | iTM1620142485 | Staining remediated/sign restored and visible 08/08/2016 |