


BREITBURN OPERATING LP
Inspection Violation Corrections (Gilbert Cordero, Inspector)

The location signs on the following wells are now correct and legible:

- ✓ Conoco 7 State No.015
- ✓ Conoco 7 State No.025
- ✓ Conoco 7 State No.024
- ✓ Conoco 7 State No.021
- ✓ Conoco 7 State No.020
- ✓ Conoco 7 State No.019
- ✓ Conoco 7 State No.018
- ✓ Conoco 7 State No.017
- ✓ Conoco 7 State No.016
- ✓ Conoco 7 State No.014
- ✓ Conoco 7 State No.012
- ✓ Conoco 7 State No.009
- ✓ Conoco 7 State No.004
- ✓ Conoco 7 State No.003



Forwarded E-mail