Form 3160-5 (August 2007)

### **UNITED STATES** DEPARTMENT OF THE INTERIOR **BUREAU OF LAND MANAGEMENT**

FORM APPROVED OMB NO. 1004-0135 Expires: July 31, 2010

Lease Serial No. NMLC029338A

Do not use th abandoned we	is form for proposals to II. Use form 3160-3 (APL	drill or to release an TESIA O) for such proposals.	3 1 2016	6. If Indian, Allottee	or Tribe Name
SUBMIT IN TRI	PLICATE - Other instruc	dinna an marramaa aida	CEIVED	7. If Unit or CA/Agre	cement, Namic and/or No.
i. Type of Well  Soil Well □ Gas Well □ Off	her	KI		8. Well Name and No MultipleSee Att	
Name of Operator     BURNETT OIL COMPANY IN		LESLIE GARVIS rnettoil.com		9. API Well No. MultipleSee A	Attached
3a. Address 801 CHERRY STREET UNIT FORT WORTH, TX 76102-68		3b. Phone No. (include area code Ph: 817-583-8730	)	10. Field and Pool, or MultipleSee A	
4. Location of Well (Footage, Sec., 7	., R., M., or Survey Description)			11. County or Parish,	and State
MultipleSee Attached				EDDY COUNT	Y, NM
.*			•		
12. CHECK APPI	ROPRIATE BOX(ES) TO	INDICATE NATURE OF	NOTICE, RI	EPORT, OR OTHE	R DATA
TYPE OF SUBMISSION	. ,	ТҮРЕ О	F ACTION		
Notice of Intent	☐ Acidize	☐ Deepen	☐ Production (Start/Resume)		☐ Water Shut-Off
	☐ Alter Casing	☐ Fracture Treat ☐ Reclamation		ation	■ Well Integrity
☐ Subsequent Report	☐ Casing Repair	■ New Construction	<ul> <li>☐ Recomplete</li> <li>☐ Temporarily Abandon</li> <li>☐ Water Disposal</li> </ul> ☑ Other Venting and/or ng		
☐ Final Abandonment Notice	☐ Change Plans	Plug and Abandon			-
	Convert to Injection	☐ Plug Back			<b>φ</b>
13. Describe Proposed or Completed Ope If the proposal is to deepen directions Attach the Bond under which the wo	ılly or recomplete horizontally, ş	give subsurface locations and measu	ired and true ve	rtical depths of all pertin	nent markers and zones.

following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection.)

Burnett is requesting permission to flare at the Gissler A 2 battery from October through December 2016. We will only be flaring as needed (i.e during DCP maintenance). All gas flared will be metered and reported as per BLM requirements.

We have previously received approval to install a flare at this location and an updated battery diagram showing the flare location is on file.

The Gissler A2 battery is located at: T17S, R30E, SECTION 14, UNIT J, NWSE 1650' FSL, 1650' FEL LEASE: NMLC-029338-A

SEE ATTACHED FOR CONDITIONS OF APPROVAL

	•				<b></b>		
14. I hereby certify that If	ne foregoing is true and correct.  Electronic Submission #350366 verific  For BURNETT OIL COMPAI  Committed to AFMSS for processing by DEBC	NY INC.	sent to the Carlsbad	$T^{*}$	1 1		7
Name(Printed/Typed)	LESLIE GARVIS	Title	REGULATORY C	OÓRDINA	tor //	\ //	
Signature	(Electronic Submission)	Date	09/08/2016	AP			
	THIS SPACE FOR FEDERA	AL OR	STATE OFFICE	JSE /			•
Approved By	7	Title		ØC	T 19 100	Da #	<u> </u>
Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.		Office		BURE /U	BAD FIEL OFF	ME 1	
	1 and Title 43 U.S.C. Section 1212, make it a crime for any p or fraudulent statements or representations as to any matter w			nake to any d	lepartment or ageno	y of the United	

### Additional data for EC transaction #350366 that would not fit on the form

#### Wells/Facilities, continued

	Agreement	Lease	Well/Fac Name, Number	API Number	Location
	NMLC029338A	NMLC029338A	GISSLER A 24	30-015-33498-00-\$1	Sec 14 T17S R30E NWSE 1650FSL 1776FEL
	NMLC029338A	NMLC029338A	GISSLER A 16	30-015-30275-00-S1	Sec 23 T17S R30E NENE 660FNL 680FEL
	NMLC029338A	NMLC029338A	GISSLER A 17	30-015-32447-00-C1	Sec 14 T17S R30E NESW 1800FSL 2310FWL
	NMLC029338A	NMLC029338A	GISSLER A 17	30-015-32447-00-C2	Sec 14 T17S R30E NESW 1800FSL 2310FWL
	NMLC029338A	NMLC029338A	GISSLER A 18	30-015-32448-00-C1	Sec 14 T17S R30E SESW 990FSL 1650FWL
	NMLC029338A	NMLC029338A	GISSLER A 18	30-015-32448-00-C2	Sec 14 T17S R30E SESW 990FSL 1650FWL
	NMLC029338A	.NMLC029338A	GISSLER A 19	30-015-32835-00-\$1	Sec 14 T17S R30E NWSE 2310FSL 2310FEL
	NMLC029338A	NMLC029338A	GISSLER A 20	30-015-32846-00-S1	Sec 14 T17S R30E NESE 2310FSL 990FEL
	NMLC029338A	NMLC029338A	GISSLER A 21	30-015-33243-00-S1	Sec 14 T17S R30E SWNE 2310FNL 1400FEL
	NMLC029338A	NMLC029338A	GISSLER A 22	30-015-33124-00-S1	Sec 14 T17S R30E NESW 2240FSL 1720FWL
	NMLC029338A	NMLC029338A	GISSLER A 23	30-015-33123-00-S1	Sec 14 T17S R30E SENE 2210FNL 360FEL
	NMLC029338A	NMLC029338A	GISSLER A 25	30-015-34021-00-S1	Sec 14 T17S R30E SESW 330FSL 2230FWL
	NMLC029338A	NMLC029338A	GISSLER A 26	30-015-34503-00-S1	Sec 14 T17S R30E NWSE 2384FSL 2199FEL
	NMLC029338A	NMLC029338A	GISSLER A 27H	30-015-34850-00-\$1	Sec 14 T17S R30E NESE 2310FSL 480FEL
	NMLC029338A	NMLC029338A	GISSLER A 28H	30-015-34909-00-S1	Sec 14 T17S R30E SWSE 990FSL 1980FEL
	NMLC029338A	NMLC029338A	GISSLER A 31	30-015-36035-00-S1	Sec 14 T17S R30E SWSE 790FSL 2380FEL
	NMLC029338A	NMLC029338A	GISSLER A 32	30-015-36036-00-S1	Sec 14 T17S R30E SWNE 1650FNL 2310FEL
	NMLC029338A	NMLC029338A	GISSLER A 33H	30-015-36654-00-S1	Sec 14 T17S R30E NESE 1800FSL 990FEL
	NMLC029338A	NMLC029338A	GISSLER A 37	30-015-38247-00-S1	Sec 14 T17S R30E SESW 990FSL 2275FWL
	NMLC029338A .	NMLC029338A	GISSLER A 40	30-015-39928-00-S1	Sec 14 T17S R30E NENW 2505FSL 1400FWL
	NMLC029338A	NMLC029338A	GISSLER A 41	30-015-39931-00-S1	Sec 14 T17S R30E SWSE 330FSL 1550FEL
	NMLC029338A	NMLC029338A	GISSLER A 43	30-015-41177-00-S1	Sec 23 T17S R30E NWNE 990FNL 1650FEL
	NMLC029338A	NMLC029338A	GISSLER A 45	30-015-41366-00-S1	Sec 14 T17S R30E SESW 330FSL 1650FWL
	MINICOZSSSOA	141012002939074	Oloocall A 45	30-013-41300 00 01	32,828029 N Lat, 103.945307 W Lon
	NMLC029338A	NMLC029338A	GISSLER A 46	30-015-41544-00-S1	Sec 23 T17S R30E NENE 330FNL 330FEL
	MMLCOZOGOM	THINECOZOGOA	GIOGEER A 40	30-0 18-4 1044 00 01	32.826211 N Lat. 103.934558 W Lon
	NMLC029338A	NMLC029338A	GISSLER A 47	30-015-41967-00-S1	Sec 23 T17S R30E NENE 1090FNL 330FEL
	MINICUZSSSOM	WINECOZ 93307	GIGGEEN A 47	30-013-41301-00-01	32.824130 N Lat. 103.934562 W Lon
	NMLC029338A	NMLC029338A	GISSLER A 48	30-015-42225-00-S1	Sec 14 T17S R30E NESW 1800FSL 1650FWL
	MINICOLOGICA	NINECOZSSOA	OIGGEER A 40	30-010-42220 00 01	32.832069 N Lat. 103.945305 W Lon
٠	NMLC029338A	NMLC029338A	GISSLER A 7	30-015-04152-00-S2	Sec 14 T17S R30E SWSE 330FSL 2310FEL
	NMLC029338A	NMLC029338A	GISSLER A 9	30-015-04153-00-S2	Sec 14 T17S R30E SENE 1980FNL 660FEL
	MINICOUZBOOM	THINLOUZ 3330M	GIOCELITAS	30-010-04133-00-02	CCC 14 1170 TOOL CEIVE 10001 TE 0001 EE
			•		

### 10. Field and Pool, continued

LOCO HILLS-GLORIETA-YESO

### 32. Additional remarks, continued

The following wells are associated wit Gissler A 7 30-015-04152 Gissler A 9 30-015-04153 Gissler A 16 30-015-30275 Gissler A 17 30-015-32447 Gissler A 18 30-015-32448 Gissler A 19 30-015-32846 Gissler A 20 30-015-32846 Gissler A 21 30-015-33243 Gissler A 22 30-015-33124 Gissler A 22 30-015-33124 Gissler A 22 30-015-33123 Gissler A 24 30-015-33498 Gissler A 25 30-015-34021 Gissler A 26 30-015-34503 Gissler A 27H 30-015-34850 Gissler A 28H 30-015-34909 Gissler A 31 30-015-36036 Gissler A 31 30-015-36036 Gissler A 37 30-015-38247 Gissler A 40 Grayburg 30-015-39928 Gissler A 43 30-015-41177 Gissler A 45 30-015-41177 Gissler A 46 30-015-41166 Gissler A 47 30-015-41967 Gissler A 48 30-015-42225 The following wells are associated with this battery:

#### Revisions to Operator-Submitted EC Data for Sundry Notice #350366

**Operator Submitted** 

**BLM Revised (AFMSS)** 

Sundry Type:

**FLARE** 

NOI

NMLC029338A

**FLARE** NOI

Lease:

NMLC029338A

Agreement:

Operator:

BURNETT OIL CO. INC. BURNETT PLAZA - SUITE 1500 801 CHERRY STREET - UNITF FORT WORTH, TX 76102

Ph: 817-583-8730

BURNETT OIL COMPANY INC

FORT WORTH, TX 76102-6881

Ph: 817.332.5108

Admin Contact:

LESLIE GARVIS REGULATORY COORDINATOR

E-Mail: Igarvis@burnettoil.com

Ph: 817-583-8730

LESUIE GARVIS

REGULATORY COORDINATOR

E-Mail: lgarvis@burnettoil.com .

Ph: 817-583-8730

Tech Contact:

LESLIE GARVIS REGULATORY COORDINATOR

E-Mail: lgarvis@burnettoil.com

Ph: 817-583-8730

LESLIE GARVIS REGULATORY COORDINATOR

E-Mail: Igarvis@burnettoil.com

Ph: 817-583-8730

Location:

State:

Field/Pool:

County: **EDDY** 

LOCO HILLS BLINBRY YESO

MN **EDDY** 

**GRAYBURG** 

GRAYBURG JACKSON-SR-Q-GRBG-SA LOCO HILLS-GLORIETA-YESO

Well/Facility:

GISSLER A 24

Sec 14 T17S R30E Mer NMP NWSE 1650FSL 1776FEL

Sec 14 T17S R30E NWSE 1650FSL 1776FEL

GISSLER A 16

GISSLER A 24

Sec 23 T17S R30E NENE 660FNL 680FEL GISSLER A 17

Sec 14 T17S R30E NESW 1800FSL 2310FWL

GISSLER A 17 Sec 14 T17S R30E NESW 1800FSL 2310FWL

GISSLER A 18

Sec 14 T17S R30E SESW 990FSL 1650FWL

GISSLER A 18
Sec 14 T17S R30E SESW 990FSL 1650FWL
GISSLER A 19
Sec 14 T17S R30E NWSE 2310FSL 2310FEL
GISSLER A 20
Sec 14 T17S R30E NESE 2310FSL 990FEL

GISSLER A 21

Sec 14 T17S R30E SWNE 2310FNL 1400FEL

GISSLER A 22 Sec 14 T17S R30E NESW 2240FSL 1720FWL

GISSLER A 23

Sec 14 T17S R30E SENE 2210FNL 360FEL GISSLER A 25 Sec 14 T17S R30E SESW 330FSL 2230FWL

GISSLER A 26 Sec 14 T17S R30E NWSE 2384FSL 2199FEL

GISSLER A 27H

Sec 14 T17S R30E NESE 2310FSL 480FEL

GISSLER A 28H Sec 14 T17S R30E SWSE 990FSL 1980FEL

GISSLER A 31 Sec 14 T17S R30E SWSE 790FSL 2380FEL GISSLER A 32

GISSLER A 32 Sec 14 T17S R30E SWNE 1650FNL 2310FEL GISSLER A 33H Sec 14 T17S R30E NESE 1800FSL 990FEL GISSLER A 37 Sec 14 T17S R30E SESW 990FSL 2275FWL GISSLER A 40 Sec 14 T17S R30E NENW 2505FSL 1400FWL GISSLER A 41

GISSLER A 41 Sec 14 T17S R30E SWSE 330FSL 1550FEL

GISSLER A 43

Sec 23 T17S R30E NWNE 990FNL 1650FEL

GISSLER A 45

Sec 14 T17S R30E SESW 330FSL 1650FWL

32.828029 N Lat, 103.945307 W Lon GISSLER A 46 Sec 23 T17S R30E NENE 330FNL 330FEL 32.826211 N Lat, 103.934558 W Lon GISSLER A 47 Sec 23 T17S R30E NENE 1090FNL 330FEL 32.824130 N Lat, 103.934562 W Lon GISSLER A 48 Sec 14 T17S R30E NESW 1800FSL 1650FWL 32.832069 N Lat, 103.945305 W Lon GISSLER A 7 Sec 14 T17S R30E SWSE 330FSL 2310FEL GISSLER A 5 Sec 14 T17S R30E SENE 1980FNL 660FEL

# BUREAU OF LAND MANAGEMENT Carlsbad Field Office 620 East Greene Street Carlsbad, New Mexico 88220 575-234-5972

Pursuant to **NTL-4A III**, Lessees or operators are hereby authorized to vent or flare gas on a short-term basis <u>without incurring a royalty</u> obligation in the following circumstances:

- A. <u>Emergencies.</u> During temporary emergency situations, such as compressor or other equipment failures, relief of abnormal system pressures, or other conditions which result in the unavoidable short-term venting or flaring of gas. However, this authorization to vent or flare gas in such circumstances without incurring a royalty obligation is limited to 24 hours per incident and to 144 hours cumulative for the lease during any calendar month, except with the prior authorization, approval, ratification, or acceptance of the Supervisor.
- B. <u>Well Purging and Evaluation Tests.</u> During the unloading or cleaning up of a well during drillstem, producing, routine purging, or evaluation tests, not exceeding a period of 24 hours.
- C. <u>Initial Production Tests.</u> During initial well evaluation tests, not exceeding a period of 30 days or the production of 50 MMcf of gas, whichever occurs first, unless a longer test period has been authorized by the appropriate State regulatory agency and ratified or accepted by the Supervisor.
- D. <u>Routine or Special Well Tests.</u> During routine or special well tests, other than those cited in NTL-4A III.B and C above, only after approval by the Supervisor.

If a flaring event conforms with the requirements listed above as per NTL-4A III., the flared volumes are not royalty bearing and the operator does not need to submit a Sundry Notice. Report flared volumes as unavoidably lost on OGOR B.

## **Condition of Approval to Flare Gas**

- 1. The first 24 hours of a <u>temporary emergency flare\*</u> is considered "unavoidably lost" and is therefore royalty free. Flared volumes that are considered unavoidably lost are not to be included in Sundry Notice (Form 3160-5). NTL-4A specifies no more than 24 hours per incident and no more 144 hours cumulative for the lease during any calendar month. These Volumes are not royalty bearing and shall be reported on OGOR "B" as disposition code"23".
- 2. Flared volumes considered to be "avoidably lost":
  - Exceeding the first 24 hours for each temporary emergency flare event (144 hours cumulative for the lease per month), well purging and evaluation test.
  - During initial well evaluation tests, exceeding a period of 30 days or the production of 50 MMcf of gas, whichever occurs first
  - Scheduled flaring operations

These flare events will require prior approval via Notice of Intent- Sundry Notice (Form 3160-5). Volumes flared beyond limits defined in NTL-4A are considered "avoidably lost" and will require payment of royalties, unless an exception is granted in accordance with NTL-4A.IV.B.. <u>Volumes for avoidably lost gas shall be reported on OGOR "B" reports as disposition code "08"</u>. If the operator believes that the flared volumes were "unavoidably lost" and the BLM determines them to be "avoidably lost", the operator can submit a more detailed request via Sundry Notice (Form 3160-5) for an exception in accordance with NTL-4A.IV.B.. As an alternative to producing oil and flaring gas the operator may choose to shut the well in and avoid paying royalties on otherwise avoidably lost gas.

- 3. Approval not to exceed 90 days, if flaring is still required past 90 days submit new request for approval.
- 4. Submit Subsequent Report with actual volumes of gas flared for each month gas is flared on a Sundry Notice (Form 3160-5). Include method for volume determination and duration. Report unavoidably lost (first 24 hrs of unexpected event) and avoidably lost (exceeding the first 24 hrs or flared gas that has been approved as avoidably lost by the Authorized Officer) volumes and durations on the Subsequent Report.

- 5. In determining the volumes of gas to be reported in accordance with NTL-4A the BLM CFO requires Vent/flare gas metering to meet all requirements for a sales meter as per Federal Regulations, Onshore Order #5 and NTL 2008-01. Include meter serial number on Sundry Notice (Form 3160-5).
  - If installation of an approved gas meter is not economically feasible for continued operations. Submit Notice of Intent Sundry Notice (Form 3160-5) to request an alternate method of determining gas volumes with a valid justification. Alternate methods are listed in NTL-4A. The Authorized Officer may require the installation of additional measurement equipment whenever it is determined that the present methods are inadequate to meet the purposes of this Notice.
- 6. An updated facility diagram is required within 60 days of modifications to existing facilities per Onshore Order #3.
- 7. This approval does not authorize any additional surface disturbance.
- 8. Subject to like approval from NMOCD

### **Regulations and Definitions**

**Definition:** As per **NTL-4A II. A.** "Avoidably lost" production shall mean the venting or flaring of produced gas without the prior authorization, approval, ratification, or acceptance of the Supervisor and the loss of produced oil or gas when the Supervisor determines that such loss occurred as a result of (1) negligence on the part of the lessee or operator, or (2) the failure of the lessee or operator to take all reasonable measures to prevent and/or to control the loss, or (3) the failure of the lessee or operator to comply fully with the applicable lease terms and regulations, appropriate provisions of the approved operating plan, or the prior written orders of the Supervisor, or (4) and combination of the foregoing.

NTL-4A.IV.B. Oil Well Gas. Except as provided in II.C and III above, oil well gas may not be vented or flared unless approved in writing by the Supervisor. The Supervisor may approve an application for the venting or flaring of oil well gas if justified either by the submittal of (1) an evaluation report supported by engineering, geologic, and economic data which demonstrates to the satisfaction of the Supervisor that the expenditures necessary to market or beneficially use such gas are not economically justified and that conservation of the gas, if required, would lead to the premature abandonment of recoverable oil reserves and ultimately to a greater loss of equivalent energy than would be recovered if the venting or flaring were permitted to continue or (2) an action plan that will eliminate venting or flaring of the gas within 1 year from the date of application.

\*Temporary Emergency Flaring is defined as an unexpected situation requiring immediate action. A flaring event is considered an emergency if the occurrence is out of the operators control and the operator had less than 24 hrs notification of the event. Scheduled or routine flare events will not be considered an emergency.