Submit 1 Conv To Appropriate District		•		E 0.103
Submit 1 Copy To Appropriate District Office	State of New Mexico		Form C-103	
<u>District 1</u> (575) 393-6161 1625 N. French Dr., Hobbs, NM 88240	Energy, Minerals and Natural Resources		WELL API NO.	Revised July 18, 2013
District II - (575) 748-1283	7/0 1901		30-015-22819	
811 S. First St., Artesia, NM 88210 District III – (505) 334-6178			5. Indicate Type of Lease	
1000 Rio Brazos Rd , Aztec, NM 87410	Brazos Rd, Aztec, NM 87410 Santa Ea. NIM 97505		STATE FEE	
District IV ~ (505) 476-3460 Salita FC, INIVI 87505 1220 S. St. Francis Dr., Santa Fe, NM		6. State Oil & Gas Lease No. 647-349, 647-351		
87505			7. Lease Name or Unit Agreement Name	
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH			Empire Abo Unit (309164)	
PROPOSALS.) 1. Type of Well: Oil Well 🖌 Gas Well 🗌 Other			8. Well Number 393	
2. Name of Operator			9. OGRID Number	
Apache Corporation			873	
3. Address of Operator 303 Veterana Airport Lana, Suita 1000, Midland, TX 70705			10. Pool name or Wildcat	
303 Veterans Airpark Lane, Suite 1000 Midland, TX 79705			Empire; Abo (22040)	
4. Well Location Unit Letter B : 11	00 feet from the North	line and 225	i0 feet fro	om the East line
Section 35		inge 28E	NMPM	County Eddy
11. Elevation (Show whether DR, RKB, RT, GR, etc.)				
3686' GL				
12. Check Ap	propriate Box to Indicate N	ature of Notice,	Report or Other	Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:				
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WOR				
PULL OR ALTER CASING	MULTIPLE COMPL	CASING/CEMEN	т јов 🗍	
CLOSED-LOOP SYSTEM		OTHER:		
13. Describe proposed or complet	ed operations. (Clearly state all r		d give pertinent dat	es, including estimated date
of starting any proposed work proposed completion or recon). SEE RULE 19.15.7.14 NMAC	C. For Multiple Con	mpletions: Attach	wellbore diagram of
Apache would like to perform the following	•			
Producing Interval: 5,948-6,038'	-			
Objective: TA Wellbore. Currently perform	ming geological and petrophysical	I studies to determin	ne feasibility for rec	ompletion. Evaluating wellbore
to bring it back to production. Procedure:				
1. POOH with rods and pump			NM OIL CONSERVATION	
2. Set a CIBP @ 5,895' and dump bail 35' of cmt			ARTESIA DISTRICT	
 Circulate fluid and pressure test casing to 500 psi Record the test on a chart and submit to OCD for approval 			►1日 月 日 10月	
			· · · · · ·	μ ^μ , τη τ
	TA status may be granted	aftera	0505	0/ED
successful MIT test is performed.			RECE	
Contact the OCD to schedule the test				
Spud Date: 03/21/1979	so it may be witnessed.	iule the test		
Spud Date: 03/21/1979		_		
	LAST PROD	2/1/2011	6	
I hereby certify that the information ab				
<u> </u>	-			
SIGNATURE ALAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAA	LSm TITLE Regular	tooy Analyst	D	ATE 01/09/2017
SIGNATURE Paser tour	LITE vegua	tory manyot	D/	AIE 010012017
Type or print name Isabel Hudson	E-mail address	Isabel.hudson@ap	achecorp.com Ph	IONE: (432) 818-1142
For State Use Only		,	······································	
	I Mars TITLE CO	MALIAN 11A	5 alerin	The states
APPROVED BY: Conditions of Approval (if any):	IIILE	mpcipnce		45 <u>47</u> 47

2- 4



January 9, 2017

Empire ABO Unit # E-393 Legal Name: Empire ABO Unit #393 API # 30-015-22819 Eddy County, NM Producing Interval: **5,948-6,038**'

<u>Objective</u>: TA Wellbore. Currently performing geological and petrophysical studies to determine feasibility for recompletion. Evaluating wellbore to bring it back to production.

Procedure:

- 1. POOH with rods and pump
- 2. Set a CIBP @ 5,895' and dump bail 35' of cmt
- 3. Circulate fluid and pressure test casing to 500 psi
- 4. Record the test on a chart and submit to OCD for approval

c

