Submit I Copy To Appropriate District Office	State of New Mexico			Form C-103
District I – (575) 393-6161	Energy, Minerals and Natural Resources			Revised July 18, 2013
1625 N. French Dr., Hobbs, NM 88240			WELL API NO.	
<u>District II</u> – (575) 748-1283 811 S. First St., Artesia, NM 88210	OIL CONSERVATION DIVISION		30-015-26368	
District III ~ (505) 334-6178	1220 South St. Francis Dr.		5. Indicate Type of Le	
1000 Rio Brazos Rd., Aztec, NM 87410			STATE	FEE 🛛
<u>District IV</u> – (505) 476-3460	Santa Fe, NM 87505		6. State Oil & Gas Le	ase No.
1220 S. St. Francis Dr., Santa Fe, NM 87505				
	CES AND REPORTS ON WE	211	7. Lease Name or Uni	it Agreement Name
(DO NOT USE THIS FORM FOR PROPO			7. Bease Name of On	it rigicomone rumo
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH			South Culebra Bluff	23
PROPOSALS.)			8. Well Number 12	25
1. Type of Well: Oil Well			8. Well Number 12	
2. Name of Operator			9. OGRID Number 3	71115
Rockcliff Operating New Mexico	LLC			
3. Address of Operator			10. Pool name or Wile	dcat
1301 McKinney, Suite 1300, Houston TX 77010			Loving; Brushy Canyon, East	
4. Well Location			<u>-I </u>	
Unit Letter: H	2140 foot from the	e <u>North</u> line and <u>400</u> f	act from the East line	
_				5 · · · · ·
Section 23	Township 23 S	Range 28 E		Eddy County
	11. Elevation (Show whether	DR, RKB, RT, GR, etc.)	
	2993' GL			_
12. Check A	Appropriate Box to Indicat	e Nature of Notice	Report or Other Dat	a
	-ppropriate zon to maron	,	report of o mer Dut	
NOTICE OF IN	TENTION TO:	SUB	SEQUENT REPO	RT OF:
PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐ REMEDIAL WOR				TERING CASING
TEMPORARILY ABANDON ☑ CHANGE PLANS ☐ COMMENCE DR		*******	ND A	
PULL OR ALTER CASING MULTIPLE COMPL CASING/CEMEN			 -	
DOWNHOLE COMMINGLE	Mozi i zz domi z	or to into robinitary	. 002	
CLOSED-LOOP SYSTEM				
OTHER:	П	OTHER:		П
13. Describe proposed or comp	leted operations (Clearly state		d give pertinent dates in	cluding estimated date
of starting any proposed we	ork). SEE RULE 19.15.7.14 NM	MAC For Multiple Co.	mpletions: Attach wellh	ore diagram of
proposed completion or rec		virte: Tor Manipie eo	imprecions. Tituen weno	ore diagram or
proposed completion of rec	ompionon,			
Will set CIBP within 100' of upper	most perforation (currently 4	1818') fill with inert t	fluid and pressure test	to 500 psi with a
pressure drop of not more than 1			idia, dila pressare test	to 500 psi with a
pressure drop of flot flore than i	0% over a 30 minute period.			
			and oftens likk	OIL CONSERVATIO
TA status may be gr			1110000	
		successful MIT test i	s performed.	
		Contact the OCD to	schedule the test	MAR 09 2017
Spud Date: $l_2 - 9$	- 90 Rig Relea	so it may be witness	sed.	
Spud Date.	- / C Rig Reier	30 it may be trees		accen/ED
		1 MT DOOD	alilance	RECEIVED
		LAST PROD	8/1/2015	
I hereby certify that the information	above is true and complete to the	ne best of my knowledg	e and belief.	
	, / 1)			
/<~/	1/201			
SIGNATURE	TITI	Æ Consultant	DATE <u>3-9-17</u>	
Type or print name Brian Wood	E-mail address: brian@	permitswest.com	PHONE: (505)	466-8120
For State Use Only				
			004	11-
APPROVED BY: Peubago	NCas TITLE (10,000 1 1 And 11 A	SPACE DATE	211217
	TITLE C	CALL TIMES	DAIL DAIL	<u> </u>