

# Matador Production Company

One Lincoln Centre • 5400 LBJ Freeway • Suite 1500 • Dallas, Texas 75240

Voice 972.371.5284 • Fax 214.866.4832

[darnold@matadorresources.com](mailto:darnold@matadorresources.com)

**Dana R. Arnold**  
Operations and Regulatory Counsel

August 1, 2017

New Mexico Oil Conservation Division  
Attn: Will Jones  
1220 South St. Francis Drive  
Santa Fe, New Mexico 87505  
[WilliamV.Jones@state.nm.us](mailto:WilliamV.Jones@state.nm.us)

**NM OIL CONSERVATION**  
ARTESIA DISTRICT

AUG 01 2017

RECEIVED

**Re: Well Tubing Exception**  
**PAUL 25 24S 28E RB #225H (30-015-43723)**

Dear Mr. Jones:


Matador Production Company ("Matador") completed its **PAUL 25 24S 28E RB #225H (30-015-43723)** well (the "Well") on June 14, 2017. Matador requests to delay installing tubing in the Well since it continues to flow large volumes with high pressures that would be restricted from the smaller ID provided by tubing; it also is continuing to clean up and sand could inhibit the tubing installation and equipment potentially causing expensive workover operations. ←

Matador believes the delay in the tubing will not cause waste or damage the Well. The Well has four strings of casing that adequately protect wellbore integrity. Further, the Well has been designed to withhold high pressures: everything below the wellhead is rated to 15,000 psi pressure for hydraulic fracturing operations and the wellhead is rated to 5,000 psi. Lastly, the gas composition for the Well does not contain H2S or CO2.

Accordingly, Matador would like to request an exception to 19.15.16.10.J to allow for no tubing in the Well for an initial six month period from completion, until approximately December 14, 2017 and states in support of its request that no waste will be caused as a result of this exception. At the end of the six month period, Matador will re-evaluate the need for tubing to be installed and communicate with the Division as to the results of its analysis.

Thank you, and please contact me with any questions.

Sincerely,



Dana R. Arnold

cc: [Ranell.Klein@state.nm.us](mailto:Ranell.Klein@state.nm.us)

Tubing Exception for this well expires  
90 days from "Ready to Produce" date  
applicable to the well. *RwP*