## NM OIL CONSERVATION

ARTESIA DISTRICT

E F B	91		20	5.
÷≻H	2	0	20	И

Submit One Copy To Appropriate I	District State	of New Me	xico		Form C-103	
Office District I	Energy, Minera	als and Natu	ral ResourcesREC	EIVED	January 20, 2011	
1625 N. French Dr., Hobbs, NM 88	3240			WELL API NO.		
District II 1301 W. Grand Ave., Artesia, NM	OIL CONSE	RVATION	DIVISION	30-015-33717		
District III	strict III 1220 South St. Francis Dr.		icis Dr.	5. Indicate Type of Lease STATE STATE		
1000 Rio Brazos Rd., Aztec, NM 87410 Santa Fa, NM 87505		6. State Oil & Gas L				
1220 S. St. Francis Dr., Santa Fe, NM			ease no.			
87505		0.1111111				
	'NOTICES AND REPORTS PROPOSALS TO DRILL OR TO D			7. Lease Name or Un New Mexico Z State		
	"APPLICATION FOR PERMIT" (F			New Mexico Z State		
PROPOSALS.)		CUUD		8. Well Number 003	3	
1. Type of Well:Oil We2. Name of Operator	ell Gas Well Other	SWD		9. OGRID Number		
COG Operating LLC				229137		
3. Address of Operator				10. Pool name or Wi	ildcat	
600 W Illinois Ave, Midland	l, TX 79701			Millman; Yates-SR Q		
4. Well Location					<u> </u>	
Unit Letter B : 33	$\underline{0}$ feet from the <u>North</u> line a	and 2310 feet	from the East line			
	vnship <u>19S</u> Range <u>28E</u> NI					
	11. Elevation (Show			(64.64) (C		
		3388'		tin Tana arta arta		
12. Check Appropriate	Box to Indicate Nature c	of Notice, R	eport or Other D	Data		
				SEQUENT REPC		
PERFORM REMEDIAL WOR TEMPORARILY ABANDON			REMEDIAL WORI			
PULL OR ALTER CASING			CASING/CEMENT		AND A	
FOLE ON ALTER CASING			CASING/CEMENT	10B 🗌		
OTHER:			⊠ Location is re	ady for OCD inspecti	on after P&A	
All pits have been remed			e terms of the Oper	ator's pit permit and cl	on after P&A losure plan.	
<ul><li>All pits have been remed</li><li>Rat hole and cellar have</li></ul>	been filled and leveled. Cath	nodic protection	ne terms of the Oper on holes have been	ator's pit permit and cl properly abandoned.	losure plan.	
<ul> <li>All pits have been remed</li> <li>Rat hole and cellar have</li> <li>A steel marker at least 4'</li> </ul>	been filled and leveled. Cath ' in diameter and at least 4' al	nodic protection bove ground l	ne terms of the Oper on holes have been evel has been set in	ator's pit permit and cl properly abandoned. concrete. It shows the	losure plan.	
<ul> <li>All pits have been remed</li> <li>Rat hole and cellar have</li> <li>A steel marker at least 4'</li> <li>OPERATOR NAM</li> </ul>	been filled and leveled. Cath ' in diameter and at least 4' a' E, LEASE NAME, WELL	nodic protection bove ground l NUMBER, A	te terms of the Oper on holes have been y evel has been set in <b>PI NUMBER, QU</b>	ator's pit permit and cl properly abandoned. concrete. It shows the ARTER/QUARTER	losure plan. e LOCATION OR	
<ul> <li>All pits have been remed</li> <li>Rat hole and cellar have</li> <li>A steel marker at least 4"</li> <li>OPERATOR NAM UNIT LETTER, SE</li> </ul>	been filled and leveled. Cath ' in diameter and at least 4' al	nodic protection bove ground l NUMBER, A D RANGE.	te terms of the Oper on holes have been evel has been set in <u>PI NUMBER, QU</u> All INFORMATIO	ator's pit permit and cl properly abandoned. concrete. It shows the ARTER/QUARTER	losure plan. e LOCATION OR	
<ul> <li>All pits have been remed</li> <li>Rat hole and cellar have</li> <li>A steel marker at least 4'</li> <li>OPERATOR NAM</li> <li>UNIT LETTER, SE</li> <li>PERMANENTLY S</li> </ul>	been filled and leveled. Cath ' in diameter and at least 4' a E, LEASE NAME, WELL CTION, TOWNSHIP, AN STAMPED ON THE MAR	nodic protection bove ground l NUMBER, A D RANGE. KER'S SUR	te terms of the Oper on holes have been j evel has been set in <u>PI NUMBER, QU</u> <u>All INFORMATIC</u> <u>FACE.</u>	ator's pit permit and cl properly abandoned. concrete. It shows the <u>ARTER/QUARTER</u> <u>DN HAS BEEN WELL</u>	losure plan. e <u>LOCATION OR</u> <u>DED OR</u>	
<ul> <li>All pits have been remed</li> <li>Rat hole and cellar have</li> <li>A steel marker at least 4'</li> <li>OPERATOR NAM</li> <li>UNIT LETTER, SE</li> <li>PERMANENTLY S</li> <li>The location has been level</li> </ul>	been filled and leveled. Cath ' in diameter and at least 4' al E, LEASE NAME, WELL CTION, TOWNSHIP, AN	nodic protection bove ground l NUMBER, A D RANGE. KER'S SUR	te terms of the Oper on holes have been j evel has been set in <u>PI NUMBER, QU</u> <u>All INFORMATIC</u> <u>FACE.</u>	ator's pit permit and cl properly abandoned. concrete. It shows the <u>ARTER/QUARTER</u> <u>DN HAS BEEN WELL</u>	losure plan. e <u>LOCATION OR</u> <u>DED OR</u>	
<ul> <li>All pits have been remed</li> <li>Rat hole and cellar have</li> <li>A steel marker at least 4'</li> <li>OPERATOR NAM</li> <li>UNIT LETTER, SE</li> <li>PERMANENTLY S</li> <li>The location has been level other production equipment.</li> </ul>	been filled and leveled. Cath ' in diameter and at least 4' at E, LEASE NAME, WELL CTION, TOWNSHIP, AN STAMPED ON THE MAR weled as nearly as possible to	nodic protection bove ground l <u>NUMBER, A</u> <u>D RANGE. <u>A</u> <u>KER'S SUR</u> original groun</u>	te terms of the Oper on holes have been y evel has been set in <u>PI NUMBER, QU</u> <u>All INFORMATIC</u> <u>FACE.</u> nd contour and has b	ator's pit permit and cl properly abandoned. concrete. It shows the ARTER/QUARTER ON HAS BEEN WELL been cleared of all junk	losure plan. e <u>LOCATION OR</u> <u>DED OR</u>	
<ul> <li>All pits have been remed</li> <li>Rat hole and cellar have</li> <li>A steel marker at least 4'</li> <li>OPERATOR NAM UNIT LETTER, SE PERMANENTLY S</li> <li>The location has been lev other production equipment.</li> <li>Anchors, dead men, tie d</li> </ul>	been filled and leveled. Cath 'in diameter and at least 4' al E, LEASE NAME, WELL CTION, TOWNSHIP, AN STAMPED ON THE MAR weled as nearly as possible to lowns and risers have been cu	nodic protection bove ground l <u>NUMBER, A</u> <u>D RANGE. KER'S SUR</u> original ground original ground	the terms of the Oper on holes have been p evel has been set in <u>PI NUMBER, QU</u> <u>All INFORMATION FACE.</u> Ind contour and has be two feet below grou	ator's pit permit and cl properly abandoned. concrete. It shows the <u>ARTER/QUARTER</u> <u>IN HAS BEEN WELL</u> been cleared of all junk nd level.	losure plan. E LOCATION OR DED OR K, trash, flow lines and	
<ul> <li>All pits have been remed</li> <li>Rat hole and cellar have</li> <li>A steel marker at least 4'</li> <li>OPERATOR NAM UNIT LETTER, SE PERMANENTLY S</li> <li>The location has been lev other production equipment.</li> <li>Anchors, dead men, tie d</li> <li>If this is a one-well lease</li> </ul>	been filled and leveled. Cath ' in diameter and at least 4' a E, LEASE NAME, WELL CTION, TOWNSHIP, AN STAMPED ON THE MAR veled as nearly as possible to owns and risers have been cu	nodic protection bove ground I <u>NUMBER, A</u> <u>D RANGE.</u> <u>KER'S SUR</u> original ground original ground the off at least the set the	the terms of the Oper on holes have been p level has been set in <u>PI NUMBER, QU</u> <u>All INFORMATIC</u> <u>FACE.</u> and contour and has be two feet below grout y and pit location(s)	ator's pit permit and cl properly abandoned. concrete. It shows the <u>ARTER/QUARTER</u> <u>DN HAS BEEN WELL</u> been cleared of all junk nd level. have been remediated	losure plan. LOCATION OR DED OR c, trash, flow lines and in compliance with	
<ul> <li>All pits have been remed</li> <li>Rat hole and cellar have</li> <li>A steel marker at least 4'</li> <li>OPERATOR NAM UNIT LETTER, SE PERMANENTLY S</li> <li>The location has been lev other production equipment.</li> <li>Anchors, dead men, tie d</li> <li>If this is a one-well lease OCD rules and the terms of the</li> </ul>	been filled and leveled. Cath in diameter and at least 4' at E. LEASE NAME, WELL CTION, TOWNSHIP, AN STAMPED ON THE MAR weled as nearly as possible to lowns and risers have been cut or last remaining well on lead the Operator's pit permit and cut	nodic protection bove ground I <u>NUMBER, A</u> <u>D RANGE.</u> <u>KER'S SUR</u> original ground original ground the off at least the set to the se	the terms of the Oper on holes have been p level has been set in <u>PI NUMBER, QU</u> <u>All INFORMATIC</u> <u>FACE.</u> and contour and has be two feet below grou by and pit location(s) All flow lines, produce	ator's pit permit and cl properly abandoned. concrete. It shows the <u>ARTER/QUARTER</u> <u>DN HAS BEEN WELL</u> been cleared of all junk nd level. have been remediated uction equipment and j	losure plan. LOCATION OR DED OR c, trash, flow lines and in compliance with junk have been removed	
<ul> <li>All pits have been remed</li> <li>Rat hole and cellar have</li> <li>A steel marker at least 4'</li> <li>OPERATOR NAM UNIT LETTER, SE PERMANENTLY S</li> <li>The location has been leven other production equipment.</li> <li>Anchors, dead men, tie d</li> <li>If this is a one-well lease OCD rules and the terms of the from lease and well location.</li> <li>All metal bolts and other is supported by the second sec</li></ul>	been filled and leveled. Cath in diameter and at least 4' at E. LEASE NAME, WELL CTION, TOWNSHIP, AN STAMPED ON THE MAR weled as nearly as possible to lowns and risers have been cut or last remaining well on lead the Operator's pit permit and cut	nodic protection bove ground I <u>NUMBER, A</u> <u>D RANGE.</u> <u>KER'S SUR</u> original ground original ground the off at least the set to the se	the terms of the Oper on holes have been p evel has been set in <u>PI NUMBER, QU</u> <u>All INFORMATIC</u> <u>FACE.</u> and contour and has be two feet below grou y and pit location(s) All flow lines, produces ses have been removi	ator's pit permit and cl properly abandoned. concrete. It shows the <u>ARTER/QUARTER</u> <u>DN HAS BEEN WELL</u> been cleared of all junk nd level. have been remediated uction equipment and j	Iosure plan. <u>LOCATION OR</u> <u>DED OR</u> <u>A trash</u> , flow lines and in compliance with junk have been removed <u>ا</u> ر ncrete bases do not have	
<ul> <li>All pits have been remed</li> <li>Rat hole and cellar have</li> <li>A steel marker at least 4'</li> <li>OPERATOR NAM UNIT LETTER, SE PERMANENTLY S</li> <li>The location has been leven other production equipment.</li> <li>Anchors, dead men, tie d</li> <li>If this is a one-well lease OCD rules and the terms of the from lease and well location.</li> <li>All metal bolts and other is to be removed.)</li> </ul>	been filled and leveled. Cath 'in diameter and at least 4' at E. LEASE NAME, WELL CTION, TOWNSHIP, AN STAMPED ON THE MAR weled as nearly as possible to owns and risers have been cu or last remaining well on leas the Operator's pit permit and co materials have been removed	nodic protection bove ground la <u>NUMBER, A</u> <u>D RANGE. A</u> <u>KER'S SURI</u> original ground original ground to off at least to ase, the battery closure plan.	the terms of the Oper on holes have been p evel has been set in <u>PI NUMBER, OU</u> <u>All INFORMATIC</u> <u>FACE.</u> and contour and has be two feet below grou y and pit location(s) All flow lines, produces ses have been remov	ator's pit permit and cl properly abandoned. concrete. It shows the <u>ARTER/QUARTER</u> <u>DN HAS BEEN WELL</u> been cleared of all junk nd level. have been remediated uction equipment and j	Iosure plan. <u>LOCATION OR</u> <u>DED OR</u> <u>k, trash</u> , flow lines and in compliance with junk have been removed <u>ا</u> ر ncrete bases do not have	
<ul> <li>All pits have been remed</li> <li>Rat hole and cellar have</li> <li>A steel marker at least 4'</li> <li>OPERATOR NAM UNIT LETTER, SE PERMANENTLY S</li> <li>The location has been leven other production equipment.</li> <li>Anchors, dead men, tie d</li> <li>If this is a one-well lease OCD rules and the terms of the from lease and well location.</li> <li>All metal bolts and other store to be removed.)</li> <li>All other environmental</li> </ul>	been filled and leveled. Cath 'in diameter and at least 4' at E, LEASE NAME, WELL CTION, TOWNSHIP, AN STAMPED ON THE MAR weled as nearly as possible to owns and risers have been cut or last remaining well on leas the Operator's pit permit and conternals have been removed concerns have been addresse	nodic protection bove ground I <u>NUMBER, A</u> <u>D RANGE.</u> <u>KER'S SURI</u> original ground original ground to off at least the se, the battery closure plan.	the terms of the Oper on holes have been p evel has been set in <u>PI NUMBER, OU</u> <u>All INFORMATIC</u> <u>FACE.</u> and contour and has be two feet below grou y and pit location(s) All flow lines, produces ses have been removed rules.	ator's pit permit and cl properly abandoned. concrete. It shows the <u>ARTER/OUARTER</u> <u>DN HAS BEEN WELL</u> been cleared of all junk nd level. have been remediated uction equipment and j wed. (Poured onsite con-	losure plan. LOCATION OR DED OR x, trash, flow lines and in compliance with junk have been removed $x_{j}$ increte bases do not have $y_{j}$ increte bases do not have	
<ul> <li>All pits have been remed</li> <li>Rat hole and cellar have</li> <li>A steel marker at least 4'</li> <li>OPERATOR NAM</li> <li>UNIT LETTER, SE</li> <li>PERMANENTLY S</li> <li>The location has been level other production equipment.</li> <li>Anchors, dead men, tie d</li> <li>If this is a one-well lease</li> <li>OCD rules and the terms of the from lease and well location.</li> <li>All metal bolts and other stobe removed.)</li> <li>All other environmental</li> <li>Pipelines and flow lines</li> </ul>	been filled and leveled. Cath 'in diameter and at least 4' at E. LEASE NAME, WELL CTION, TOWNSHIP, AN STAMPED ON THE MAR weled as nearly as possible to lowns and risers have been cut or last remaining well on leas the Operator's pit permit and c materials have been removed concerns have been addresse have been abandoned in acco	nodic protection bove ground I <u>NUMBER, A</u> <u>D RANGE.</u> <u>KER'S SURI</u> original ground original ground to off at least the se, the battery closure plan.	the terms of the Oper on holes have been p evel has been set in <u>PI NUMBER, OU</u> <u>All INFORMATIC</u> <u>FACE.</u> and contour and has be two feet below grou y and pit location(s) All flow lines, produces ses have been removed rules.	ator's pit permit and cl properly abandoned. concrete. It shows the <u>ARTER/OUARTER</u> <u>DN HAS BEEN WELL</u> been cleared of all junk nd level. have been remediated uction equipment and j wed. (Poured onsite con-	losure plan. LOCATION OR DED OR x, trash, flow lines and in compliance with junk have been removed $x_{j}$ increte bases do not have $y_{j}$ increte bases do not have	
<ul> <li>All pits have been remed</li> <li>Rat hole and cellar have</li> <li>A steel marker at least 4'</li> <li>OPERATOR NAM UNIT LETTER, SE PERMANENTLY S</li> <li>The location has been leven other production equipment.</li> <li>Anchors, dead men, tie d</li> <li>If this is a one-well lease OCD rules and the terms of the from lease and well location.</li> <li>All metal bolts and other stores to be removed.)</li> <li>All other environmental</li> <li>Pipelines and flow lines stores and pipelines</li> </ul>	been filled and leveled. Cath 'in diameter and at least 4' al E, LEASE NAME, WELL CTION, TOWNSHIP, AN STAMPED ON THE MAR veled as nearly as possible to lowns and risers have been cu or last remaining well on leas ne Operator's pit permit and co materials have been removed concerns have been addresse have been abandoned in acco ines.	nodic protection bove ground I <u>NUMBER, A</u> <u>DRANGE</u> <u>KER'S SURI</u> original ground it off at least to ase, the battery closure plan l. Portable battery closure plan d as per OCD ordance with 1	the terms of the Oper on holes have been p evel has been set in <u>PI NUMBER, QU</u> All INFORMATIC FACE. and contour and has be two feet below grou y and pit location(s) All flow lines, produ- ses have been removed rules. 9.15.35.10 NMAC.	ator's pit permit and cl properly abandoned. concrete. It shows the <u>ARTER/QUARTER</u> <u>DN HAS BEEN WELI</u> been cleared of all junk nd level. have been remediated uction equipment and j wed. (Poured onsite con ete Feacie All fluids have been r	losure plan. LOCATION OR DED OR (,  trash,  flow lines and) in compliance with junk have been removed $(, j_{-j})$ ncrete bases do not have $(, j_{-j})$ removed from non-	
<ul> <li>All pits have been remed</li> <li>Rat hole and cellar have</li> <li>A steel marker at least 4'</li> <li>OPERATOR NAM</li> <li>UNIT LETTER, SE</li> <li>PERMANENTLY S</li> <li>The location has been level other production equipment.</li> <li>Anchors, dead men, tie d</li> <li>If this is a one-well lease</li> <li>OCD rules and the terms of the from lease and well location.</li> <li>All metal bolts and other stobe removed.)</li> <li>All other environmental</li> <li>Pipelines and flow lines</li> </ul>	been filled and leveled. Cath 'in diameter and at least 4' al E, LEASE NAME, WELL CTION, TOWNSHIP, AN STAMPED ON THE MAR veled as nearly as possible to lowns and risers have been cu or last remaining well on leas ne Operator's pit permit and concerns have been removed concerns have been addresse have been abandoned in acco ines. or last remaining well on leas	nodic protection bove ground la <u>NUMBER, A</u> <u>D RANGE</u> <u>KER'S SURI</u> original ground original ground the off at least the se, the battery closure plan l. Portable battery closure plan d as per OCD ordance with 1 ase, all electric	the terms of the Oper on holes have been p evel has been set in <u>PI NUMBER, QU</u> All INFORMATIC FACE. and contour and has be two feet below grou y and pit location(s) All flow lines, produ- ses have been removed rules. 9.15.35.10 NMAC.	ator's pit permit and cl properly abandoned. concrete. It shows the <u>ARTER/QUARTER</u> <u>DN HAS BEEN WELI</u> been cleared of all junk nd level. have been remediated uction equipment and j wed. (Poured onsite con ete Feacie All fluids have been r	losure plan. LOCATION OR DED OR (,  trash,  flow lines and) in compliance with junk have been removed $(, j_{-j})$ ncrete bases do not have $(, j_{-j})$ removed from non-	
<ul> <li>All pits have been remed</li> <li>Rat hole and cellar have</li> <li>A steel marker at least 4'</li> <li>OPERATOR NAM UNIT LETTER, SE PERMANENTLY S</li> <li>The location has been level other production equipment.</li> <li>Anchors, dead men, tie d</li> <li>If this is a one-well lease</li> <li>OCD rules and the terms of the from lease and well location.</li> <li>All metal bolts and other stope removed.)</li> <li>All other environmental</li> <li>Pipelines and flow lines stope retrieved flow lines and pipeli</li> <li>If this is a one-well lease</li> </ul>	been filled and leveled. Cath 'in diameter and at least 4' at E, LEASE NAME, WELL CTION, TOWNSHIP, AN STAMPED ON THE MAR veled as nearly as possible to owns and risers have been cu or last remaining well on leas the Operator's pit permit and co materials have been removed concerns have been addresses have been abandoned in acco ines. or last remaining well on leas an emoved from lease and we	nodic protection bove ground I <u>NUMBER, A</u> <u>D RANGE.</u> <u>KER'S SURI</u> original ground at off at least to see, the battery closure plan. I. Portable ba d as per OCD ordance with 1 ase, all electrica I location.	the terms of the Oper on holes have been p evel has been set in <u>PI NUMBER, OU</u> <u>All INFORMATIC</u> <u>FACE.</u> and contour and has be two feet below grou by and pit location(s) All flow lines, produ- ses have been remo- rules. 9.15.35.10 NMAC. cal service, poles an	ator's pit permit and cl properly abandoned. concrete. It shows the <u>ARTER/OUARTER</u> <u>DN HAS BEEN WELL</u> been cleared of all junk nd level. have been remediated uction equipment and j wed. (Poured onsite con etc. Fencie All fluids have been r d lines, not to include p	losure plan. LOCATION OR DED OR (, trash, flow lines and in compliance with junk have been removed (, j) ncrete bases do not have (, j) removed from non-	
<ul> <li>All pits have been remed</li> <li>Rat hole and cellar have</li> <li>A steel marker at least 4'</li> <li>OPERATOR NAM UNIT LETTER, SE PERMANENTLY S</li> <li>The location has been leve other production equipment.</li> <li>Anchors, dead men, tie d</li> <li>If this is a one-well lease</li> <li>OCD rules and the terms of the from lease and well location.</li> <li>All metal bolts and other is to be removed.)</li> <li>All other environmental</li> <li>Pipelines and flow lines is retrieved flow lines and pipeli</li> <li>If this is a one-well lease</li> </ul>	been filled and leveled. Cath ' in diameter and at least 4' at E. LEASE NAME, WELL CTION, TOWNSHIP, AN STAMPED ON THE MAR weled as nearly as possible to lowns and risers have been cu or last remaining well on lead the Operator's pit permit and co materials have been removed concerns have been addresses have been abandoned in acco ines. or last remaining well on lead the operator of the materials of the second or last remaining well on lead the operator of the second of the second or last remaining well on lead the operator of the second of the second or last remaining well on lead the operator of the second of the second of the second the second of the second	nodic protection bove ground I <u>NUMBER, A</u> <u>D RANGE.</u> <u>KER'S SURI</u> original ground at off at least to see, the battery closure plan. I. Portable ba d as per OCD ordance with 1 ase, all electrica I location.	the terms of the Oper on holes have been p evel has been set in <u>PI NUMBER, OU</u> <u>All INFORMATIC</u> <u>FACE.</u> and contour and has be two feet below grou by and pit location(s) All flow lines, produ- ses have been remo- rules. 9.15.35.10 NMAC. cal service, poles an	ator's pit permit and cl properly abandoned. concrete. It shows the <u>ARTER/OUARTER</u> <u>DN HAS BEEN WELL</u> been cleared of all junk nd level. have been remediated uction equipment and j wed. (Poured onsite con etc. Fencie All fluids have been r d lines, not to include p	losure plan. LOCATION OR DED OR (, trash, flow lines and in compliance with junk have been removed (, j) ncrete bases do not have (, j) removed from non-	
<ul> <li>All pits have been remed</li> <li>Rat hole and cellar have</li> <li>A steel marker at least 4'</li> <li>OPERATOR NAM UNIT LETTER, SE PERMANENTLY S</li> <li>The location has been leve other production equipment.</li> <li>Anchors, dead men, tie d</li> <li>If this is a one-well lease</li> <li>OCD rules and the terms of the from lease and well location.</li> <li>All metal bolts and other is to be removed.)</li> <li>All other environmental</li> <li>Pipelines and flow lines is retrieved flow lines and pipeli</li> <li>If this is a one-well lease</li> </ul>	been filled and leveled. Cath ' in diameter and at least 4' at E. LEASE NAME, WELL CTION, TOWNSHIP, AN STAMPED ON THE MAR weled as nearly as possible to lowns and risers have been cu or last remaining well on lead the Operator's pit permit and co materials have been removed concerns have been addresses have been abandoned in acco ines. or last remaining well on lead the operator of the materials of the second or last remaining well on lead the operator of the second of the second or last remaining well on lead the operator of the second of the second or last remaining well on lead the operator of the second of the second of the second the second of the second	nodic protection bove ground I <u>NUMBER, A</u> <u>D RANGE. A</u> <u>CRANGE. A</u>	the terms of the Oper on holes have been p evel has been set in <u>PI NUMBER, OU</u> <u>All INFORMATIC</u> <u>FACE.</u> and contour and has be two feet below grou y and pit location(s) All flow lines, produ- ses have been remo- concer rules. 9.15.35.10 NMAC. cal service, poles an District office to sche	ator's pit permit and cl properly abandoned. concrete. It shows the <u>ARTER/OUARTER</u> <u>DN HAS BEEN WELD</u> been cleared of all junk nd level. have been remediated uction equipment and junk ved. (Poured onsite con- ete Fenci- All fluids have been r d lines, not to include p edule an inspection.	losure plan. LOCATION OR DED OR x, trash, flow lines and in compliance with junk have been removed $x, f_{s}, f_{s}$ nerete bases do not have $y, f_{s}, f_{s}$ removed from non- primary service	
<ul> <li>All pits have been remed</li> <li>Rat hole and cellar have</li> <li>A steel marker at least 4'</li> <li>OPERATOR NAM UNIT LETTER, SE PERMANENTLY S</li> <li>The location has been leve other production equipment.</li> <li>Anchors, dead men, tie d</li> <li>If this is a one-well lease OCD rules and the terms of the from lease and well location.</li> <li>All metal bolts and other to be removed.)</li> <li>All other environmental</li> <li>Pipelines and flow lines be retrieved flow lines and pipeli</li> <li>If this is a one-well lease company equipment, has been</li> </ul>	been filled and leveled. Cath ' in diameter and at least 4' at E. LEASE NAME, WELL CTION, TOWNSHIP, AN STAMPED ON THE MAR weled as nearly as possible to lowns and risers have been cu or last remaining well on lead the Operator's pit permit and co materials have been removed concerns have been addresses have been abandoned in acco ines. or last remaining well on lead the operator of the materials of the second or last remaining well on lead the operator of the second of the second or last remaining well on lead the operator of the second of the second or last remaining well on lead the operator of the second of the second of the second the second of the second	nodic protection bove ground I <u>NUMBER, A</u> <u>D RANGE. A</u> <u>CRANGE. A</u>	the terms of the Oper on holes have been p evel has been set in <u>PI NUMBER, OU</u> <u>All INFORMATIC</u> <u>FACE.</u> and contour and has be two feet below grou by and pit location(s) All flow lines, produ- ses have been remo- rules. 9.15.35.10 NMAC. cal service, poles an	ator's pit permit and cl properly abandoned. concrete. It shows the <u>ARTER/OUARTER</u> <u>DN HAS BEEN WELD</u> been cleared of all junk nd level. have been remediated uction equipment and junk ved. (Poured onsite con- ete Fenci- All fluids have been r d lines, not to include p edule an inspection.	losure plan. LOCATION OR DED OR x, trash, flow lines and in compliance with junk have been removed $x, f_{s}, f_{s}$ nerete bases do not have $y, f_{s}, f_{s}$ removed from non- primary service	
<ul> <li>All pits have been remed</li> <li>Rat hole and cellar have</li> <li>A steel marker at least 4'</li> <li>OPERATOR NAM UNIT LETTER, SE PERMANENTLY S</li> <li>The location has been leven other production equipment.</li> <li>Anchors, dead men, tie d</li> <li>If this is a one-well lease OCD rules and the terms of the from lease and well location.</li> <li>All metal bolts and other stobe removed.)</li> <li>All other environmental</li> <li>Pipelines and flow lines of the retrieved flow lines and pipelities is a one-well lease company equipment, has been company equipment, has been company statement.</li> </ul>	been filled and leveled. Cath ' in diameter and at least 4' at E. LEASE NAME, WELL CTION, TOWNSHIP, AN STAMPED ON THE MAR weled as nearly as possible to lowns and risers have been cu or last remaining well on leas the Operator's pit permit and co materials have been removed concerns have been addresses have been abandoned in acco ines. or last remaining well on leas have been abandoned in acco ines. or last remaining well on leas have been abandoned in acco ines. or last remaining well on leas have been this form to the MMM	nodic protection bove ground I <u>NUMBER, A</u> <u>D RANGE. A</u> <u>C RANGE. A</u> original ground original ground the off at least the se, the battery closure plan. I. Portable battery closure plan. I. Portable battery closure plan. I. Portable battery closure plan. A se, all electric appropriate I <u>TITLE S</u>	the terms of the Oper on holes have been p evel has been set in <u>PI NUMBER, QU</u> <u>All INFORMATIC</u> <u>FACE.</u> and contour and has b two feet below grou y and pit location(s) All flow lines, produ- ses have been remo- trules. 9.15.35.10 NMAC. cal service, poles an District office to sche <u>Genior Engineering</u>	ator's pit permit and cl properly abandoned. concrete. It shows the <b>ARTER/QUARTER</b> <b>DN HAS BEEN WELD</b> been cleared of all junk nd level. have been remediated uction equipment and j wed. (Poured onsite con- ete Fenci- All fluids have been r d lines, not to include p edule an inspection. Tech DATE $2/2$	losure plan. LOCATION OR DED OR x, trash, flow lines and in compliance with junk have been removed $x, f_{s}, f_{s}$ removed from non- primary service 21/18	
<ul> <li>All pits have been remed</li> <li>Rat hole and cellar have</li> <li>A steel marker at least 4'</li> <li>OPERATOR NAM UNIT LETTER, SE PERMANENTLY S</li> <li>The location has been leve other production equipment.</li> <li>Anchors, dead men, tie d</li> <li>If this is a one-well lease</li> <li>OCD rules and the terms of the from lease and well location.</li> <li>All metal bolts and other is to be removed.)</li> <li>All other environmental</li> <li>Pipelines and flow lines is retrieved flow lines and pipeli</li> <li>If this is a one-well lease</li> </ul>	been filled and leveled. Cath ' in diameter and at least 4' at E. LEASE NAME, WELL CTION, TOWNSHIP, AN STAMPED ON THE MAR weled as nearly as possible to lowns and risers have been cu or last remaining well on lead the Operator's pit permit and co materials have been removed concerns have been addresse have been abandoned in acco ines. or last remaining well on lead a removed from lease and we beleted, return this form to the MMM MARCELESE	nodic protection bove ground I <u>NUMBER, A</u> <u>D RANGE. A</u> <u>C RANGE. A</u> original ground original ground the off at least the se, the battery closure plan. I. Portable battery closure plan. I. Portable battery closure plan. I. Portable battery closure plan. A se, all electric appropriate I <u>TITLE S</u>	the terms of the Oper on holes have been p evel has been set in <u>PI NUMBER, QU</u> <u>All INFORMATIC</u> <u>FACE.</u> and contour and has b two feet below grou y and pit location(s) All flow lines, produ- ses have been remo- trules. 9.15.35.10 NMAC. cal service, poles an District office to sche <u>Genior Engineering</u>	ator's pit permit and cl properly abandoned. concrete. It shows the <b>ARTER/QUARTER</b> <b>DN HAS BEEN WELD</b> been cleared of all junk nd level. have been remediated uction equipment and j wed. (Poured onsite con- ete Fenci- All fluids have been r d lines, not to include p edule an inspection. <u>Tech</u> DATE $2/2$ PHONE: 432-221/040	losure plan. LOCATION OR DED OR x, trash, flow lines and in compliance with junk have been removed y/y ncrete bases do not have $y' - f_{s} + f_{s}$ removed from non- primary service 21/18 67	
<ul> <li>All pits have been remed</li> <li>Rat hole and cellar have</li> <li>A steel marker at least 4'</li> <li>OPERATOR NAM UNIT LETTER, SE PERMANENTLY S</li> <li>The location has been leven other production equipment.</li> <li>Anchors, dead men, tie d</li> <li>If this is a one-well lease</li> <li>OCD rules and the terms of the from lease and well location.</li> <li>All metal bolts and other is to be removed.)</li> <li>All other environmental</li> <li>Pipelines and flow lines of the retrieved flow lines and pipelities</li> <li>If this is a one-well lease company equipment, has been company equipment, has been company equipment, has been company Company environment is the statement of the stat</li></ul>	been filled and leveled. Cath ' in diameter and at least 4' at E. LEASE NAME, WELL CTION, TOWNSHIP, AN STAMPED ON THE MAR weled as nearly as possible to lowns and risers have been cu or last remaining well on leas the Operator's pit permit and co materials have been removed concerns have been addresses have been abandoned in acco ines. or last remaining well on leas have been abandoned in acco ines. or last remaining well on leas have been abandoned in acco ines. or last remaining well on leas have been this form to the MMM	nodic protection bove ground I <u>NUMBER, A</u> <u>D RANGE. A</u> <u>C RANGE. A</u> original ground original ground the off at least the se, the battery closure plan. I. Portable battery closure plan. I. Portable battery closure plan. I. Portable battery closure plan. A se, all electric appropriate I <u>TITLE S</u>	the terms of the Oper on holes have been p evel has been set in <u>PI NUMBER, QU</u> <u>All INFORMATIC</u> <u>FACE.</u> and contour and has b two feet below grou y and pit location(s) All flow lines, produ- ses have been remo- trules. 9.15.35.10 NMAC. cal service, poles an District office to sche <u>Genior Engineering</u>	ator's pit permit and cl properly abandoned. concrete. It shows the <b>ARTER/QUARTER</b> <b>DN HAS BEEN WELD</b> been cleared of all junk nd level. have been remediated uction equipment and j wed. (Poured onsite con- ete Fenci- All fluids have been r d lines, not to include p edule an inspection. <u>Tech</u> DATE $2/2$ PHONE: 432-221/040	losure plan. LOCATION OR DED OR x, trash, flow lines and in compliance with junk have been removed $x, f_{s}, f_{s}$ removed from non- primary service 21/18	

Conditions of Approval (if any):