Form 3160-5 (June 2015)

## **UNITED STATES** DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

OCD Artesia

FORM APPROVED OMB NO. 1004-0137

	January 31, 20
Lease Serial No.	
NMLC061869	

SUNDRY N	OTICES AND REPORTS ON WELLS	
Do not use this	form for proposals to drill or to re-enter an	
abandoned well.	Use form 3160-3 (APD) for such proposals.	

abandoned well. Use form 3160-3 (APD) for such proposals.					6. If Indian, Allottee or Tribe Name			
SUBMIT IN TRIPLICATE - Other instructions on page 2			7. If Unit or CA/Agreement, Name and/or No. NMNM134249					
1. Type of Well  ☑ Oil Well ☐ Gas Well ☐ Other				8. Well Name and No. BIG SINKS DRAW 25 FED COM 1H				
Name of Operator     Contact: SHEILA A FISHER     DEVON ENERGY PRODUCTION CON1-Mail: Sheila.Fisher@dvn.com					9. API Well No. 30-015-41548-00-S1			
3a. Address 6488 SEVEN RIVERS HIGHW ARTESIA, NM 88211	o. (include area code) 18-1829		10. Field and Pool or Exploratory Area JENNINGS					
4. Location of Well (Footage, Sec., T., R., M., or Survey Description)					11. County or Parish, State			
Sec 25 T25S R31E SWNW 2440FNL 500FWL 32.101269 N Lat, 103.740195 W Lon					EDDY COUNTY, NM			
12. CHECK THE AP	PPROPRIATE BOX(ES) TO	O INDICA	TE NATURE OI	F NOTICE,	REPORT, OR OTH	ER D	OATA	
TYPE OF SUBMISSION			ТҮРЕ ОР	ACTION				
☐ Notice of Intent	☐ Acidize	☐ Dee	pen	☐ Product	ion (Start/Resume)		Vater Shut-Off	
_	☐ Alter Casing	🗖 Нус	Iraulic Fracturing	☐ Reclams	ation		Vell Integrity	
Subsequent Report	Casing Repair	■ Nev	v Construction	☐ Recomp	olete	<b>X</b>	Other	
☐ Final Abandonment Notice	☐ Change Plans	Plug	g and Abandon	<ul><li>☐ Temporarily Abandon</li><li>☐ Water Disposal</li></ul>		Site Facility Diagra m/Security Plan		
	□ Convert to Injection	Plug	g Back					
Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports must be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 must be filed once testing has been completed. Final Abandonment Notices must be filed only after all requirements, including reclamation, have been completed and the operator has determined that the site is ready for final inspection.  Attached is the site facility diagram for the Big Sinks Draw 25 Fed Com 1H and the associated wells  Associated wells that produce to the Big Sinks Draw 25 Fed Com 1H:  Associated wells that produce to the Big Sinks Draw 25 Fed Com 1H:  Big Sinks Draw 25 Fed Com 2H  Location SENW, \$25, T25S, R31E  Lease Number NMLC061869  API: 30-015-42520  Big Sinks Draw 25 Fed Com 3H  Location SWNE, \$25, T25S, R31E  API 36 7111  Accepted for Record Purposes.  Approval Subject to Onsite Inspection.  Date: 2-13-18  Americany  Fac. ID = BS 22  14. Thereby certify that the foregoing is true and correct.							operator has  7-/8  NMCCD  s.  aspection.	
Com	Electronic Submission #384 For DEVON ENERGY F nmitted to AFMSS for process	PRODUCTION	DN COM LP, sent SCILLA PEREZ or	to the Carls 1 09/12/2017	bad (17PP0909SE)			
Name (Printed/Typed) SHEILA A FISHER Title FIELD ADMIN SUP				FORT				
Signature (Electronic Submission) Date 08/11/2017								
	THIS SPACE FOR	FEDER/	AL OR STATE	OFFICE U	SE			
Approved By  Conditions of approval, if any, are attached certify that the applicant holds legal or equivalent would entitle the applicant to conduct the second of the se	nitable title to those rights in the su act operations thereon.	bject lease	Title Office	willfully to	aka to any danatimant as		Date  Of the United	
Title 18 U.S.C. Section 1001 and Title 43 States any false, fictitious or fraudulent s				willially to ma	ake to any department or a	igency	of the Officed	

## Additional data for EC transaction #384395 that would not fit on the form

## 32. Additional remarks, continued

Lease Number NMLC061869 API: 30-015-41940

Big Sinks 25 Fed Com 4H Location SENE, S25, T25S, R31E Lease Number NMLC061869 API: 30-015-43551

