NM OIL CONSERVATION ARTESIA DISTRICT

AUG 0 7 2018

Form C-102 RECEIVED August 1, 2011 Submit one copy to appropriate

*

State of New Mexico

Pool Name

SWD/DEVONIAN-SILURIAN

□AMENDED REPORT

Well Number

Elevation

2995'

District Office

DISTRICT I 1625 N. French Dr., Hobbs, NM 88240 Phone: (575) 393-6161 Fax: (575) 393-0720 DISTRICT II 811 S. First St., Artesia, NM 88210 Phone: (575) 748-1283 Fax: (575) 748-9720 DISTRICT III 1000 Rio Brazos Road, Artec, NM 87410 Phone: (505) 334-6178 Fax: (505) 334-6170 DISTRICTIV

Energy, Minerals & Natural Resources Department **OIL CONSERVATION DIVISION** 1220 South St. Francis Dr. Santa Fe, New Mexico 87505

1220 S. St. Francis Dr., Santa Fe, NM 87505 Phone: (505) 476-3460 Fax: (505) 476-3462

API Number

30.015.45146

Property Code 322223

OGRID No. 260297

WELL LOCATION AND ACREAGE DEDICATION PLAT

Property Name

LAKESIDE 20702 SWD Operator Name

BTA OIL PRODUCERS, LLC

Pool Code

97869

					Surface Locati	оп	,		
UL or lot No.	Section 29	Towns 23-	· •	Lot Idn	Feet from the 1750	North/South line NORTH	Feet from the 2640	East/West line EAST	County EDDY
		-		Bottom Hol	le Location If Diffe	erent From Surface			
UL or lot No. Section		Towns	ship Range	Lot Idn	Feet from the	North/South line	Fect from the	East/West line	County
Dedicated Acres	Joint or	Infill	Consolidation (Code Ord	er No.				
GEODETIC COOR NAD 27 NI SURFACE LOC Y=465103.5 X=601006. LAT.=32.2782. LONG.=104.006	DINATES ME ATION 1 2 64° N	GEODETIC NAL SURFA Y=4 X=6 LAI.=3	C COORDINATES D 83 NME CE LOCATION 65163.3 N 42189.4 E 12.278386' N 104.007003' W	S.L.		ONSOLIDATED OR A	OPER I hareby on complete to that this arg unEDDYee proposed to well at the of such m pooling a haretofare KRE: E-mail / SUR I hereby or was plotted me or une or	ATY REDDEL Name DDELL@BTAC Address VEYOR CERTIFI ertify that the well location of from field noise of sortual as my supervision, and that a to the best of my belief. JUNE 24, 20 JUNE 2	CATION refin is true and and belief, and whiting interest or ad including the right to drill this struct with an owner or to a voluntary pooling order 10/18/17 Date DIL. COM ICATION aboven on this plat aurveys made by the same is true

RN 9-9-18



U.S. Department of the Interior BUREAU OF LAND MANAGEMENT



APD ID: 10400025050

Submission Date: 01/10/2018

Highlighted data raflects the most recent changes

Operator Name: BTA OIL PRODUCERS LLC

Well Number: 1

Show Final Text

Well Name: LAKESIDE 20702 SWD Well Type: INJECTION - DISPOSAL

Well Work Type: Drill

Section 1 - Geologic Formations

Formation			True Vertical	Measured			Producing
ID	Formation Name	Elevation	Depth	Depth	Lithologies	Mineral Resources	Formation
1	QUATERNARY	2995	0	Ó	ANHYDRITE	NONE	No
2	RUSTLER	2368	627	627	ANHYDRITE	NONE	No
3	TOP SALT	1018	1977	1977	SALT	NONE	No
4	DELAWARE	108	2887	2887		OIL	No
5	BELL CANYON	18	2977	2977		OIL	No
6	BRUSHY CANYON	-1232	4227	4772	-	OIL	No
7	BONE SPRING LIME	-3582	6577	6577		OIL	No
8	WOLFCAMP	-7012	10007	10007		OIL	No
9	WOODFORD	-11366	14361	14361		OIL	No
10	DEVONIAN	-11512	14507	14507		NONE	Yes

Section 2 - Blowout Prevention

Rating Depth: 15000 Pressure Rating (PSI): 10M

Equipment: The blowout preventer equipment (BOP) shown in Exhibit A will consist of a (10M system) double ram type (10000 psi WP) preventer and a bag-type (Hydril) preventer (10000 psi WP). Both units will be hydraulically operated and the ram type preventer will be equipped with blind rams on top and 4-1/2" drill pipe rams on bottom. The BOP's will be installed on the 13-3/8" surface casing and utilized continuously until total depth is reached. All BOP's and associated equipment will be tested as per BLM drilling Operations Order No. 2. A 2" kill line and 3" choke line will be incorporated in the drilling spool below the ram-type BOP. Other accessory BOP equipment will include a Kelly cock, floor safety valve, choke lines, and choke manifold having a 10000 psi WP rating.

Requesting Variance? YES

Variance request: A Choke Hose Variance is requested. See attached test chart and spec.

Testing Procedure: Pipe rams will be operated and checked each 24-hour period and each time the drill pipe is out of the hole. These functional tests will be documented on the daily driller's log.