

Submit 3 Copies To Appropriate District Office

District I

1625 N. French Dr., Hobbs, NM 88248

District II

1301 W. Grand Avenue, Artesia, NM 87410

District III

1000 Rio Brazos Rd., Aztec, NM 87410

District IV

1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy, Minerals and Natural Resources

Form C-103

Revised March 25, 1999

WELL API NO.

30-015-76528

5. Indicate Type of Lease

STATE ☐

FEE ☒

6. State Oil & Gas Lease No.

7. Lease Name or Unit Agreement Name:

REID

8. Well No.

1

9. Pool name or Wildcat

E. LOVING (BRUSHY CANYON)

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:

Oil Well ☒

Gas Well ☐

Other ☐

2. Name of Operator

PAU ENERGY, INC.

3. Address of Operator

5100 E. SKELLY DR., STE. 600, TULSA, OK 74135

4. Well Location

Unit Letter

0

880

feet from the

SOUTH

line and

1980

feet from the

EAST

line

Section

14

Township

23S

Range

28E

NMPM

County

EDDY

10. Elevation (Show whether DR, RKB, RT, GR, etc.)

2469.9' GR

11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☒

PLUG AND ABANDON ☐

TEMPORARILY ABANDON ☐

CHANGE PLANS ☐

PULL OR ALTER CASING ☐

MULTIPLE COMPLETION ☐

OTHER:

RECOMPLETE U. BRUSHY CANYON

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐

ALTERING CASING ☐

COMMENCE DRILLING OPNS. ☐

PLUG AND ABANDONMENT ☐

CASING TEST AND CEMENT JOB ☐

OTHER: ☐

12. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

A) MUD WASH. ND WH & NU BOPE. REL TAP & TOH W/TEG.

B) PU ENL TRUCK. PUH GR & JTB. PUH & SET CTRP AT 5690'. TEST CSG TO 2600 PSIG. PERFORATE THE U. BRUSHY CANYON FROM 4691' TO 4812' OA USING 4" CSG GUN & 2SPF, 72' OA W/1 1/2" HOLES. PD ENL.

C) PU FKR & TH W/TEG. SET FKR AT 4650'±. ND BOPE & NU WH. SWAB TEST.

D) RI TREATERS. LOAD BS & PRESS UP TO 500 PSIG. ACIDIZE NEW PERFS W/2000 GAL 7.5% HCL & 250 BS. SWAB LOAD BACK & TEST.

E) FRAC TREAT W/5000 GAL XL GEL & 113,000# 16/30 SD & 44,000# RESIN. COATED SD 16/30. FLOW & SWAB LOAD BACK. POP.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE

Mike Kaiser

TITLE

OP ENGR

DATE

06/24/03

Type or print name

MIKE KAISER

Telephone No.

(918) 663-2800

(This space for State use)

District Supervisor

APPROVED BY

Jim W. Green

TITLE

DATE

JUL 01 2003

Conditions of approval, if any: