Submit 1 Copy To Appropriate District S Office District I - (575) 393-6161 Energy, N 1625 N. French Dr., Hobbs, NM 88240 District II - (575) 748-1283 OIL CO 811 S. First St., Artesia, NM 88210 OIL CO District III - (505) 334-6178 122 1000 Rio Brazos Rd., Aztec, NM 87410 District IV - (505) 476-3460 1220 S. St. Francis Dr., Santa Fe, NM 87505 SUNDRY NOTICES AND REP (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL O DIFFERENT RESERVOIR. USE "APPLICATION FOR PERIPROPOSALS.) 1. Type of Well: Oil Well Gas Well	State of New Keying Minerals and Natural Resources PNSERV ACTON DAMBSION 20 South St. Francis Dr. San AFTE, ANNI AFTERIA O.C.D. ORTS ON WELLS R TO DEEPEN OR PLUG BACK TO A MIT" (FORM C-101) FOR SUCH Other	Form C-103 Revised July 18, 2013 WELL API NO. 30-015-22249 5. Indicate Type of Lease STATE FEE 6. State Oil & Gas Lease No. K-6653 7. Lease Name or Unit Agreement Name Millman H.D. State Com 8. Well Number 2
2. Name of Operator		9. OGRID Number
3. Address of Operator		10. Pool name or Wildcat
5847 San Felipe Ste 3000 Houston Texas 77057		South Millman (Morrow)
4. Well Location		
Unit Letter <u>B: 660</u> feet from the <u>North</u> line and <u>1980</u> feet from the <u>East</u> line		
Section 17 Township 19S Range 28E NMPM Eddy County		
3,525 GR	(Snow whether DR, RRB, R1, GR, etc.)	,
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK ALTERING CASING		
TEMPORARILY ABANDON CHANGE PLA PULL OR ALTER CASING MULTIPLE CO DOWNHOLE COMMINGLE	ANS COMMENCE DRI DMPL CASING/CEMENT	LLING OPNS P AND A
OTHER:	OTHER:	
13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.		
		fy OCD 24 hrs . prior to
 Notify NMOCD 24 hrs before rigging up. MIRU WS. LD production equipment. RU WL. Set CIBP at 10,720'(top perf 10,813). Cap with 35ft of cement. Fill casing with treated water and pressure test casing to 500 psig for thirty minutes. Record pressure chart. Open all casing valves (bradenhead and intermediate) during the internal pressure tests and report a flow or pressure change occurring immediately before, during or immediately after the 30 minute pressure test. 		
6. File subsequent C103 complete with chart. TA status may be granted at		status may be granted in the
Succ		cessful MIT test is performed
	Con	tact the OCD to schedule the test
		may be witnessed.
Spud Date:	Rig Release Date:	
I hereby certify that the information above is true and complete to the best of my knowledge and belief.		
SIGNATURE MARCAN TITLE Permian District Superintendent DATE 1915/2018		
Type or print name <u>C.M. "Marty" Bloodworth, P.E.</u> E-mail address: <u>mbloodworth@vnrenergy.com</u> PHONE: 432-770-9738		
For State Use Only		
APPROVED BY:		



.