

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

Oil Cons.
N.M. DIV-Dist. 2
1301 W. Grand Avenue
Artesia, NM 88210

FORM APPROVED
OMB No. 1004-0135
Expires November 30, 2000

SUNDRY NOTICES AND REPORTS ON WELLS
Do not use this form for proposals to drill or to re-enter an
abandoned well. Use Form 3160-3 (APD) for such proposals.

SUBMIT IN TRIPLICATE - Other instructions on reverse side

1. Type of Well

☒ Oil Well ☐ Gas Well ☐ Other

2. Name of Operator

Bill & Patsy Rich

3a. Address

2401 Martin Ln.

3b. Phone No. (include area code)

505-887-3928

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)

Sec 14, T25S, R26E

330 FNL + 520 FEL

5. Lease Serial No.

NM 19423

6. If Indian, Allottee or Tribe Name

If Unit or CA/Agreement, Name and/or No.

Well Name and No.

H-M Fed #1

9. API Well No.

30-015-21914

10. Field and Pool, or Exploratory Area

11. County or Parish, State

Eddy, N.M.

12. CHECK APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION	TYPE OF ACTION			
<input type="checkbox"/> Notice of Intent	<input type="checkbox"/> Acidize	<input type="checkbox"/> Deepen	<input type="checkbox"/> Production (Start/Resume)	<input type="checkbox"/> Water Shut-Off
<input type="checkbox"/> Subsequent Report	<input type="checkbox"/> Alter Casing	<input type="checkbox"/> Fracture Treat	<input type="checkbox"/> Reclamation	<input type="checkbox"/> Well Integrity
<input type="checkbox"/> Final Abandonment Notice	<input type="checkbox"/> Casing Repair	<input type="checkbox"/> New Construction	<input type="checkbox"/> Recomplete	<input type="checkbox"/> Other
	<input type="checkbox"/> Change Plans	<input checked="" type="checkbox"/> Plug and Abandon	<input type="checkbox"/> Temporarily Abandon	
	<input type="checkbox"/> Convert to Injection	<input type="checkbox"/> Plug Back	<input type="checkbox"/> Water Disposal	

13. Describe Proposed or Completed Operation (clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recompleat horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection.)

ALL work Completed - 5-17-03
Except Surface Cleanup
See Attached

Approved as to plugging of the well bore.
Liability under bond is retained until
surface restoration is completed.

ACCEPTED FOR RECORD

JUN 20 2003

LES BABYAK

PETROLEUM ENGINEER

14. I hereby certify that the foregoing is true and correct

Name (Printed/Typed)

Patsy Rich

Title

Owner

Signature

Patsy Rich

Date

6-7-03

THIS SPACE FOR FEDERAL OR STATE OFFICE USE

Approved by

Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.

Title

Date

Office

MAYO MARRS CASING PULLING INC.
BOX 863
KERMIT, TEXAS 79745

BILLY & PATSY RICH

Lease: H.M. FEDERAL # 1

Project: P & A – CEMENTING REPORT

04-24-2003 - SET CIBP @ 1909' – SPOT 25 SXS CEMENT ON TOP – 1600'
04-25-2003 – PULL 1250' OF CASING
04-25-2003 – SPOT 35 SXS @ 1306'-1185' TAG
04-25-2003 – SPOT 70 SXS @ 217'-31' & TAG
04-28-2003 - SPOT 15 SXS @ 60' TO SURFACE

INSTALL DRY HOLE MARKER
CIRCULATE 10# MUD

MAYO MARRS CASING PULLING INC.

BILL & PATSY RICH

Lease: H.M. FEDERAL # 1

Project: P & A

JOB # 03-

4-24-03

NOTIFY BLM - KNOCK DOWN HILL ON LOCATION WITH BACKHOE - MOVE PUMP JACK IN ORDER TO RIG UP - MIRU - NUBOP - POOH WITH RODS & TUBING - RIH & SET CIBP @ 1909' WITH MMCPI WORKSTRING & SPOT 25 SXS @ 1909' 1600' - PER HOMER SAENZ BLM - POOH WITH TUBING - CLOSE IN WELL

4-25-03

CUT CASING @ 1250' - LAY DOWN 4 1/2" CASING - RIH & SPOT 35 SXS @ 1306' POOH - WOC - RIH & TG @ 1185' - POOH & SPOT 35 SXS @ 217' - POOH - CLOSE IN WELL

4-28-03

RIH & NO TAG - RESET PLUG - SPOT 35 SXS @ 217' - POOH - WOC - RIH & TAG @ 31' - INSTALL DRY HOLE MARKER WITH 5 SXS CEMENT @ 30' TO SURFACE - RIG DOWN CUT OFF WELLHEAD & ANCHORS - LEVEL PIT & CELLAR - MOVE OUT
(2 HRS RIG TO RESET PLUG)

MMCPI WORKSTRING

2 HRS RIG

BID 60 SXS USED 135

BID \$ 7,470.00